



INTERNATIONAL SHIP REPAIR & MARINE SERVICES, INC.

1616 PENNY STREET • TAMPA, FLA. 33605

TEL. (813) 247-1118 • FAX (813) 247-6553

www.internationalship.com

10 May 2002

Ms. Cindy Phillips, P.E.
FDEP Bureau of Air Regulation
MS5505
2600 Blair Stone Road
Tallahassee, FL 32399-2400

RECEIVED

MAY 15 2002

BUREAU OF AIR REGULATION

Subject: Reciprocating Internal Combustion Engines Major Source

Dear Ms. Phillips:

Since we do not have the final definitions of what will be covered under the regulations mentioned in Mr. Sheplak's letter of 5 April 2002 (copy enclosed), we are responding by saying that we may be subject to these regulations.

We are responding with the following:

1. International Ship Repair & Marine Services, Inc., 1616 Penny Street, Tampa, FL 33605, Major Source: Diesel engine on vessel/shipyard
2. Reciprocating Internal Combustion Engines
3. 700 Horsepower diesel engines used to operate a drydock. Exact inventory of all engines and horsepowers has not been completed to date. Approximately 2 such engines over 500 horsepower.
4. Our facility operates under a Title V permit for painting and sandblasting.

Sincerely,
International Ship Repair & Marine Services, Inc.

Randy Crotts
Risk Manager