

Indiantown Cogeneration, L.P.

RECEIVED

MAY 14 2002

BUREAU OF AIR REGULATION

Indiantown Cogeneration, L.P.
P.O. Box 1799
13303 SW Silver Fox Lane
Indiantown, FL 34956
Tel: 561.597.6500
Fax: 561.597.6210

May 9, 2002

Mr. Michael Halpin
Florida Department of Environmental Protection
Bureau of Air Regulation
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Re: Indiantown Cogeneration, L.P. Request for Emergency Authorization
Package Boiler Permit No.: PSD-FL-168, 0850102-001-AV

Dear Mr. Halpin:

Per your recent discussions with Michelle Golden and Nicholas Laryea, we are submitting the attached request for emergency authorization for temporary operation of a rental boiler.

An explosion has rendered auxiliary boiler "B" at the facility inoperative. The rental boiler is needed to supply steam to our steam host Louis Dreyfus (formerly Caulkins Indiantown Citrus), for the 1 to 2 week period until the main boiler comes back on-line.

Regarding the rental boiler:

- It is a trailer mounted, Nebraska Boiler with Low-NOx burners and Flue Gas Recirculation capability;
- It will fire natural gas only;
- Its maximum rated heat input is 97.6 MMBtu/hr, which is smaller than the auxiliary boiler it will be replacing (179 MMBtu/hr);
- Fuel use will be tracked and included in the annual totals for the auxiliary boilers;
- Operating hours will be tracked and included in the annual totals for the auxiliary boilers; and
- Emissions will be tracked based on fuel use, vendor data, and emission factors, and included in the annual totals for the auxiliary boilers.

Mr. Michael Halpin
FDEP
May 9, 2002

2

Attached is the following:


- Air permit application forms
- Specifications for the Rental Boiler
- Simple block process flow diagram for the rental boiler
- Calculation spreadsheet documenting that the mass flow emission rate for the rental boiler will be less than the package boiler.

Once the main (pulverized coal) boiler is back online and supplying steam, the rental boiler will be removed from service. We expect this to happen before May 23, 2002.

Repairs to the auxiliary boiler will be performed, but will not be completed before the main boiler comes back online.

We understand that David Dee of Landers and Parsons will be contacting you regarding this emergency authorization. Thank you for your time and consideration. If you have any questions please contact Nicholas Laryea at 561-597-6500 ext. 19.

Sincerely,



George K. "Chip" Allen
General Manager

cc: Nicholas Laryea, Indiantown Cogeneration LP
David S. Dee, Landers & Parsons
A J. Jablonowski, Earth Tech
A Vogel-Marr, PG&E NEG
USEPA Region IV
File

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Mr. George K. Allen
 General Manager
 Indiantown Cogeneration,
 P. O. Box 1799
 Indiantown, FL 34956

COMPLETE THIS SECTION ON DELIVERY

A. Received by (Please Print Clearly) B. Date of Delivery
 5-13-02

C. Signature
 X *Stuelder* Agent
 Addressee

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

. P.

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

7001 0320 0001 3692 8932

PS Form 3811, July 1999

Domestic Return Receipt

102595-00-M-0952

**U.S. Postal Service
 CERTIFIED MAIL RECEIPT
 (Domestic Mail Only; No Insurance Coverage Provided)**

OFFICIAL USE

7001 0320 0001 3692 8932

| | |
|---|-----------|
| Postage | \$ |
| Certified Fee | |
| Return Receipt Fee (Endorsement Required) | |
| Restricted Delivery Fee (Endorsement Required) | |
| Total Postage & Fees | \$ |

Postmark
 Here

Sent To
 George K. Allen
 Street, Apt. No.
 or P.O. Box 1799
 City, State, ZIP+4
 Indiantown, FL 34956

PS Form 3800, January 2001

See Reverse for Instructions