Golder Associates Inc.

6241 NW 23rd Street, Suite 500 Gainesville, FL 32653-1500 Telephone (352) 336-5600 Fax (352) 336-6603

February 13, 2004



RECEIVED

0337506

Florida Department of Environmental Protection Division of Air Resources Management 2600 Blair Stone Road, MS 5500 Tallahassee, FL 32399-2400 FEB 16 2004

BUREAU OF AIR REGULATION

Attention: Mr. Syed Arif, P. E.

RE:

CARGILL FERTILIZER INC., GREEN BAY FACILITY

DEP FILE NO. 1050053-034-AC

MODIFICATION OF SOUTH DAP PLANT FOR MAP PRODUCTION

Dear Mr. Arif:

Cargill Fertilizer Inc. was issued construction permit No. 1050053-034-AC on July 18, 2003, for the modification of the South DAP Fertilizer Plant to also produce MAP. Cargill has implemented the changes allowed under the permit, and is now operating to produce MAP. This construction permit is due to expire on March 31, 2004.

Due to the fact that the current Title V operating permit for the Green Bay facility (permit No. 1050053-012-AV) expires on December 28, 2004, the Title V renewal application is due to the Department no later than July 1, 2004. As a result of this upcoming deadline, Cargill would like to delay submitting an application for a Title V permit revision for construction permit No. 1050053-034-AC, in order to submit it as part of the renewal application. This will save both Cargill and the Department the resources required to process a separate revision application.

In order to proceed in this manner, Cargill is requesting that the current construction permit be extended until December 31, 2004, coinciding with expiration of the Title V permit. Please let me know if you have any questions concerning this request.

Sincerely,

GOLDER ASSOCIATES INC.

David a. Buff

David A. Buff, P.E., Q.E.P.

Principal Engineer

DB/nav

cc:

T. Abel, Cargill

F. Bergen, Golder

D. Jellerson, Cargill

Y:\Projects\2003\0337506 Cargill - Green Bay\4\4.1\L021304.doc