

Golder Associates Inc.

6241 NW 23rd Street, Suite 500
Gainesville, FL 32653-1500
Telephone (352) 336-5600
Fax (352) 336-6603



TRANSMITTAL LETTER

To: Jeff Koerner
FDEP Air Resource Management
2600 Blair Stone Road MS 5505
Tallahassee, Florida 32399-2400

Date: April 16, 2013
Project No.: 113-876152-0100

RECEIVED

APR 17 2013

DIVISION OF AIR
RESOURCE MANAGEMENT

Sent by: mhr

- | | | | |
|--------------------------|--------------|-------------------------------------|-----------------|
| <input type="checkbox"/> | Mail | <input type="checkbox"/> | UPS |
| <input type="checkbox"/> | Air Freight | <input checked="" type="checkbox"/> | Federal Express |
| <input type="checkbox"/> | Hand Carried | | |

Per: Ken Kosky *2/4*

Quantity	Item	Description
1	Document	EPSAP Application Number 3393-1

Remarks:

Document3

Electronic Permit Submittal and Processing System (EPSAP) Professional Engineer Signature Document

"This document is signed and sealed to secure the data in this permit application and any attached files that were submitted electronically as described in Florida Department of Business and Professional Regulation, Board of Professional Engineers, Procedures for Signing and Sealing Electronically Transmitted Plan, Specifications, Reports or other Documents, Rule 61G15-23.003., F.A.C.."

EPSAP Application Number: 3393-1

Facility Identification Number: 1070014

Facility Owner/Company Name: FLORIDA POWER & LIGHT (PPN)

Purpose of Application:

Title V air operation permit renewal.

Signature File Created: 4/2/2013 1:49:08 PM

File Description	Authentication Code
Submitted Application Data	D5DCFC011452DD50440E82763EF2745C904919D
Uploaded Facility Documents:	
Additional Applicable Requirements.pdf	24E8BBD1CCFBC6FA83FCB2B7CA98A02EDD88A9D2
Facility Plot Plan.pdf	F161F5F35AA2641CC1466952FD38096B7A2E060E
Flow Duct Burners.pdf	E89FFCBDA2F2AF4A106DBB6727F71A2F5CBE3DD9
CT Process Flow.pdf	4F09AF21DDE44F1B7A5CE45848330B1A64B4CC93
Aux Boiler Process Flow.pdf	80DCE165E5B7B5531C80AD3AF630A04185F95FF0
PrecToPrevEmissPM.pdf	56D17B2B4D226B791179ED7E5D159B088385E9DF
PPN Acid Rain App 2012.pdf	5B7319292D924003C2C2DF41FE03D04D08E6487A
PPN CAIR APP 2012.pdf	F62B663F01C3A596CE3046868EB416C82AA6E6AA
DEPcorelist_updated.pdf	556A4C941CD69ED0E8E31CD862A08DA2A23B7B94
List of Title VI Activities.doc	ABCA8ABD082FB18181A72FF572822732C09C6259
Putnam List of Insignificant Activities.pdf	6320216AF43BDBB1AA09951C70205C313314818B
Current_Putnam_Permit.pdf	F4EF19D09212B5D0BD63530D31CAE04B6EDDCDC2
PN_1070014-007-AV_CAIR_2009.pdf	73331D9ACAF33E546D606CE58FF15A4446858F31
PPN 2012 Annual Statement of Compliance.pdf	A6412A2A9550BCE357A292F13AC19E458714DAEC
Putnam_RICE_INVENTORY.xlsx	FED68D6D0AB710E810DAB7AE9AB47F9391A8A50F
PPN_Requested Changes to Current Title V Air Operation Permit.docx	7F772A744F3E0E5FA1055895D5A3AD5869993389
Uploaded Emissions Unit Documents:	
CT Process Flow.pdf	4F09AF21DDE44F1B7A5CE45848330B1A64B4CC93
Procedures for Startups and Shutdowns (CTs).pdf	05DC83B7B5B9231BA2DD40FA83B2332375DF926B
Flow Duct Burners.pdf	E89FFCBDA2F2AF4A106DBB6727F71A2F5CBE3DD9
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
ProcessFlow_EmergencyDieselGenerator.pdf	33CF97C137429A346642451A4C1AD5696148DE63
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
compliance records.doc	0858D4D207C8D9A9F62F7956477B6487A2EFFF2F
compliance records.doc	0858D4D207C8D9A9F62F7956477B6487A2EFFF2F
compliance records.doc	0858D4D207C8D9A9F62F7956477B6487A2EFFF2F

compliance records.doc	0858D4D207C8D9A9F62F7956477B6487A2EFFF2F
compliance records.doc	0858D4D207C8D9A9F62F7956477B6487A2EFFF2F
Test Results_DB.pdf	E3A7AF11D59B4899B8B630A1B79B257E144F4BA3
compliance records.doc	0858D4D207C8D9A9F62F7956477B6487A2EFFF2F
Test Results_DB.pdf	E3A7AF11D59B4899B8B630A1B79B257E144F4BA3
compliance records.doc	0858D4D207C8D9A9F62F7956477B6487A2EFFF2F
Test Results_DB.pdf	E3A7AF11D59B4899B8B630A1B79B257E144F4BA3
compliance records_auxboiler.doc	DFE8BF7A4D268AFDF39580579697B083A303275A
Test Results_DB.pdf	E3A7AF11D59B4899B8B630A1B79B257E144F4BA3
Test Results_DB.pdf	E3A7AF11D59B4899B8B630A1B79B257E144F4BA3
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
Aux Boiler_Applicable Requirements_2of2.jpg.doc	CB3FF7359D92321D7C73EE8A416F099F61F27DB1
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Diesel Generator_StartupShutdown.pdf	79CA5D4ECC08A6B1428D5BACB165F6743EAE7EA0
Putnam_RICE_INVENTORY.xlsx	FED68D6D0AB710E810DAB7AE9AB47F9391A8A50F
Duct Burners_Applicable Requirements.jpg	38CAE6ECE97ABC1ED8EA40DBA0355076E3E3F987
Duct Burners_Applicable Requirements.jpg	38CAE6ECE97ABC1ED8EA40DBA0355076E3E3F987
Duct Burners_Applicable Requirements.jpg	38CAE6ECE97ABC1ED8EA40DBA0355076E3E3F987
Duct Burners_Applicable Requirements.jpg	38CAE6ECE97ABC1ED8EA40DBA0355076E3E3F987
Aux Boiler_Applicable Requirements_1of2.jpg	38CAE6ECE97ABC1ED8EA40DBA0355076E3E3F987
Test Results_DB.pdf	E3A7AF11D59B4899B8B630A1B79B257E144F4BA3
Test Results_DB.pdf	E3A7AF11D59B4899B8B630A1B79B257E144F4BA3
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
CAM.doc	869D4BB0DD5F7D026DA3AAEF7A9D7E9271D38F09
CT_Identification of Applicable Requirements.docx	ABE9743E9A195BC6BDEFBDFFA57D6E79EA19444C
CT_Identification of Applicable Requirements.docx	ABE9743E9A195BC6BDEFBDFFA57D6E79EA19444C
CT_Identification of Applicable Requirements.docx	ABE9743E9A195BC6BDEFBDFFA57D6E79EA19444C
CT_Identification of Applicable Requirements.docx	ABE9743E9A195BC6BDEFBDFFA57D6E79EA19444C
Photos_EDG.pdf	1D536E37F99BFC71B857565C6FB585EC04833F53
EmergencyGenerator_IdentificationofApplicableReqs.doc	3394311F310C316D4BD111630B33BF6DB763D7B3
Alternative Methods of Operation_CTs.pdf	1660CED159EDD5DA2B4F547127F75ACCCF58A1F1
Old_Diesel Fire Pump_Cummins spec sheet.pdf	CA0EF8E68C1707FB94181921D0403A74AB018325
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Fuel Analysis.doc	AB64AAF0A5947D7574C605A4477A15D0A3391E26
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
EU004_ProcessFlow.pdf	CB29BD8C082154CB4C7B3B5A6FCC523A7AA970F1

CT_SUSD.doc	0C8B4D05313456E47A1468224C48F05097165265
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
Alternative Methods of Operation_CTs.docx	F6BCEE092C8D71D83745ABF8875FBAB58320FA99
CT_SUSD.doc	0C8B4D05313456E47A1468224C48F05097165265
Flow Duct Burners.pdf	E89FFCBDA2F2AF4A106DBB6727F71A2F5CBE3DD9
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
Flow Duct Burners.pdf	E89FFCBDA2F2AF4A106DBB6727F71A2F5CBE3DD9
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
Startup and Shutdown (Aux Boiler).pdf	8BC1D114F8DBA7F62D95D016324C669DAD868338
compliance records.doc	0858D4D207C8D9A9F62F7956477B6487A2EFFF2F
Test Results_DB.pdf	E3A7AF11D59B4899B8B630A1B79B257E144F4BA3
Unit 1 and 2 VEs.pdf	598D7BB474606F3E90BDE93C626FDE62150BF2BE
Unit 1 and 2 VEs.pdf	598D7BB474606F3E90BDE93C626FDE62150BF2BE
Unit 1 and 2 VEs.pdf	598D7BB474606F3E90BDE93C626FDE62150BF2BE
Unit 1 and 2 VEs.pdf	598D7BB474606F3E90BDE93C626FDE62150BF2BE
Unit 1 and 2 VEs.pdf	598D7BB474606F3E90BDE93C626FDE62150BF2BE
Unit 1 and 2 VEs.pdf	598D7BB474606F3E90BDE93C626FDE62150BF2BE
Unit 1 and 2 VEs.pdf	598D7BB474606F3E90BDE93C626FDE62150BF2BE
Unit 1 and 2 VEs.pdf	598D7BB474606F3E90BDE93C626FDE62150BF2BE
Aux Boiler Process Flow.pdf	80DCE165E5B7B5531C80AD3AF630A04185F95FF0
EU005_Process Flow.pdf	A05094217741F2E5EAC90ED4A5ED296F4ACC6FB9
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
Alternative Methods of Operation_CTs.pdf	1660CED159EDD5DA2B4F547127F75ACCCF58A1F1
EU006_ProcessFlow.pdf	7FC0C2AB295CFDB35BA5D1D5F67FF152DEB8CD6A
CT_SUSD.doc	0C8B4D05313456E47A1468224C48F05097165265
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
Alternative Methods of Operation_CTs.pdf	1660CED159EDD5DA2B4F547127F75ACCCF58A1F1
Flow Duct Burners.pdf	E89FFCBDA2F2AF4A106DBB6727F71A2F5CBE3DD9
Continuous Assurance Monitoring_General.doc	877815CD97CD3678E29C139C7984F9907ABF499B
Final Signature File	FED5D7B13A483691B56172D725EB7F5E28395046

Professional Engineer (PE): KENNARD KOSKY License No: 14996

(sign and affix PE seal below)

Kennard F Kosky
 KENNARD F. KOSKY
 COLDER ASSOCIATES INC
 Board of Professional Engineers
 Certificate of Authorization #0001670

