

August 15, 2012

RECEIVED

AUG 2 0 2012

DIVISION OF AIR RESOURCE MANAGEMENT

Florida Department of Environmental Protection Division of Air Resource Management 2600 Blair Stone Road, MS 5500 Tallahassee, FL 32399

RE: APAC - Southeast, Inc. Clearwater Asphalt Plant Status Update

(Facility ID 7770073)

To Whom It May Concern,

The APAC - Southeast, Inc. Clearwater Asphalt Plant has not operated since June of 2011 and we are requesting DEP to update the site's operational status to "Long-Term Reserve Shutdown." Consequently, because the site has not operated, and is not anticipated to operate, during the 2012 Federal Fiscal Year (FFY) we are requesting a waiver to conduct the annual Method 5 and 9 compliance tests at the asphalt plant for the 2012 FFY. The plant has not operated due to a lack of demand in the area.

Testing of the asphalt plant will be completed as soon as practicable but no later than 30 days after the facility resumes operations.

A relocated RAP crushing unit has not operated at the site since March of 2010. A Method 9 test report will not be submitted for the 2012 FFY because a RAP crushing unit did not operate and is not anticipated to operate at the site during the 2012 FFY. A current Method 9 test report will be submitted to the County upon resuming crushing operations at the site.

Please contact Erin Zimmet at Erin.Zimmet@oldcastlematerials.com or 386-257-5504 ext. 221 with any questions regarding this submission.

Thank you,

Mark Marine

President, APAC - Southeast, Inc.