DARABI AND ASSOCIATES, INC.

Environmental Consultants

Suite A · 730 North Waldo Road, Gainesville, Florida 32601 · Phone: 904/376-6533

October 22, 1997

Mr. A. A. Linero, P.E., Administrator New Source Review Section Department of Environmental Protection 2600 Blair Stone Road Tallahassee, Florida 32399 RECEIVED

OCT 27 1997

BUREAU OF AIR REGULATION

RE:

Mulliniks Construction Co., Inc.

File No. 7775036-002AC, 7775037-002AC, 7775038-002AC

Dear Mr. Linero:

In response to your letter of October 9, 1997, we provide the following additional information:

- 1. The list of components for each crusher unit is shown on Attachment 1.
- 2. Process flow diagram for each crusher is attached.
- 3. Attachment 2 identifies fugitive dust control measures.
- 4. Attachment 3 shows the fugitive dust emission for each crusher.
- 5. The unit can be operated in accordance with sub part 000 and rule 62-296.71 FAC where applicable. The 5% standard should be imposed only in areas that are subject to the rule.
- 6. Attachment 4 provides the required O&M schedule.
- 7. Copy of the existing air construction permit for Duval County is attached.

Please proceed with the process of this application.

cc: W. Hanks, BAR Districts Local Proq.

Sincerely,

DARABIAND)ASSOCIATES, INC

Frank A. Darabi, P.E.

President

FAD/lef[MULL.988] Enclosure xe: Billy Mulliniks

Crusher Plant ID: CP03

Make: Eagle Crusher

Crusher Plant ID: CP04

Make: Cedar Rapids

Crusher Plant ID: CP05

Make: Excel

Fugitive Dust Control:

To control fugitive dust emission from this facility, the best management practice such as the following will be incorporated into the daily operations:

- 1. All storage material will be kept in a confined area and wetted as needed.
- 2. The unpaved roads will be sprayed with water on an as needed basis.
- 3. Care will be exercised while transporting materials to minimize overfilling and spillage.

Mobile Rock Crusher

Fugitive Emission Factors:

From: Storage Piles at 35,000 tons stored AP.42 - Section 11.2.3

PM 0.0087 lbs/ton

 $35,000 \times 0.0087 = 304.5 \text{ lbs} \quad 0.15 \text{ TPY}$

From: Unpaved Road 0.33 lbs/VMT

 $0.33 \times 0.5 \text{ VMT} = 0.165 \text{ lbs/hr} \quad 0.165 \text{ TPY}$

(0.165)(2000 hrs/yr) =

Total 0.15 + 0.165 = 0.215 TPY

O&E MANUAL

Primary Crusher - visually check bearings, wear items, safety guards, grease all on daily basis.

Secondary Crusher - visually check bearings, wear items, safety guards, grease all on daily basis.

Screens - check to make sure screens are secured daily, check for damage to screens, grease and safety check daily.


Conveyor Belts - check daily for bearings, safety, tears in belts.

Water Nozzle - check hourly, and daily to make sure they stay properly positioned for the best control on all controlled places.

Water Pump - Make sure pump is checked and properly operating on a daily basis.


Power Units - Check engine oil and water daily, make sure all guards are in place.

Loader - Check daily general maintenance, oil, water, wear, tires.



PLANT D: CP04 200 TPH --WATER SPO1 G2 POWER PRIMARY CRUSHER UNIT PC1 150 HP 510 F02 1 CONVEYOR •1 WATER SP02 G3 POWER GENERATOR 300 HP SECONDARY CRUSHER SCI \$08 1 -WATER SP03 F05 GI **SCREEN** CONVEYOR •2 POWER STECKPILE S1 UNIT 600 HP FO4 F07 -WATER SP04 CONVEYOR *3 STOCKPILE

PLANT ID: CP05





Department of Environmental Protection

Lawton Chiles Governor Twin Towers Office Building 2600 Blair Stone Road Tallahassee, Florida 32399-2400

Virginia B. Wetherell Secretary

October 9, 1997

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Mr. Billy Mulliniks, Jr., President Mulliniks Construction Company, Inc. 5937 Soutel Drive Jacksonville, Florida 32219

Re: File Nos. 7775036-002-AC, 7775037-002-AC, & 7775038-002-AC Mobile Concrete and Asphalt Material Crushing Units

Dear Mr. Mulliniks:

The Department has reviewed your application for permits to construct three mobile concrete and asphalt material crushing units that was received in this office on October 7, 1997. We need the additional information/clarification listed below to process this request.

- 1. List the key components of the facility. Give make and model number of the equipment when available.
- 2. Provide a process flow diagram and brochure, if available, on the crusher system.
- 3. Describe how fugitive dust from this operation will be controlled.
- 4. Estimate the fugitive particulate matter emissions from each crusher. Use of AP-42 emissions factors to calculate these emissions will be acceptable.
- 5. Can this unit be operated in compliance with the visible emissions standards of 10 percent opacity for conveyors and 15 percent opacity for crushers specified in the new source performance standard (40 CFR 60, Subpart OOO) and a visible emission standard of 5 percent opacity as required by the particulate matter Reasonably Available Control Technology regulations (Rule 62-296.711, F.A.C.)?
- 6. Please provide an Operation and Maintenance plan for the crusher unit, including the water spray system used to control fugitive emissions.
- 7. Please provide a copy of the existing air construction permits for these facilities.

Mr. Billy Mulliniks Page 2 October 9, 1997

The Department will resume processing this application after receipt of the requested information. If you have any questions on this matter, please call Willard Hanks at 850/488-1344.

Sincerely,

A. A. Linero, P.E.

Administrator

New Source Review Section

AAL/wh

cc: Mr. Frank Darabi, Darabi and Assoc. District Air Program Administrators County Air Program Administrators

SENDER: Complete items 1 and/or 2 for additional services. Complete items 3, 4a, and 4b. Print your name and address on the reverse of this form so that we can return this card to you. Attach this form to the front of the mallpiece, or on the back if space does not permit. Write Return Receipt Requested on the mailpiece below the article number. The Return Receipt will show to whom the article was delivered and the date delivered.		I also wish to receive the following services (for an extra fee): 1. Addressee's Address 2. Restricted Delivery Consult postmaster for fee.	
Billy Mulliniks, Pres. Billy Mulliniks, Pres. Mulliniks Const. Co. 5937 Soutel Dr Jacksonville, Fl 32219	4b. Service Register Express Return Re 7. Date of D	Type ed Mail ceipt for Merchandis elivery	Certified Insured
5. Received By: (Print Name) Build Myllinulis 6. Signature: (Addressee or Agent) X Dun Mul Du PS Form 3811. December 1994	100	e's Address (Only	. I

P 265 659 466

US Postal Service
Receipt for Certified Mail
No Insurance Coverage Provided.

	Do not use for Internation	nal Mail (See reverse)
	Billy L	Julleniks
	Smet & Number	iks Coxist
	Post Office, State, & ZIP Co.	
	Postage	\$
10	Certified Fee	
	Special Delivery Fee	
	Restricted Delivery Fee	
199	Return Receipt Showing to Whom & Date Delivered	
PS Form 3800 , April 1995	Return Receipt Showing to Whom, Date, & Addressee's Address	
800	TOTAL Postage & Fees	\$
m 3	Postmark or Date	10-9-97
S Fo	7775036-002 7775037-002	777 5038-002
ă	111303/200	مرکز ۱۰۰