

## HALOGENATED SOLVENT DEGREASERS



## COMPLIANCE INSPECTION CHECKLIST

NSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI) RE-INSPECTION (FUI) ARMS COMPLAINT NO:							
AIRS ID#: 1030389 DATE: <u>8/20/2007</u> ARRIVE: <u>1:00PM</u> DEPART: <u>2:10PM</u>							
FACILITY NAME: F. K. INSTRUMENT CO INC							
FACILITY LOCATION: 2134 SUNNYDALE BLVD							
CLEARWATER 33765							
RESPONSIBLE OFFICIAL: ERICH KLOPFER PHONE: (727)461-6060							
CONTACT NAME: SAME PHONE: (							
REMITTANCE YEAR: 2006 ENTITLEMENT PERIOD: 5/10/2007 / 5/10/2012 (effective date) (end date)							
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box)  ☑ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE							
PART II: NOTIFICATION – Rule 62-210.300 FAC (check ☑ appropriate box(es))							
1. Halogenated solvent used at facility:  perchloroethylene							
PART III: CLASSIFICATION – Rule 62-213.300 FAC							
Indicate the machine type(s) observed at the facility:							
Batch Vapor, $x \le 1.21 \text{ m}^2$ $\square$ New In-line $\square$ Batch Cold (immersion) $\square$ Batch Cold (remote reservoir) $\square$							

	T IV: <u>GENERAL CONTROL REQUIREMENTS</u> – Rule 62-213.300 FAC . <u>Batch Vapor and In-Line Machines</u>			
	1. Does the facility maintain an idling and downtime mode cover that is readily opened and closed, that completely covers, has no cracks, holes, or defects; OR maintain a room designed			
	with reduced draft according to Part II, Section (5)(c)6.b of the permit notification?	⊠Yes	□No	
	2. Does the facility maintain a freeboard ratio of 0.75 or greater?	⊠Yes	□No	
	3. Does the facility utilize a parts basket or parts whose size is less than 50% of the solvent-air interface area; OR introduce parts or parts basket at 0.9 m/min (3 ft/min) or less?	⊠Yes	□No	
	4. Does the facility conduct all spraying operations within the vapor zone or an area not directly exposed to ambient air?	⊠Yes	□No	
	5. Does the facility install and maintain an automated parts handling system capable of moving the parts/parts basket at 3.4 m/min. (11ft/min) or less?		⊠No	
	6. Does the facility install and maintain a carbon adsorber on all machines using a lip exhaust? The exhaust concentration should not exceed 100 ppm halogenated solvent, the carbon adsorber should not be by-passed, the lip exhaust shall be located above the closed machine cover	r □Yes	□No	⊠N/A
	7. Does the facility have each machine equipped with:  a. a device to shut off sump heat if the solvent level drops to the heater coils?  b. a device to shut off sump heat if the vapor level rises above the height of the	⊠Yes	□No	
	vapor condenser?  c. a primary condenser?	⊠Yes ⊠Yse	□N □N	
	8. Does the facility store all waste solvent, still bottoms, and sump bottoms in closed containers?	⊠Yes	□No	
В. <u>В</u>	<ol> <li>atch Cold Cleaning Machines</li> <li>Does the facility collect and store all waste solvent in closed containers?</li> <li>Does the facility use a flexible hose or flushing device only within the</li> </ol>	□Yes	⊠No	
	freeboard area?	□Yes	⊠No	
	3. Does the facility drain cleaned parts for 15 seconds or longer or until dripping ceases, whichever is longer?	□Yes	⊠No	
	4. Does the facility maintain the solvent level inside the machine at or below the fill line?	Yes	⊠No	
	5. Does the facility immediately clean up spills during solvent transfer?  Store wipe rags in a covered container?	□Yes	⊠No	
	6. Does the facility operate the agitator to produce a rolling motion? (applicable only when air or pump agitated solvent bath used)	□Yes	□No	⊠N/A
	7. Does the facility ensure that the machine is not exposed to drafts greater than 40 m/min (132 ft/min) when the cover is open?	_ □Yes	⊠No	_
	8. Does the facility ensure that sponges, fabrics, wood and paper products are <u>not</u> placed in the machine?	□Yes	⊠No	
	9. Does the facility employ a tightly fitting cover over the solvent sump?  The cover must be closed at all times except during parts cleaning	∐Yes	□No	⊠N/A
_	10. Does the facility employ a tightly fitting cover and a water layer with a thickness of at least 2.5 cm (1 in.); OR employ a tightly fitting cover and maintain a freeboard ratio of 0.75? Tightly fitting cover must be closed at all times except during parts entry and removal.	⊠Yes	□No	□N/A

PA	PART V: PROCESS VENT CONTROLS – Rule 62-213.300 FAC (not applicable to batch cold cleaning machines)							
		e to meet requirements using			ļ			
	idling ei	mission limit / work practice s	standards (proceed to Part V	<i>T</i> )				
		institut in the production of	minutes (process to 1 a	,,	ļ			
		2						
A.	Batch Vapor	$\underline{\mathbf{r}}$ Machines, $\mathbf{x} \leq 1.21 \text{ m}^2$						
	(Select control	<u>l</u>			ļ			
	combination)		<u>DEVICE IN USE</u>					
	1.	working mode cover	1.0 freeboard ratio -	superheated vapor				
	2.	reduced room draft	1.0 freeboard ratio -	superheated vapor				
	3.	reduced room draft	1.0 freeboard ratio -	dwell				
	4.	freeboard refrig. device	superheated vapor					
	5.	freeboard refrig. device freeboard refrig. device	working mode cover reduced room draft					
	6.	freeboard refrig. device	1.0 freeboard ratio -					
	7.	freeboard refrig. device	dwell					
	9.	freeboard refrig. device	carbon adsorber					
	10. □g	carbon adsorber	1.0 freeboard ratio -	superheated vapor				
B.	Batch Vanor	Machines, $x > 1.21 \text{ m}^2$						
	_							
	(Select control		DEVICE IN LICE					
	combination	2	<u>DEVICE IN USE</u>					
	1.	freeboard refrig. device	superheated vapor	1.0 freeboard ratio				
	2. <u> </u>	freeboard refrig. device	superheated vapor	working mode cover				
	3.	freeboard refrig. device	superheated vapor	reduced room draft				
	4. ∐g 5. □g	freeboard refrig. device	superheated vapor	carbon adsorber				
	5.	freeboard refrig. device freeboard refrig. device	reduced room draft - reduced room draft -	dwell				
	0. <u> </u>	1.0 freeboard ratio	reduced room draft -	superheated vapor				
	<b>—</b> 8	_	_					
C.	Existing In-I	Line Machines						
	(Select control	_						
	combination)		<u>DEVICE IN USE</u>					
	1.	freeboard refrig. device	1.0 freeboard ratio -					
	2. <u>□</u> g	superheated vapor	1.0 freeboard ratio -					
	3.	freeboard refrig. device	dwell					
	4.	carbon adsorber	dwell					
D.	New In-Line	<u>Machines</u>						
	(Select control							
	combination)		<u>DEVICE IN USE</u>					
		freeboard refrig. device	superheated vapor -					
		freeboard refrig. device	carbon adsorber					
	Ш	superheated vapor	carbon adsorber					

PART VI: RECORDKEEPING REQUIREMENTS – Rule 62-213.300(3) FAC										
Has the responsible official maintained the following:										
<ol> <li>Owner's manuals, design specifications, and other instructional materials for cleaning machine and control equipment?</li></ol>			□No □No □No □No							
5. Dates of solvent additions and amounts added to each machine? (applicable only to those using an alternative emission limit)			□No	□N/A						
6. Idling emissions limit tests, including values obtained during the initial performance test? (applicable only to those using an idling emissions limit)			□No	⊠N/A						
			□No	⊠N/A						
			□No	□N/A						
			□No	□N/A						
			∐No	□N/A						
Shea L. Jackson	8/20/2007									
Inspector's Name (Please Print)	Date of Inspection									
	2008									
Inspector's Signature Approximate Date of Next			<u> </u>							

## **COMMENTS:**

- I met with the responsible official Erich Klopfer.
- Mr. Uwe Moerseburg, vice president of operations continues to maintain the tank and trichloroethylene usage records The facility is closely monitoring the tank use
- I reviewed the records logs with Mr. Klopfer and toured the facility. (See copies)
- I reviewed their records back to May 2006 July 2007. The 3 -month rolling average totals in the record logs ranged from 11.3 31.2 lbs / ft 2 for May 2007. There were no exceedances of the 30.7 lb/ft2 emission limit found during the record review. I advised Mr. Klopher that is appears that the amount for May is coming very close to exceedance. He stated they are trying very hard to not exceed and when that happens they don't use the tank. He stated the trichloroethylene tank is specifically operated for military contracted parts, and they still maintained that in his opinion there is not a good substitute.
- Mr. Klopfer stated he had only disposed of one 50 gallon drum of trichloroethylene waste just recently. (see Hazardous waste manifest invoice 6/6/2007 (See copy). He stated they are redoing the waste area and labeling the drums he should the new labels he was going to be using.
- I observed the tank it was not in use at this time. The freeboard ratio solvent /air interface is 25" x 16"x 2.75". The tank was locked at this time
- The baskets used for dipping, have not been changed I saw the 2 small baskets one was  $\sim 12$ " x 12" and the other was a round  $\sim 8$ " diameter basket, these were less the 50% of the air/solvent interface area.
- The parts are occasionally sprayed inside the tank. (See photo)
- The solvent tank is not required to have a carbon absorber above the closed cover. I asked him about the water separator on the tank. He showed the valve outlet for the covered separator compartment, but he stated they had never had to open or drain during their use of the tank. I advised him if there had been any water in the compartment would have to be treated as Hazardous waste disposal.
- Mr. Klopfer stated the tank is used only when specified under certain military defense contracts. They had come close to their in May 2007 as the 3 month rolling average was at 30.2 lbs/ft 2
- I toured the second building and observed the drums and machines on site. I observed cutting oils and water in use for the CNC machines operation. There did not appear to be any new chemical products in use. I observed mostly machine oils. Mr.

Klopfer stated they have not made any changes in the chemical products used at the facility, since last year. They are using denatured alcohol, for parts cleaning, ~ 2 gallons used per month. I observed the Citrus cleaner. Mr. Klopher stated he has had the same drum for 5 years and it continues to clean well and he has not run low on the cleaner.

• Mr. Klopher had purchased a new machine. He stated it has a closed loop system that does not mix the oil and waters, so does not have to use as much oil. He stated the newer machine s as these come along will reduce the oil waste. (See photo)