Appendix CP-1: Compliance Plan

EU014:

1. Visual inspection of emissions unit 014, scrubber No. 5, has been added to the monthly routine preventative maintenance routine and checklist to verify that no wet particulates are escaping the stack.

2. A management of change procedure has also been put in place requiring that repairs to dust equipment will be coordinated and approved by both the engineering and environmental managers before such repairs are made.

3. There is a facility improvement project to repair compressed air leaks in the plant's #3 Paint Line as a result of the consent order.