

**INSPECTION REPORT FORM
AIR POLLUTION EMISSION SOURCES**

FACILITY: APAC (Macasphalt) - Melbourne		DISTRICT: Central District	COUNTY: Brevard
ADDRESS: 6210 N. US 1 Melbourne, FL		CONTACT: Corbin Williams (Plant Manager) 321-242-1732	
AIRS# 0090049	PERMIT #: 0090049-007-AO	EXPIRATION DATE: September 30, 2010	
SOURCE DESCRIPTION: EU2 – Drum Mix Asphalt Plant			
INSPECTION DATE: January 7, 2009	AUDIT TYPE: Level 2	COMPLIANCE STATUS: In Compliance	
INSPECTION COMMENTS/RECOMMENDATIONS:			
<p>On January 7, 2009, Mr. Rodell Rice of FDEP visited the subject site for an annual compliance inspection. Contact was made with Mr. Corbin Williams, the plant manager. The plant was in operation at the time of the inspection. Mr. Williams provided Mr. Rice with copies of the operating records and the latest fuel analysis reports.</p> <p><u>Facility-wide Conditions</u> No objectionable odors were detected on or off facility grounds. No areas were observed where reasonable precautions were not taken to minimize pollutant emissions. No areas were observed where reasonable precautions were not taken to prevent the release of unconfined particulate. No visible emissions were observed coming from the baghouse stack. The plant was in operation.</p> <p><u>Emissions Units and Conditions</u> The following information pertains to the 12-month operating period ending December 2008: The plant produced 290,979.97 tons of asphalt, 24.2% of the 1.2 million ton permit limit. The total fuel consumption was 678,397 gallons, 26.8% of the 2.553 million gallon permit limit. The plant operated for 1708.6 hours. The fuel oil analysis indicated a sulfur content of less than 1.0%. Mr. Rice reviewed the last 12 months worth of fuel analyses and found the sulfur content to be consistently in compliance.</p>			
INSPECTOR(S) NAME(S): Rodell Rice			
SIGNATURE(S):		DATE: January 8, 2009	