

## DIGITAL PHOTOGRAPHIC LOG

1. **Facility Name:** Kinder Morgan-Port Manatee Terminal
2. **County / AIRS ID No:** Manatee County / 0810004
3. **Inspection Type:** INS2
4. **Inspection Date:** 09/14/2012
5. **Date Photographic Log was completed:** 09/26/2012
6. **Camera Used:** Canon PowerShot SD400 Digital Elph 5.0 Mega Pixels Serial No. 0523215786
7. **Recording Media:** SanDisk 256MB SD Card
8. **All Digital Photos Were Copied To:** Hard Disk of Computer DEP 143986
9. **Original Copy Is Stored In/On:** Hard disk of computer DEP 143986.
10. **Were the photos altered?:** NO\_\_ YES X explain yes: photo sizes were reduced for this log.
11. **Photographer:** Wendy D. Akins
12. **Signature of Photographer:** \_\_\_\_\_



Photo ID No: IMG\_424--Photo shows changes to Railcar Unloading Building rubber stripping (window increases)



Photo ID No: IMG\_425--This photos documents new aluminum skin on the Railcar Unloading Building.



Photo ID No: IMG\_426—Baghouse 3 (Emission Unit No. 003) for Railcar Unloading Building.



Photo ID No: IMG\_428—Baghouse 2 (Emission Unit No. 002) for Railcar Unloading Building.



Photo ID No: IMG\_429—Railcar Unloading Building



Photo ID No: IMG\_430—Emission Unit No. 001 and Railcar Unloading Building



Photo ID No: IMG\_431—Emission Unit No. 013 for Ship Unloading to Storage (New Hopper).



Photo ID No: IMG\_432—Emission Unit No. 013 for Ship Unloading to Storage (New Hopper) drop point to conveyor.



Photo ID No: IMG\_433—Tarp Equivalent “Catch all” devices.



Photo ID No: IMG\_434—Painting in progress. Paint will help protect conveyor covers from the elements.