DIGITAL PHOTOGRAPHIC LOG

- 1. Facility Name: Strategic Materials
- 2. County / Facility ID No: Manatee / 0810090
- 3. Inspection Type: INS2
- 4. Inspection Date: 08/15/12
- 5. Type of Camera Used: Canon Power Shot 5.0 mega pixels A530 (Air Section digital camera)
- 6. Digital Recording Media: Canon 16 MB MultiMediaCard
- 7. All Digital Photos Were Copied To: N/A
- 8. Original Copy Is Stored On: Nedin Bahtic's Computer\Documents and Settings\Bahtic_N\My Documents\My Pictures\Inspections\Manatee\0810090 Strategic Materials (08-15-12)

edin Balitic

- 9. Were the photos altered?: NO YES explain yes:
- 10. Photographer: Nedin Bahtic
- 11. Signature of Photographer:



Photo ID No. / Date / Time: IMG_1445 / 08-15-12 / 0948 Old glass processing line (Line No. 2)



Photo ID No. / Date / Time: IMG_1446 / 08-15-12 / 0949 Recently installed windscreen



Photo ID No. / Date / Time: IMG_1447 / 08-15-12 / 0949 Recently installed windscreen



Photo ID No. / Date / Time: IMG_1448 / 08-15-12 / 0950 Recently installed windscreen



Photo ID No. / Date / Time: IMG_1449 / 08-15-12 / 1006 Raw material pile on central/east side of property



Photo ID No. / Date / Time: IMG_1450 / 08-15-12 / 1010 South side of Line No. 1 building



Photo ID No. / Date / Time: IMG_1451 / 08-15-12 / 1011 View towards South (future Rational Energies building in background)



Photo ID No. / Date / Time: IMG_1452 / 08-15-12 / 1013 South side of Line No. 1 building



Photo ID No. / Date / Time: IMG_1453 / 08-15-12 / 1057 Recently installed windscreen (right) and waste pile (left)



Photo ID No. / Date / Time: IMG_1454 / 08-15-12 / 1057 Recently installed windscreen



Photo ID No. / Date / Time: IMG_1455 / 08-15-12 / 1119 View towards West