

0810201 Superior Asphalt
water truck at refilling station



09/21/2012 08:54

EPA Method 5 sampling probe
showing point indicators



09/21/2012 09:14

0810201 Superior Asphalt
aggregate piles (recycled
asphalt, sand, stone, glass)



09/21/2012 09:16

0810201 Superior Asphalt
aggregate bins and top of
baghouse



09/21/2012 09:16

0810201 Superior Asphalt final
product elevator, gas flue to baghouse
(foreground), facility entrance with
water truck (background)



09/21/2012 09:31

0810201 Superior Asphalt
entrance road looking out
(exiting). Gates are at property
boundary.



09/21/2012 09:46