

**INSPECTION REPORT FORM
AIR POLLUTION EMISSION SOURCES**

FACILITY: <p style="text-align: center;">Skyline - Homette #535</p>		DISTRICT: <p style="text-align: center;">Central District</p>	COUNTY: <p style="text-align: center;">Marion</p>
ADDRESS: <p style="text-align: center;">1230 SW 10th Street Ocala, FL 34474</p>		CONTACT: <p style="text-align: center;">Bruce Monteith - Division Manager (352) 629-7551 ext.</p>	
AIRS# <p style="text-align: center;">0830101</p>	PERMIT #: <p style="text-align: center;">0830101-006-AF</p>	EXPIRATION DATE: <p style="text-align: center;">July 30, 2012</p>	
SOURCE DESCRIPTION: <p style="text-align: center;">Mobile Home Manufacturing</p>			
INSPECTION DATE: <p style="text-align: center;">November 3, 2011</p>	AUDIT TYPE: <p style="text-align: center;">Level 2</p>	COMPLIANCE STATUS: <p style="text-align: center;">In-compliance</p>	
INSPECTION COMMENTS/RECOMMENDATIONS: <p>Ms. Wanda Parker-Garvin of FDEP visited the subject facility to conduct a compliance inspection. She made contact with Mr. Robert Watson, Plant Manager and Mr. Bruce Monteith, Division Manager of Skyline/Homette #535. Mr. Monteith provided Ms. Parker-Garvin with the usage records required by the current permit. Mr. Watson accompanied Ms. Parker-Garvin on a walkthrough inspection of the facility.</p> <p>The facility was not operating at the time of inspection, and Ms. Parker-Garvin did not observed any visible emissions. The company uses five (5) saws to score/break pieces of dryway, which connect to a vacuum system leading to a cyclone. It disposes waste material from the cyclone monthly and paints metal pieces in the Metal Assembly Frame area. The pieces remain in the area to dry from 2-5 days.</p> <p><u>Facility-wide Conditions:</u> No objectionable odors or visible emissions were detected on or off the site. No Pollution control device appeared to be circumvented or improperly operated. No areas were observed where precautions had not been taken to minimize pollutant emissions or prevent the release of unconfined particulate.</p> <p><u>Emissions Units and Conditions (October 2010 through September 2011):</u> The facility emitted 17.39 tons total VOC, 17.6% of the permit limit of 99 tons per 12-month period. The facility emitted 0.16 tons total HAPs, 0.64% of the permit limit of 25 tons per 12-month period. The highest single HAP is glycol ethers 0.11 tons, 1.1% of the permitted limit of 10 tons per 12-month period.</p> <p>Based on the site inspection and documentation provided, Ms. Parker-Garvin found the facility to be in compliance.</p>			
INSPECTOR (S) NAME (S): <p style="text-align: center;">Wanda Parker-Garvin</p>			
SIGNATURE (S): <p style="text-align: center;"><i>Wanda Parker Garvin</i></p>		DATE: <p style="text-align: center;">December 18, 2011</p>	

(rec'd 12/18/11 cs)