

## DIGITAL PHOTOGRAPHIC LOG

1. Facility Name: Pasco County Resource Recovery Facility, operated by Covanta Energy Group.
2. County / AIRS ID No: Pasco / 1010056
3. Inspection Type: INS2
4. Inspection Date: 01/20/2012
5. Date Photo Log was completed: 01/27/2012
6. Type of Camera Used: Olympus Camedia Digital Camera, 5.0 Megapixel, C-50 ZOOM, S/N 115248297
7. Digital Recording Media: FUJIFILM xD-Picture Card, 128 MB, S/N DPC-128, R31695 5RZ7, 0244 MAD
8. All Digital Photos Were Copied To: Digital Photographic Log and on hard disk of desktop computer DEP 143271
9. Original Copy Is Stored In/On: Hard disk of desktop computer DEP 143271
10. Were the photos altered?: NO X YES \_\_\_\_\_ explain yes:
11. Photographer: Amaury Betancourt
12. Signature of Photographer: \_\_\_\_\_



**Photo ID:** 1010056\_Photo\_01\_20\_2012-1; **Time:** 01/20/2012, Approx. 11:00 A.M.

Trash pit at Pasco County Resource Recovery Facility. The crane picks up trash and distributes trash within the pile to obtain a more uniform trash distribution. The crane then picks up trash and places the trash in the inlets of the municipal waste combustors, and the inlets are shown near the top of this photograph.



**Photo ID:** 1010056\_Photo\_01\_20\_2012-2; **Time:** 01/20/2012, Approx. 11:00 A.M.  
Building for trash drop-off at the Pasco County Resource Recovery Facility. The trash pit is shown on the right of the photograph.





Photo ID No: 1010056\_Photo\_01\_20\_2012-3

Time: 01/20/2012, Approx. 11:45 A.M.

Control room for CEM equipment, located in a trailer outside the main facility, at the Pasco County Resource Recovery Facility.



Photo ID No: 1010056\_Photo\_01\_20\_2012-4

Time: 01/20/2012, Approx. 11:45 A.M.

Gas tanks located outside the CEM Equipment trailer at the Pasco County Resource Recovery Facility.