INSPECTION REPORT FORM AIR POLLUTION EMISSION SOURCES

FACILITY:		DISTRICT:		COUNTY:	
Transflo Terminal Services, Inc.		Central District		Seminole	
ADDRESS:		CONTACT:			
2591 West 5th Street		Sidney Smith, Terminal Manager			
Sanford, FL		407-330-1761			
AIRS#	PERMIT #:	EXPIRATION DATE:			
1170379	1170379-008-AF	November 5, 2013			
SOURCE DESCRIPTION:					
Bulk Solids and Liquid Transfer Facility					
INSPECTION DATE:	AUDIT TYPE:			COMPLIANCE STATUS:	
January 19, 2012	Level 2		In	In Compliance	
INSPECTION COMMENTS/RECOMMENDATIONS:					
Wanda Parker-Garvin with FDEP visited the subject facility to perform a compliance inspection. She made contact with Mr. Sidney Smith, Terminal Manager. Mr. Smith initially gave Ms. Parker-Garvin safety instructions in case of an incident or if an emergency evacuation was needed. Ms. Parker-Garvin obtained and reviewed a copy of the records required by Conditions 13 of the current permit. Mr. Smith stated the facility no longer transfers aviation fluid and that was reflected in the renewal application. Mr. Smith accompanied Ms. Parker-Garvin on a walk-through of the site. The dry commodities or bulk solids are located on the outside tracks and the hazardous commodities or bulk liquids are located on the inside tracks for safety reasons. Ms. Parker-Garvin witnessed limestone being loaded into a truck and she did not observe any unconfined emissions. Facility-wide Conditions No objectionable odors were detected on or off facility property.					
No areas were observed where reasonable precautions were not used to prevent unconfined particulate emissions.					
Emissions Units and Conditions (December 2010 – November 2011) The facility transferred 25,282 tons of bulk solids , 6.32% of the permit limit of 400,000 tons per 12-month period. The facility transferred 0 tons of Portland cement , 0 % of the permit limit of 100,000 tons per 12-month period. The facility transferred 5,946,094 gallons of non-HAP liquids , 1.91% of the permit limit of 311,000,000 gallons per 12-month period. The facility emitted (7.32 lbs) 0 tons of HAPs , .0% of the permit limit is 25 tons HAPs per 12-month period. The facility emitted 0.45 tons VOCs , 1.8% of the permit limit is 25 tons VOCs per 12-month period.					
Based on the inspection and documentation provided, Ms. Parker-Garvin found the facility to be in-compliance.					
INSPECTOR(S) NAME(S): Wanda Parker-Garvin					
SIGNATURE(S):			DATE	<u>. </u>	
Wanda Parker Lawin			57111	February 16, 2012	