

**05-14-2013 Lime Kiln Stack Test
at the Miami-Dade County Alexander Orr WTP
Facility No. 0250314**



**Location of Stack Test. Note direction of gas flow is down.
(Stack in background is blocked and inoperable.)**



Closeup of sample probes in the sample ports during sampling.



Sampling Equipment



Sampling Equipment