

CONCRETE BATCHING PLANT



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) ⊠ COMPLAINT/DISCOVERY (CI) □			
RE-INSPECTIO	ON (FUI) ARMS COMPLAINT NO:	: <u></u>	
FACILITY: Vulcan Materials Company		DISTRICT:	
DBA/Site Name: Florida Rock Industries, Inc Tarpon Springs Ready Mix Plant		Southwest	
ADDRESS: 633 New Anclote Road		CONTACT PHONE:	
Tarpon Springs, FL		727-919-4392	
ARMS NO:	PERMIT NO:	Expiration Date: 11/7/2016 Renewal Date: 10/7/2016	
1030063 002	1030063-008-AG	Test Date: 2/24/2000	
EMISSION UNIT DESCRIPTION: Concrete Block Plant: Cement Silo controlled by a CP-LPR-6-S-FS dust collector, serial number 016173			
INSPECTION DATE:	INSPECTION COMPLIANCE STATUS (c)	$heck \Box only one box)$	
1/24/12		liance; Significant Non-Compliance	
	PART I: General Review:		
1. Permit File Review		∑Yes □ No	
2. Introduction and Entry		⊠Yes □ No	
Comments: I met with Ray Ford, the Superintender	nt, who provided me with the maintenance logs	S.	
3. Is the Authorized Representative still		□Yes ⊠ No	
Comments: James Burkholder is the A	Authorized Rep. Letter sent April 2011.		
4. Is the facility contact still John Berger?			
5. If the answer to 3 or 4 is "No", did the facility provide an administrative update within 30 days? [62-210.310(2)(d), F.A.C.]			
PART II: <u>TESTING REQUIREMENTS</u> – Rule 62-296.414, F.A.C. (check □ appropriate box(es), if a shaded box is checked, this would indicate noncompliance)			
Compliance Demonstration 1. □ New Facilities / □ New Process Equipment— (permitted pursuant to Rule 62-296.414(4)(a), F.A.C., Air General Permits) Did this facility demonstrate initial compliance no later than 30 days after beginning operation?□ Yes □ No			
2. \(\subseteq \textbf{Existing Facilities} - \text{(permitted pursuant to Rule 62-296.414(4)(a), F.A.C., Air General Permits)} \) In order to demonstrate annual compliance, was an annual visible emissions test conducted on each dust collector exhaust point within 365 days (annually thereafter) of the previous visible emissions compliance test? \(\subseteq \text{Yes} \) \(\subseteq \subseteq \text{No} \)			
*See Comments			
Test Reports 3. Do the submitted visible emission tests demonstrate compliance with the 5 percent opacity limit?			
4. Was the department notified at least 15	days prior to the test? [62-297.310(4)(a)9. F	A.C.] Yes No	
5. Was the required test report filed with the department as soon as practical, but no later than 45 days after the test was completed? [62-297.310(8)(b)			
6. Was the facility visible emissions test(s) conducted according to EPA Method 9? [62-297.401(9)(c), F.A.C] Yes No			
7. During visible emissions tests of the silo dust collector exhaust points was the loading of the silo conducted at a rate that is representative of the normal silo loading rate, or at least at the minimum 25 tons per hour rate,			

PART II. TESTING DECHIDEMENTS Dula 62 206 414 E A C		
PART II: <u>TESTING REQUIREMENTS</u> – Rule 62-296.414, F.A.C. (check □ appropriate box(es), if a shaded box is checked, this would indicate noncompliance)		
unless such rate is unachievable in practice? [62-296.414(3), F.A.C.]	Yes No	
•		
8. Are emissions from a weigh hopper (batcher) operation controlled by the silo dust collector? (If answer		
to this question is "Yes", then continue on to questions 8.a) and 8.b) below. If answer is "No" then		
skip to question 9.)	□ Yes □ No	
a) Was the batching operation in operation during the visible emissions test? [62-296.414(3(c)), F.A.C.]		
b) During the visible emissions test, was the batching rate representative of the normal batching rate and duration? [62-296.414(3)(c), F.A.C.]	∏ Yes ∏ No	
9. If emissions from the weigh hopper (batcher) operation are controlled by a dust collector, which is separate from		
the silo dust collector, are the visible emissions tests of the weigh hopper (batcher) dust collector while batching		
at a rate that is representative of the normal batching rate and duration? [62-296.414(3)(d), F.A.C.]	□ Yes □ No	
10. Was a visible emissions test(s) conducted by the inspector during this site visit according to EPA Method 9?	□ Yes □ No	
a) The visible emission test resulted in an opacity of% for the highest six minute average.		
b) Did the test indicate the facility is operating in compliance with the 5% opacity standard?	Yes No	
PART III: OPERATING/RECORDKEEPING REQUIREMENTS - Rule 62-210.310(5)(b), F.A	.C.	
(check \square appropriate box(es), if a shaded box is checked, this would indicate noncompliance)		
1. Is this facility: 1) a 🖂 stationary; 2) a 🗌 relocatable; or does it have: 3) both, 🗌 stationary and relocatable	e	
concrete batching and/or nonmetallic mineral processing plants? (Please check \Box only one box.)		
2. For any combination of stationary or relocatable concrete batching plants, located with other concrete batching	g plants	
or nonmetallic mineral processing plants:		
a) Are there any additional nonexempt units located at this facility? [62-210.310(5)(b)4.a., F.A.C.]	<u>∐ Yes</u> <u>∐</u> No	
b) Is the total combined annual facility-wide fuel usage of all plants less than or equal to the fuel usages listed below: [62-210.310(5)(b)4.b., F.A.C.]	□ Yes □ No	
1) 275,000 gallons of diesel fuel – usage equals gallons		
2) 23,000 gallons of gasoline – usage equals gallons		
3) 44 million standard cubic feet on natural gas – usage equals cubic feet		
4) 1.3 million gallons of propane – usage equals gallons 5) or an equivalent prorated amount if multiple fuels are used onsite – usage equals % of all	fuels	
	jueis	
3. Does the owner/operator of the concrete batching plant submitting this registration maintain records to account for site-wide fuel consumption for each calendar month and each consecutive twelve (12) months, and		
are these records available for Department inspection for a period of at least five (5) years?		
[62-210.310(5)(b)4.d., F.A.C.]	☐ Yes ☐ No	
<u>Relocation Notification</u> - (Rule 61-210.310(5)(b)3.b., F.A.C.)		
1. Is the relocatable concrete batching plant used to mix cement and soil for onsite soil augmentation or		
stabilization?—(if your answer is YES, please proceed to 1. a) thru 1.b) below)	□ Yes □ No	
a) Did the owner or operator notify the Department by telephone, e-mail, fax, or written communication		
at least one (1) business day prior to changing location?b) Did the owner or operator transmit a Facility Relocation Notification Form (DEP No. 62-210.900(6))	∐ Yes ∐ No	
to the Department no later than five (5) business days following a relocation?	□ Yes □ No	
	110	
If your answer to number 1. above is NO, proceed to 2. below 2. Did the owner or operator transmit a Facility Relocation Notification Form (DEP No. 62-210.900(6)) at		
least five (5) business days prior to relocation?	□ Yes □ No	
PART IV: <u>Unconfined Emissions - 62-296.414(2)</u>		
(check □ appropriate box(es), if a shaded box is checked, this would indicate noncompliance)		
1. Does the owner /operator of the concrete batching plant take reasonable precautions to control unconfined emissions	V _{aa} □ M	
unconfined emissions	⊠ Yes ∐ No	
wnich of the following methods are used: a) management of roads, parking areas, stock piles, and yards, which shall include one or more of the following:		
1) Paving and maintenance of roads, parking areas, stock piles, and yards?		
2) application of water or environmentally safe dust-suppressant chemicals when necessary to control		
emissions?		
3) removal of particulate matter from roads and other paved areas under control of the owner/operator to re-entrainment, and from building or work areas to reduce airborne particulate matter?	⊠ Yes □ No	

PART IV: <u>Unconfined Emissions - 62-296.414(2)</u> (check □ appropriate box(es), if a shaded box is checked, this would indicate noncompliance)		
4) reduction of stock pile height, or installation of wind breaks to mitigate wind entrainment of		
particulate matter from stock piles?		
PART V: General Procedure Requirements and Conditions (check □ appropriate box(es), if a shaded box is checked, this would indicate noncompliance)		
Administrative Changes: 1. Were there any changes in the name, address, or phone number of the facility or authorized representative not associated with a change in ownership or with a physical relocation of the facility or any emissions units or operations comprising the facility; or any other similar minor administrative change at the facility Yes No 2. If yes, did the facility provide written notification within 30 days of the change? [62-210.310(2)(d), F.A.C.] Yes No		
Permit Effective Period – [62-210.310(3)(a), F.A.C.] 1. Is the general permit for this facility still within the 5 year effective period? Yes No		
2. Did the facility submit the new re-registration form at least 30 days prior to permit expiration?		
New or Modified Process Equipment or Change in Ownership		
1. Since the last registration form submittal has there been [62-210.310 (2)(b)2] a) installation of any new process equipment?		
Noncompliance Notice: - [62-210.310(3)(i), F.A.C.] 1. Did the facility have any instances where they were unable to comply with or will be unable to comply with any condition or limitation of the air general permit?		
PART VI: Comments		
O&M Plan The pollution control equipment shall be operated and maintained in accordance to the operation and maintenance (O&M) plan. The O&M plan shall include, but is not limited to: (1) Operating parameters of the pollution control device; (2) Time table for the routine maintenance of the pollution control device as specified by the manufacturer; (3) Time table for routine periodic observations of the pollution control device sufficient to ensure proper operation; (4) A list of the type and quantity of the required spare parts for the pollution control device which are stored on the premises of the permit applicant; (5) A record log which will indicate, at a minimum: a. When maintenance and observations were performed; b. What maintenance and observations were performed; and c. Who performed said maintenance and observations. d. Acceptable parameter ranges for each operational check. [Pinellas County Code, Subsection 58-128]		
Reviewed records for the months ofNo records available due to unit shutdown		
Comments:		
This unit has been shut down for a couple of years. A visible emissions test has not been performed due to shut down.		

Exit Interview: I informed Ray that the facility appears to be i	in compliance at this time.
Shannon Ransom	1/24/12
Inspector's Name	Date of Inspection
	~1/2013
Inspector's Signature	Approximate Date of Next Inspection

H:\users\wpdocs\airqual\Air_Compliance\AQI\1030063 002 80754.doc

4 of 3 Revised 01/05/06