

Air Pollution Source Inspection Report Form

Florida Department of Environmental Protection, Southwest District

PAGE 1 OF 1**FACILITY: KEYSTONE FLORIDA INC. (KERSEY FUNERAL HOME)****ID#: 1050179****COUNTY: POLK****ADDRESS: 108 E. LAKE STELLA DR., AUBURNDALE****INSPECTION DATE: 12/15/09****TIME IN:0950****TIME OUT:1025****CONTACT: THOMAS LIMBER, JR.****INSPECTION TYPE: 2****EU(s) INSPECTED: ALL****SOURCE DESCRIPTION: HUMAN CREMATORY****CURRENT PERMIT:****PERMIT EXPIRATION DATE:****INSPECTION FINDINGS**

UNANNOUNCED INSPECTION TO OBTAIN INFORMATION PERTAINING TO AFTERBURNER TEMPERATURE AND RESIDENCE TIME DETERMINATION, INCLUDING LOCATION OF THERMOCOUPLES. SEE ATTACHMENT FOR DRAWING OF THERMOCOUPLE LOCATION.

FACILITY NAME	KEYSTONE FLORIDA
I.D. NUMBER	1050179
CREMATORY MANUFACTURER	CRAWFORD
MODEL NO.	C-1000H
SERIAL NO.	1-CH8749-1287-S
CHART RECORDER MAKE/MODEL	HONEYWELL DR45A2-1100
RECORDER CALIBRATION DATE	2/16/2005
DIGITAL CONTROLLER MAKE/MODEL	NOT AVAILABLE
CONTROLLER CALIBRATION DATE	NOT AVAILABLE
RATED BTU INPUT-CREMATION BURNER	NOT AVAILABLE
RATED BTU INPUT-AFTERBURNER	NOT AVAILABLE
RATED BTU INPUT-TOTAL	2.0 MMBTU
REFRACTORY DEPTH FROM SHELL*	9 INCHES

*DEPTH FROM OUTSIDE OF METAL SHELL TO OUTSIDE
OF REFRACTORY LINING MEASURED AT UNIT DOOR

THE CREMATORY OPERATING LOG AND CIRCULAR TEMPERATURE CHARTS WERE INSPECTED FOR JANUARY THRU NOVEMBER 2009 AND WERE IN ORDER.

COMPLIANCE STATUS: IN**INSPECTOR'S SIGNATURE:****INSPECTOR'S NAME:****DATE:**

W. SCHROEDER

