

DIGITAL PHOTOGRAPHIC LOG


1. Facility Name: CEMEX – Davenport Ready-Mix Plant
2. County / Facility ID No: Polk/1050249
3. Inspection Type: INS2
4. Inspection Date: 05/26/2011
5. Type of Camera Used: Olympus Camedia C-50 Zoom 5.0 mega pixels (Air Section digital camera)
6. Digital Recording Media: FujiFilm 128 MB xD-Picture Card
7. All Digital Photos Were Copied To: C:\Documents and Settings\haines_c\Desktop
8. Original Copy Is Stored In/On: C:\Documents and Settings\sherman_SJS\
9. Were the photos altered?: NO YES _____ explain yes:
10. Photographer: Steven Sherman
11. Signature of Photographer: 



Photo ID No. / Date / Time: Picture 001 05-26-2011 11:15
Entrance to Inactive facility.



Photo ID No. / Date / Time: Picture 002 05-26-2011 11:15
Inactive silos and weigh hopper on facility grounds.



Photo ID No. / Date / Time: Picture 003 05-26-2011 11:15
Empty aggregate storage area behind fence.