

Florida Department of Environmental Protection
ARM Inspection Report

ARMS ID No. 850010	Owner/Company Name: CONTINENTAL FLORIDA MATERIALS	Inspection Date:
-----------------------	--	------------------

Site Name: CONTINENTAL/STUART/CONCR BATCH PLNT	County: MARTIN
---	-------------------

Permit No(s). 0850010004AG	Expiration Date: March 14, 2009	Type: AG
-------------------------------	------------------------------------	-------------

Facility Contact Name: Dan Henderson	Title: Manager	Phone: 772-260-3583
---	-------------------	------------------------

Emissions Unit(s):	Compliance Status:
Fac-wide	MNC

Field Observations:

I was at US Paverscape, LLC, adjacent to this plant, when I observed fugitive dust generated by a truck backing into the batcher. The dust did not rise much above the top of the tires and was localized and did not leave the plant boundaries. I observed accumulated fine and coarse aggregate material on the ground in the area in front of the batcher. I spoke with Dan Henderson and informed him of the need to implement reasonable precautions. I advised that the materials should be swept up.

This plant ~~has~~ has become a satellite plant as of a couple months ago. It was active today for a local job. It is not known if the accumulations I observed were from the day's operations or if they had been there since the last time of operations. (Plant operations are limited).

Inspector's Name Allen Rainey	Signature: <i>Allen J Rainey</i>	Date: 6/24/07
----------------------------------	-------------------------------------	------------------