C.M.
FLORIDA 1

PERCHLOROETHYLENE DRY CLEANERS



## COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2)	COMPLAINT/DISCOVERY (CI)	
AIRS ID#: 0571058 DATE: <u>8/29/2006</u>	ARRIVE: <u>8:30 am</u> DEPART: <u>9:30 am</u>	
FACILITY NAME: SUNSET CLEANERS		
FACILITY LOCATION: 18455 N Hwy 41		
LUTZ 33549		
<b>RESPONSIBLE OFFICIAL:</b> MARK KREKORIAN	<b>PHONE:</b> (813)949-8833	
CONTACT NAME:	PHONE:	
REMITTANCE YEAR: 2005 ENTIT	<b>CLEMENT PERIOD:</b> 7/23/2006 / 7/23/2011 (effective date) (end date)	
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box)         ☑ IN COMPLIANCE       ☐ MINOR Non-COMPLIANCE         ☑ IN COMPLIANCE       ☐ MINOR Non-COMPLIANCE		
PART II: FACILITY CLASSIFICATION - Rule 62- (check ☑ only one box in A)	-213.300 FAC	
A. 1. Existing small area source dry-to-dry only, x < 140 gal/yr transfer only, x < 200 gal/yr both types, x < 140 gal/yr (constructed before 12/9/91)	2. <u>New small area source</u> dry-to-dry only, $x < 140$ gal/yr transfer only, $x < 200$ gal/yr both types, $x < 140$ gal/yr (constructed on or after 12/9/91)	
3. Existing large area source dry-to-dry only, $140 \le x \le 2,100$ gal/yr transfer only, $200 \le x \le 1,800$ gal/yr both types, $140 \le x \le 1,800$ gal/yr (constructed before 12/9/91)	4. New large area source dry-to-dry only, $140 \le x \le 2,100$ gal/yr transfer only, $200 \le x \le 1,800$ gal/yr both types, $140 \le x \le 1,800$ gal/yr (constructed on or after 12/9/91)	
5. Ineligible for General Permit drop store/out of business/petroleum facility exceeds above limits		
<b>B</b> . The total quantity of perchloroethylene (perc) purchased within the preceding 12 months by this dry cleaning facility was 90 gallons.		

PART III: <u>GENERAL CONTROL REQUIREMENTS</u> – Rule 62-213.300 FAC	(check ☑ only one box	
Does the responsible official of the dry cleaning facility:	for each question)	
1. Store perc, and wastes containing perc, in tightly sealed & impervious containers?	Yes No N/A	
2. Examine the containers for leakage?	Yes No N/A	
3. Close and secure machine doors except during loading/unloading?	Yes No	
4. Drain cartridge filters in their housing or in sealed containers for at least 24 hours prior to disposal?	Yes No N/A	
5. Maintain solvent-to-carbon ratios and steam pressure for carbon adsorber beds according to the manufacturer's specifications?	⊠Yes □ No □ N/A	

PART IV: PROCESS VENT CONTROLS – Rule 62-213.300 FAC				
(Refer to Part II-A.14. Classification: page <u>1</u> of <u>4</u> , this form)				
	1. If the facility classification is a <b>Existing small area source</b> , no controls are required. <b>Proceed to Part V.</b>			
	2. If the facility classification is a <u>New small area source</u> , the machine should be equipped with a refrigerated condenser. Complete section A. below.			
	3. If the facility classification is a <b>Existing large area source</b> , the machine should be equipped with either a refrigerated condenser or a carbon adsorber. <b>Complete both sections A and B below.</b> <i>Carbon adsorber must have been installed prior to September 22, 1993</i>			
	4. If the facility classification is a <u>New large area source</u> , the machine should be equipped with a refrigerated condenser. Complete both sections A and B below.			
А.	Has the responsible official of all <u>existing large area &amp; new sources</u> :	(check ☑ only one box for each question)		
1.	Equipped all machines with the appropriate vent controls?	Yes No		
2.	Equipped dry-to-dry machines with a closed-loop vapor venting system?	Yes No N/A		
3.	Equipped the condenser with a diverter valve so airflow will be directed away from the condenser upon opening the door?	Yes No N/A		
4.	Measured and recorded the temperature of the outlet exhaust stream of a refrigerated condenser on a weekly basis?	Yes No		
5.	Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded 45° F?	- Xes No N/A		
6.	Conducted all temperature monitoring after an appropriate cool-down period and after verifying that the coolant had been completely charged?	⊠Yes □No		

PA	PART IV: <u>PROCESS VENT CONTROLS</u> – Rule 62-213.300 FAC (continued)			
B.	Does the responsible official of an existing large or new large area source also:	(check 🗹 only each ques		
1.	Measure and record the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines on a weekly basis?	Yes 🗌	No	
2.	Measure and record the washer exhaust temperature at the condenser inlet and outlet weekly?		No □N/.   No ⊠ N/	
3.	Measure and record the perc concentration in the exhaust stream weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped exclusively with a carbon adsorber?	Yes	No 🛛 N	/A
	a) Is the perc concentration equal to, or less than 100 ppm?	Yes	No No	/A
4.	Assure that the sampling port on the carbon adsorber exhaust for measuring perc concentrations is at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet?	Yes	No 🖂 N/	/A
5.	Equip transfer machines (dryers, reclaimers, and washers) with individual condenser coils?	- Yes	No 🛛 N	/A
6.	Route airflow to the carbon adsorber (if used) at all times?	Yes	No 🛛 N	/A

PART V: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-213.300(3) FAC			
Does the responsible official:	(check ☑ only one box for each question)		
1. Maintain receipts for perc purchased?	- 🛛 Yes 🗌 No		
2. Maintain rolling monthly total of yearly perc consumption?	Yes INO		
3. Maintain leak detection inspection and repair reports for the following:			
a) documentation of leaks repaired w/in 24 hrs? or;	- 🛛 Yes 🗌 No 🗌 N/A		
b) documentation of parts ordered to repair leak and leak repaired w/in 2 days and parts installed w/in 5 days of receipt?	Yes No N/A		
4. Maintain calibration data? (for applicable direct reading instruments)	Yes No N/A		
5. Maintain exhaust duct monitoring data on perc concentrations?	Yes No N/A		
6. Maintain a startup/shutdown/malfunction plan?	Yes No		
7. Maintain deviation reports?	- Yes No N/A		
a) Problem corrected?	- 🗌 Yes 🗌 No 🖾 N/A		
8. Maintain a compliance plan, if applicable?	- 🗌 Yes 🗌 No 🖾 N/A		

## PART VI: <u>LEAK DETECTION AND REPAIRS</u> – Rule 62-213.300 FAC

1. Does the responsible official conduct a weekly (for small sources, bi-weekly) leak

(check ☑ only one box for each question)

detection and repair inspection?	Xes No		
2. Does the facility maintain a leak log?	🗌 Yes 🖾 No		
<ul> <li>c) Filter gaskets and seating ⊠Yes □No □N/A i) Exha</li> <li>d) Pumps ⊠Yes □No □N/A j) Dive</li> </ul>	ck cookers XYes No N/A ls Yes No N/A aust dampers Yes No N/A erter valves Yes No N/A tridge filter housings Yes No N/A		
<ul> <li>4. Which method(s) of detection (is/are) used by the responsible official?</li> <li>a) Visual examination (condensed solvent on exterior surfaces) a) a) a</li> <li>b) Physical detection (airflow felt through gaskets) b) b b</li> <li>c) Odor (noticeable perc odor) c) a</li> <li>d) Use of direct-reading instrumentation (FID/PID/calorimetric tubes) d) a</li> <li>e) Halogen leak detector</li></ul>			
<ul> <li>4) Kept in a clean and secure area when not in use?</li></ul>	4) Yes No		
Felipe Ascano	8/29/2006		
Inspector's Name (Please Print)	Date of Inspection		
	8/2007		
Inspector's Signature Approximate Date of Next Inspection			
<ul> <li>COMMENTS: The purpose of the visit was an annual inspection. We found the following:</li> <li>1. The record keeping of the Perc purchase was very good and organized.</li> <li>2. The gauge temperature reading was recorded weekly with an average of 41 F.</li> <li>3. The vicinity around the dry cleaning machine was very clean and well maintained.</li> <li>4. The Perc was loaded directly with a hookup connection. No container of perc was at the site.</li> <li>5. The monthly perc consumption was recorded correctly and the total for past 12 months was 90 gallons and it was verified.</li> <li>6. The machines were not in operation today. No leaks or odors were noticed.</li> </ul>			

- 7. The regulations. 8. Thi The waste from the dry cleaning machine was properly store in the tight lid containers to be disposed in accordance with
  - This facility classified as a small area source.