

## PERCHLOROETHYLENE DRY CLEANERS



## COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE:	ANNUAL (INS1, INS2)	COMPLAINT/DISCOVERY	(CI)		
	RE-INSPECTION (FUI)	ARMS COMPLAINT NO:			
AIRS ID#: 0970058 DA	TE: <u>01/14/10</u>	<b>ARRIVE:</b> <u>10:34am</u>	DEPART: <u>11:14am</u>		
FACILITY NAME: DIXIE CLEANERS					
FACILITY LOCATION	4038 13 ST				
	ST. CLOUD 34769				
OWNER/AUTHORIZE	D REPRESENTATIVE: SARA	ABJIT SINGH PHONE:	(407)892-4411		
CONTACT NAME:		PHONE:			
ENTITLEMENT PERIOD: / (effective date) (end date)					
	(circuive date) (cird date)				
PART I: INSPECTION	COMPLIANCE STATUS (che	eck 🗹 only one box)			
☐ IN COMPLIANO	CE MINOR Non-COMPI	LIANCE SIGNIFICANT	Non-COMPLIANCE		
	CLASSIFICATION - Rule 62-21	3.300 FAC			
(cneck 🛂 oni	ly one box in A)				
A. 1. Existing smal	l <u>l area source</u> X ly, x < 140 gal/yr	2. New small area source dry-to-dry only, x < 140 g	ral/vr		
transfer only,	x < 200 gal/yr	transfer only, x < 200 gal/	/yr		
both types, x (constructed b	< 140 gal/yr before 12/9/91)	both types, $x < 140$ gal/yr (constructed on or after 12			
,					
	ly, $140 \le x \le 2,100 \text{ gal/yr}$	<b>4. New large area source</b> dry-to-dry only, $140 \le x \le$			
transfer only,	$200 \le x \le 1,800 \text{ gal/yr}$ $40 \le x \le 1,800 \text{ gal/yr}$	transfer only, $200 \le x \le 1$	,800 gal/yr		
	before $12/9/91$ )	both types, $140 \le x \le 1,80$ (constructed on or after 12)			
5. Ineligible for General Permit					
drop store/out	t of business/petroleum ds above limits				
<b>B</b> . The total quantity of perchloroethylene (perc) purchased within the preceding 12 months by this dry cleaning facility was 80 gallons.					

PA	RT III: GENERAL CONTROL REQUIREMENTS – Rule 62-213.300 FAC	(check <b>☑</b> only one box			
Do	es the responsible official of the dry cleaning facility:	for each question)			
1.	Store perc, and wastes containing perc, in tightly sealed & impervious containers?	⊠Yes □No □N/A			
2.	Examine the containers for leakage?	⊠Yes □ No □ N/A			
3.	Close and secure machine doors except during loading/unloading?	⊠ Yes □ No			
	Drain cartridge filters in their housing or in sealed containers for at least 24 hours prior to disposal?	⊠Yes □ No □ N/A			
	Maintain solvent-to-carbon ratios and steam pressure for carbon adsorber beds according to the manufacturer's specifications?	□Yes □ No □ N/A			
	RT IV: PROCESS VENT CONTROLS – Rule 62-213.300 FAC efer to Part II-A.14. Classification: page 1/2, this form)				
	1. If the facility classification is a <b>Existing small area source</b> , no controls are requi	ired. Proceed to Part V.			
	2. If the facility classification is a <u>New small area source</u> , the machine should be equipped with a refrigerated condenser. <b>Complete section A. below.</b>				
	3. If the facility classification is a <b>Existing large</b> area source, the machine should be equipped with either a refrigerated condenser or a carbon adsorber. <b>Complete both sections A and B below.</b> Carbon adsorber must have been installed prior to September 22, 1993				
	4. If the facility classification is a <u>New large area source</u> , the machine should be excondenser. Complete both sections A and B below.	quipped with a refrigerated			
<b>A.</b>	Has the responsible official of all <u>existing large</u> <u>area &amp; new sources</u> :	(check ☑ only one box for each question)			
1.	Equipped all machines with the appropriate vent controls?	Yes No			
2.	Equipped dry-to-dry machines with a closed-loop vapor venting system?	Yes No N/A			
3.	Equipped the condenser with a diverter valve so airflow will be directed away from the condenser upon opening the door?	- Yes No N/A			
4.	Measured and recorded the temperature of the outlet exhaust stream of a refrigerated condenser on a weekly basis?	Yes No			
5.	Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded 45° F?	- Yes No N/A			
6.	Conducted all temperature monitoring after an appropriate cool-down period and after verifying that the coolant had been completely charged?	□Yes □No			

PART IV: PROCESS VENT CONTROLS - Rule 62-213.300 FAC (continued)				
B. Does the responsible official of an existing large or new large area source also:	(check ☑ only one box for each question)			
1. Measure and record the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines on a weekly basis?	□Yes □No			
Measure and record the washer exhaust temperature at the condenser inlet and outlet weekly?	- □Yes □ No □N/A			
a) Is the temperature differential equal to, or greater than 20° F?	☐Yes ☐ No ☐ N/A			
3. Measure and record the perc concentration in the exhaust stream weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped exclusively with a carbon adsorber?	□Yes □ No □ N/A			
a) Is the perc concentration equal to, or less than 100 ppm?	☐Yes ☐ No ☐ N/A			
4. Assure that the sampling port on the carbon adsorber exhaust for measuring perc concentrations is at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet?	□Yes □ No □ N/A			
Equip transfer machines (dryers, reclaimers, and washers) with individual condenser coils?	- Yes No N/A			
6. Route airflow to the carbon adsorber (if used) at all times?	□Yes □ No □ N/A			
PART V: RECORDKEEPING REQUIREMENTS – Rule 62-213.300(3) FAC				
Does the responsible official:	(check ☑ only one box for each question)			
1. Maintain receipts for perc purchased?	Yes No			
2. Maintain rolling monthly total of yearly perc consumption?	⊠ Yes □ No			
3. Maintain leak detection inspection and repair reports for the following:				
a) documentation of leaks repaired w/in 24 hrs? or;	Yes No N/A			
b) documentation of parts ordered to repair leak and leak repaired w/in 2 days and parts installed w/in 5 days of receipt?	☐ Yes ☐ No     N/A			
4. Maintain calibration data? (for applicable direct reading instruments)	☐ Yes ☐ No    N/A			
5. Maintain exhaust duct monitoring data on perc concentrations?	☐ Yes ☐ No    N/A			
6. Maintain a startup/shutdown/malfunction plan?	⊠ Yes □ No			
7. Maintain deviation reports?	Yes No N/A			
a) Problem corrected?	Yes No N/A			
8. Maintain a compliance plan, if applicable?	Yes No N/A			

## PART VI: <u>LEAK DETECTION AND REPAIRS</u> – Rule 62-213.300 FAC

1. Does the responsible official conduct a weekly (for small sources, bi-weekly) leak

(check  $\square$  only one box for each question)

detection and repair inspection?				
2. Does the facility maintain a leak log?				
3. Does the responsible official check the following areas for leaks?  a) Hose connections, fittings,     couplings, and valves	Muck cookers  Stills  Exhaust dampers  Yes No N/A  Yes No N/A			
4. Which method(s) of detection (is/are) used by the responsible off  a) Visual examination (condensed solvent on exterior surfaces) b) Physical detection (airflow felt through gaskets) c) Odor (noticeable perc odor) d) Use of direct-reading instrumentation (FID/PID/calorimetric te) e) Halogen leak detector  **If using direct-reading instrumentation, is the equipment: 1) Capable of detecting perc vapor concentrations in a range of the calculation (2) Calibrated against a standard gas prior to and after each use (1) 3) Inspected for leaks and obvious signs of wear on a weekly ba 4) Kept in a clean and secure area when not in use?  5) Verified for accuracy by use of duplicate samples (calorimetric terms)	a) \( \begin{align*} &			
Danielle D. Owens	January 14, 2010			
Inspector's Name (Please Print)	Date of Inspection			
Inspector's Signature	Approximate Date of Next Inspection			
<b>COMMENTS:</b> On January 14, 2010, Ms, Danielle Owens, Mr, John Harris, and Mr. Michael Eckoff of FDEP visited the subject facility to perform a level 2 compliance inspection. Contact was made with Mr. Sam Singh, owner. Mr. Singh accompanied Ms. Owens, Mr. Harris, and Mr. Eckoff on a walk through inspection of the facility. The facility was found to be in compliance with each program inspected.				

Parts IV A and B are not applicable to this facility.