OWERTAL WOTECTION
San Martin
FLORIDA

PERCHLOROETHYLENE DRY CLEANERS



## COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/DISCOVER	Y (CI)
	ARRIVE: <u>10:41 AM</u>	DEPART: <u>11:15 AM</u>
FACILITY NAME: BEEZEE CLEANERSFACILITY LOCATION:10760 SW 24th STMIAMI33165-2493		
OWNER/AUTHORIZED REPRESENTATIVE: GERAL Email: CONTACT NAME: GERARD COOMBS Email: ENTITLEMENT PERIOD: 5/17/2010 / 5/17/2015 (effective date) (end date)	Mobile:	(305)222-2214 (305)222-2214
PART I: INSPECTION COMPLIANCE STATUS       (chec         IN COMPLIANCE       IN MINOR Non-COMPLIANCE		Γ Non-COMPLIANCE
PART II:FACILITY CLASSIFICATION (check $\square$ only one box in A)- Rule 62-21A. 1.Existing small area source dry-to-dry only, x < 140 gal/yr transfer only, x < 200 gal/yr both types, x < 140 gal/yr (constructed before 12/9/91)-3.Existing large area source dry-to-dry only, 140 $\le$ x $\le$ 2,100 gal/yr transfer only, 200 $\le$ x $\le$ 1,800 gal/yr both types, 140 $\le$ x $\le$ 1,800 gal/yr both types, 140 $\le$ x $\le$ 1,800 gal/yr (constructed before 12/9/91)5.Ineligible for General Permit d rop store/out of business/petroleum / facility exceeds above limits	<ul> <li>13.300 FAC</li> <li>2. New small area source dry-to-dry only, x &lt; 140 transfer only, x &lt; 200 gal both types, x &lt; 140 gal/y. (constructed on or after 1</li> <li>4. New large area source dry-to-dry only, 140 ≤ transfer only, 200 ≤ x ≤ both types, 140 ≤ x ≤ (constructed on or after 1</li> </ul>	l/yr r 12/9/91) ⊥ x ≤ 2,100 gal/yr ≤ 1,800 gal/yr 1,800 gal/yr

**B**. The sum of the volume of all perchloroethylene (perc) purchases made in each of the previous 12 months by this dry cleaning facility was 90.00 gallons.

PART III: <u>GENERAL CONTROL REQUIREMENTS</u> – Rule 62-213.300 FAC			check ☑ x for each q	only one juestion)
1. Is all perc, and wastes containing perc, in tightly sealed & impervious containers?	- 🛛	Yes	🗌 No	N/A
2. Are all perc. containers leak free ?	🖂	Yes	🗌 No	N/A
3. Are all machine doors kept closed and secured except during loading/unloading?		Yes	🗌 No	
<ol> <li>Are cartridge filters d rained in their housing or in sealed containers for at least 24 hours prior to disposal?</li> </ol>	🛛	Yes	🗌 No	□ N/A
5. Has each dry cleaning system installed after December 21, 2005 at an area source, routed the air-PCE gas-vapor stream contained within each dry cleaning machine through a refrigerated condenser and passed the air-PCE gas-vapor stream from inside the dry cleaning machine drum through a non-vented carbon adsorber or equivalent control device immediately before the door of the dry cleaning machine is opened? The carbon adsorber must be desorbed in accordance with manufacturer's instructions.		Vas	□ No	N/A
<ul> <li>6. Is solvent-to-carbon ratios and steam pressure for carbon adsorber beds maintain according to the manufacturer's specifications?</li> </ul>		Yes Yes	No	N/A
PART IV: <u>PROCESS VENT CONTROLS</u> – Rule 62-213.300 FAC (Refer to Part II-A.14. Classification: page <u>1</u> of <u>4</u> , this form)				
	n	1 / D		
1. If the f acility classification is an <b>existing small area source</b> , no controls are required.	Proce	ed to P	art V.	
2. If the facility classification is a <b><u>new small area source</u></b> , the machine should be equipp condenser. <b>Complete section A. below.</b>	ed with	a refrig	gerated	
3. If the fa cility classification is an <b>existing large area source</b> , the machine should be experimented condenser or a carbon adsorber . <b>Complete both sections A and B below.</b> <i>must have been installed prior to September 22, 1993</i>				
4. If the facility classification is a <u>new large area source</u> , the machine should be equipp condenser. Complete both sections A and B below.	ed with	a refrig	gerated	
A. Has the responsible official of all <u>existing large area &amp; new sources</u> :			check ⊠ x for each q	only one Juestion)
1. Equipped all machines with the appropriate vent controls?	🖂	Yes	🗌 No	
2. Equipped dry-to-dry machines with a closed-loop vapor venting system?	🖂	Yes	🗌 No	N/A
3. Equipped the condenser with a diverter value so airflow will be directed away from the condenser upon opening the door?	🛛	Yes	🗌 No	N/A
4. Measured and recorded the temperature of the outlet exhaust stream of a refrigerated condenser on a weekly basis?	🛛	Yes	🗌 No	N/A
5. Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded 45° F?	🗆	Yes	🗌 No	N/A
6. Conducted all temperature monitoring after an appropriate cool-down period and				

6. Conducted all temperature monitoring after an appropriate cool-down period and				
after verifying that the coolant had been completely charged?	$\boxtimes$	Yes	🗌 No	

PA	ART IV: PROCESS VENT CONTROLS – Rule 62-213.300 FAC (continued)			
<b>B.</b> 1.	<b>For all existing large or new large area sources:</b> Is the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines measured and recorded on a weekly basis?	Yes	🗌 No	
2.	Is the washer exhaus t temperature at the condenser inlet and outlet measured and recorded weekly? a) Is the temperature differential equal to, or greater than 20° F?	Yes Yes	D No	□ N/A □ N/A
3.	Is the perc concentration in the exhaust stream inlet and outlet measured weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped exclusively with a carbon adsorber?	Yes	🗌 No	N/A
	a) Is the perc concentration equal to, or less than 100 ppm?	Yes	🗌 No	N/A
4.	Is the sampling port on the carbon adsorber exhaust for measuring perc concentrations at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet?	Yes	🗌 No	□ N/A
5.	Are transfer machines equipped (dryers, reclaimers, and washers) with individual condenser coils?	Yes	🗌 No	N/A
6.	Is airflow routed to the carbon adsorber (if used) at all times?	Yes	🗌 No	N/A

PA	ART V: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-213.300(3) FAC		```	check 🗹 ox for each c	only one question)
1.	Are receipts maintained for all perc purchased?	$\boxtimes$	Yes	🗌 No	
2.	Are rolling monthly total s of yearly perc consumption maintained ?	$\boxtimes$	Yes	🗌 No	
3.	Are leak detection inspection and repair reports maintained for the following:				
	a) Of any leaks repaired w/in 24 hrs? or;		Yes	🗌 No	N/A
	b) Of any parts ordered to repair leak and leak repaired w/in 2 days and parts installed w/in 5 days of receipt?		Yes	🗌 No	N/A
4.	Is calibration data maintained for applicable direct reading instruments?		Yes	🗌 No	N/A
5.	Is exhaust duct monitoring data on perc concentrations maintained?		Yes	🗌 No	N/A
6.	Is a startup/shutdown/malfunction plan maintained for each machine?	$\boxtimes$	Yes	🗌 No	
7.	Are deviation reports maintained?		Yes	🗌 No	N/A
	a) Problem corrected?		Yes	🗌 No	N/A
8.	Is a compliance plan maintained , if applicable?		Yes	🗌 No	N/A

PA	ART VI: LEAK DETECTION AND REPAIRS – Rule 62-213.300 FAC	(check 🗹	only one
1.	What type of leak detection equipment is used to detect leaks?	box for eac	•
	Halogenated hydrocarbon detector PCE gas analyzer None used		
2.	Is the halogenated hydrocarbon detector or PCE gas analyzer operated according to		
	the manufacturer's instructions (manual was available and RO could demonstrate		
	<i>procedure)</i> ? 🖂	Yes 🗌 No	
3.	For major sources is the halogenated hydrocarbon detector or PCE gas analyzer		
	operated according to EPA Method 21 ?	Yes 🗌 No	N/A
4.	Is the vapor leak inspection conducted by placing the probe inlet at the surface of		
	each component interface where leakage could occur and moving it slowly along		
	the interface periphery? 🖂	Yes 🗌 No	
5.	Is the PCE gas analyzer a flame ionization detector, photo ionization detector, or		
	infrared analyzer capable of detecting vapor concentrations of PCE of 25 parts per		
	million by volume (based on documented specifications) ?	Yes 🗌 No	N/A
6.	Is the halogenated hydrocarbon detector capable of detecting vapor concentrations		
	of PCE of 25 parts per million by volume (based on documented specifications) and		
	indicating a concentration of 25 parts per million by volume or greater by emitting		
	an audible or visual signal that varies as the concentration changes? $\square$	Yes 🗌 No	N/A
7.	Are the following dry cleaning system components inspected weekly for perceptible leaks (sight, sn	mell or touch) wh	nile the
	system is in operation (§63.322(k))?		
	(Inspection with a halogenated hydrocarbon detector or PCE gas analyzer also fulfills the requirement for insp	pection of percept	ible leaks)
	b) Door gaskets and seating 🖾 Yes 🔲 No 🗍 N/A h) Stills 🖾	=	<ul> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> </ul>
8.	Are the following dry cleaning system components inspected monthly for vapor leaks using a halog	genated hydrocar	bon detector
	or PCE gas analyzer while the system is in operation? (Any inspection conducted according to this parage	graph shall satisfy	the
	requirements to conduct an inspection for perceptible leaks under $63.322(k)$ or $(l)$		
	b) Door gaskets and seating       Yes       No       N/A       h) Stills         c) Filter gaskets and seating       Yes       No       N/A       i) Exhaust dampers	Yes No Yes No Yes No Yes No Yes No Yes No	<ul> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> </ul>

PART VI: LEAK DETECTION AND REPAIRS – Rule 62-213.300 FAC (continued)						
<ul> <li>9. What evidence suggests that leak checks are performed as r</li> <li>☑ Leak log documentation □ RO Assurances □</li> <li>Explain other :</li> </ul>	required? On-site observation  other					
FRANK DELGADO	2/9/2012					
	2/9/2012					
Inspector's Name (Please Print)	Date of Inspection					
	2/2013					
Inspector's Signature	Approximate Date of Next Inspection					
BECAUSE THE STILL DOOR GASKET BROKE AND HAD	AACHINE. THE MACHINE WAS SERVICED IN THE MORNING D TO BE REPLACED. SOME PERC WAS SPILLED INTO THE MANAGER SONIA TRUJILLO CLEANED THE SPILLED AND K RECEIPT WAS PROVIDED.					

**REVIEWED** By Ray Gordon at 11:54 am, Feb 14, 2012



BILL ▶

## STEINER ATLANTIC CORP.

P.O. BOX 380578 • MIAMI, FLORIDA 33238-0578

DADE: (305) 754-4551 • TOLL FREE: 1-800-333-8883 • FAX: (305) 754-7533 www.steineratlantic.com OFFICE AND SHOWROOM 290 N.E. 68th STREET MIAMI, FLORIDA 33138-552

FOB: ORIGIN

TO SHIP

MARIO MEZA 9073 N.W. SEND TEPRACE MIAMI FL 33178

a solution and the solution of a second solution

MARIO MEZA 9873 N.W. S2ND TERPACE MIAMI FL 33:78

Ber- Zer.

INVOICE NO.	DATE	ORDER NO.	DATE	CUSTOMER NO.	CUSTOMER P.O. NO.	1.1	TERMS	SALESMAN
742543	82/09/12	751377	02/09/12	6001		COD	TERMS	25
						UPS		······································

STOCK NO.	DESCRIPTION	<b>I</b>	U/M	QUANTITY	UNIT PRICE	AMOUNT
ARE SDGASET	STILL DOOR GASKET	FOR CHC40/	:A		37.50	37 55
	Subtotal Trade Discount Sales Tax Total Due					)で、500 5、6006 2、605 34、149
		, n, ♥ *				
ALL GOODS SOLD ( JE APPRECIATE Y	RE F.O.B. ORIGIN. Dur Business!					
		RTS II		voic		

· · · · · · · · · · · · ·