WHENTIAL PROTECTION	
Same Man	
FLORIDA	

PERCHLOROETHYLENE DRY CLEANERS



## **COMPLIANCE INSPECTION CHECKLIST**

	NT/DISCOVERY (CI)
AIRS ID#: 0210083 DATE: <u>12/02/2010</u> ARRIVE: <u>12</u> :	<u>:35 P.M.</u> DEPART: <u>1:40 P.M.</u>
FACILITY NAME: DRY CLEAN & MORE         FACILITY LOCATION:       994 N BARFIELD DR #11         MARCO ISLAND       34145-2363	
OWNER/AUTHORIZED REPRESENTATIVE: MUSTAFA ASLAN Email: DryCleanAndMore@yahoo.com CONTACT NAME: MUSTAFA ASLAN Email: ENTITLEMENT PERIOD: 12/31/2009 / 12/31/2014 (effective date) (end date)	PHONE: (239)642-7222 Mobile: PHONE: (239)642-7222 Mobile:
PART I: INSPECTION COMPLIANCE STATUS (check I only one         IN COMPLIANCE         IN COMPLIANCE	box) SIGNIFICANT Non-COMPLIANCE
dry-to-dry only, x < 140 gal/yrdry-to-drytransfer only, x < 200 gal/yr	$\frac{\text{ll area source}}{\text{y only, } x < 140 \text{ gal/yr}}$ $\frac{\text{only, } x < 200 \text{ gal/yr}}{\text{only, } x < 200 \text{ gal/yr}}$ $\frac{\text{ext. } x < 140 \text{ gal/yr}}{\text{st. } x < 140 \text{ gal/yr}}$ $\frac{\text{ge area source}}{\text{ge area source}} \qquad $

**B**. The sum of the volume of all perchloroethylene (perc) purchases made in each of the previous 12 months by this dry cleaning facility was 195.00 gallons.

PART III: <u>GENERAL CONTROL REQUIREMENTS</u> – Rule 62-213.300 FAC			(check 🗹 ox for each d	only one question)
1. Is all perc, and wastes containing perc, in tightly sealed & impervious containers?	$\boxtimes$	Yes	🗌 No	N/A
2. Are all perc. containers leak free ?	$\boxtimes$	Yes	🗌 No	N/A
3. Are all machine doors kept closed and secured except during loading/unloading?	$\boxtimes$	Yes	🗌 No	
<ol> <li>Are cartridge filters d rained in their housing or in sealed containers for at least 24 hours prior to disposal?</li> </ol>		Yes	🗌 No	N/A
5. Has each dry cleaning system installed after December 21, 2005 at an area source, routed the air-PCE gas-vapor stream contained within each dry cleaning machine through a refrigerated condenser and passed the air-PCE gas-vapor stream from inside the dry cleaning machine drum through a non-vented carbon adsorber or equivalent control device immediately before the door of the dry cleaning machine is opened? The carbon adsorber must be desorbed in accordance with manufacturer's instructions		Yes	No	N/A
6. Is solvent-to-carbon ratios and steam pressure for carbon adsorber beds maintain according to the manufacturer's specifications?		Yes	□ No	N/A
r				

PA	RT IV: <u>PROCESS VENT CONTROLS</u> – Rule 62-213.300 FAC							
(Re	efer to Part II-A.14. Classification: page $\underline{1}$ of $\underline{4}$ , this form)							
	1. If the f acility classification is an existing small area source, no controls are required. Proceed to Part V.							
	2. If the facility classification is a <b>new small area source</b> , the machine should be equipped with a refrigerated condenser. <b>Complete section A. below.</b>							
	3. If the fa cility classification is an <b>existing large area source</b> , the machine should be equip refrigerated condenser or a carbon adsorber . <b>Complete both sections A and B below.</b> <i>Camust have been installed prior to September 22, 1993</i>	-	with ei adsort					
	4. If the facility classification is a <u>new large area source</u> , the machine should be equipped with a refrigerated condenser. Complete both sections A and B below.							
A.	Has the responsible official of all existing large area & new sources:			check ☑ k for each	only one question)			
1.	Equipped all machines with the appropriate vent controls?	$\boxtimes$	Yes	🗌 No				
2.	Equipped dry-to-dry machines with a closed-loop vapor venting system?	$\boxtimes$	Yes	🗌 No	N/A			
	Equipped the condenser with a diverter valve so airflow will be directed away from the condenser upon opening the door?	$\boxtimes$	Yes	🗌 No	N/A			
4.	Measured and recorded the temperature of the outlet exhaust stream of a				_			

Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded $45^{\circ}$ F?		Yes	No	$\boxtimes$	N/A
Conducted all temperature monitoring after an appropriate cool-down period and after verifying that the coolant had been completely charged?	$\boxtimes$	Yes	No		

refrigerated condenser on a weekly basis? ----- Yes

N/A

No No

PA	ART IV: PROCESS VENT CONTROLS – Rule 62-213.300 FAC (continued)			
<b>B.</b> 1.	<b>For all existing large or new large area sources:</b> Is the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines measured and recorded on a weekly basis?	Yes	🛛 No	
2.	Is the washer exhaus t temperature at the condenser inlet and outlet measured and recorded weekly?	 Yes Yes	□ No	N/A N/A
3.	Is the perc concentration in the exhaust stream inlet and outlet measured weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped exclusively with a carbon adsorber?	Yes	□ No	N/A
	a) Is the perc concentration equal to, or less than 100 ppm?	Yes	🗌 No	N/A
4.	Is the sampling port on the carbon adsorber exhaust for measuring perc concentrations at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet?	Yes	🗌 No	N/A
5.	Are transfer machines equipped (dryers, reclaimers, and washers) with individual condenser coils?	Yes	🗌 No	N/A
6.	Is airflow routed to the carbon adsorber (if used) at all times?	Yes	🗌 No	N/A

PA	ART V: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-213.300(3) FAC		`	check ☑ x for each c	only one [uestion)
1.	Are receipts maintained for all perc purchased?	$\boxtimes$	Yes	🗌 No	
2.	Are rolling monthly total s of yearly perc consumption maintained ?	$\boxtimes$	Yes	🗌 No	
3.	Are leak detection inspection and repair reports maintained for the following:				
	a) Of any leaks repaired w/in 24 hrs? or;		Yes	🗌 No	N/A
	b) Of any parts ordered to repair leak and leak repaired w/in 2 days and parts installed w/in 5 days of receipt?		Yes	🗌 No	N/A
4.	Is calibration data maintained for applicable direct reading instruments?		Yes	🗌 No	N/A
5.	Is exhaust duct monitoring data on perc concentrations maintained?		Yes	🗌 No	N/A
6.	Is a startup/shutdown/malfunction plan maintained for each machine?	$\boxtimes$	Yes	🗌 No	
7.	Are deviation reports maintained?		Yes	🗌 No	N/A
	a) Problem corrected?		Yes	🗌 No	N/A
8.	Is a compliance plan maintained , if applicable?		Yes	🗌 No	N/A

PA	ART VI: LEAK DETECTION AND REPAIRS – Rule 62-213.300 FAC	(check 🗹	only one
1.	What type of leak detection equipment is used to detect leaks?	box for each	•
	Halogenated hydrocarbon detector PCE gas analyzer None used		
2.	Is the halogenated hydrocarbon detector or PCE gas analyzer operated according to		
	the manufacturer's instructions (manual was available and RO could demonstrate		
	procedure) ? 🖂	Yes 🗌 No	
3.	For major sources is the halogenated hydrocarbon detector or PCE gas analyzer		
	operated according to EPA Method 21 ?	Yes 🗌 No	N/A
4.	Is the vapor leak inspection conducted by placing the probe inlet at the surface of		
	each component interface where leakage could occur and moving it slowly along		
	the interface periphery?	Yes 🗌 No	
5.	Is the PCE gas analyzer a flame ionization detector, photo ionization detector, or		
	infrared analyzer capable of detecting vapor concentrations of PCE of 25 parts per		
	million by volume (based on documented specifications) ?	Yes 🗌 No	N/A
6.	Is the halogenated hydrocarbon detector capable of detecting vapor concentrations		
	of PCE of 25 parts per million by volume (based on documented specifications) and		
	indicating a concentration of 25 parts per million by volume or greater by emitting		
	an audible or visual signal that varies as the concentration changes? $\square$	Yes 🗌 No	N/A
7.	Are the following dry cleaning system components inspected weekly for perceptible leaks (sight, sn	nell or touch) whi	le the
	system is in operation (§63.322(k))?		
	(Inspection with a halogenated hydrocarbon detector or PCE gas analyzer also fulfills the requirement for insp	pection of perceptil	ole leaks)
	b) Door gaskets and seating 🛛 Yes 🗌 No 🗍 N/A h) Stills 🖾 Y		<ul> <li>□ N/A</li> <li>□ N/A</li> <li>□ N/A</li> <li>□ N/A</li> <li>□ N/A</li> <li>□ N/A</li> </ul>
8.	Are the following dry cleaning system components inspected monthly for vapor leaks using a halog	genated hydrocarb	on detector
	or PCE gas analyzer while the system is in operation? (Any inspection conducted according to this parage	graph shall satisfy t	he
	requirements to conduct an inspection for perceptible leaks under §63.322(k) or (l))		
	b) Door gaskets and seating       Yes       No       N/A       h) Stills       X         c) Filter gaskets and seating       Yes       No       N/A       i) Exhaust dampers       X	Yes No Yes No Yes No Yes No Yes No Yes No	□ N/A □ N/A □ N/A □ N/A □ N/A

PART VI: LEAK DETECTION AND REPAIRS – Rule 62-2	213.300 FAC (continued)	
<ul> <li>9. What evidence suggests that leak checks are performed as red</li> <li>☑ Leak log documentation □ RO Assurances □</li> <li>Explain other :</li> </ul>	quired? On-site observation  other	
ROBERT J. STEWART	12/02/2010	
Inspector's Name (Please Print)	Date of Inspection	
Robert J. Stewart	12/2011	
Inspector's Signature	Approximate Date of Next Inspection	
<b>COMMENTS:</b> The outlet exhaust stream temperature of the	refrigerated condensor was supposedly being taken but was not	

**COMMENTS:** The outlet exhaust stream temperature of the refrigerated condensor was supposedly being taken but was not being recorded in the Phenix Solvent calendar for 2009 or 2010 in use at the facility. Owner stated that since the temperature was below 45 degrees F, he assumed that he did not have to record the temperature in the calendar, although a column for this reading was available in the calendar's annotation log. The machine was in operation at the time of the inspection and the temperature of the refrigerated condensor was observed to be below 45 degrees F (read 42 degrees F) at the end of the cooling cycle. Owner was also given a copy of the Department's SBEAP Dry Cleaning Calendar for next year 2011.