

## **SURFACE COATING OPERATIONS**



## COMPLIANCE INSPECTION CHECKLIST

	COMPLAINT/DISCOVERY (CI)		
RE-INSPECTION (FUI)	ARMS COMPLAINT NO:		
AIRS ID#: 0112461 DATE: <u>06/22/2006</u>	ARRIVE: <u>9:00 AM</u> DEPART: <u>10:00 AM</u>		
FACILITY NAME: HARBOUR TOWNE MARINA			
FACILITY LOCATION: 801 NE 3RD AVENU	JE		
DANIA 33004			
RESPONSIBLE OFFICIAL: GARY GROENEWOL	PHONE: (954)926-0300		
CONTACT NAME: Brad St. Coeur PHONE: (260)172-1			
REMITTANCE YEAR: ENTIT	<b>FLEMENT PERIOD:</b> 8/27/2004 / 8/27/2009 (end date)		
	(enective date) (end date)		
DADT II. DECODD// FEDING DECUIDEMENTS   Dulo 62 210 200 F A C			
PART II: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))			
1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)  ☐ Yes ☐ No  2. Does the owner/operator of the facility maintain records to document the VOC content of the coatings and the quantity of the coatings used?————————————————————————————————————			
DADE HE CONTROL ODED ATTIVOTAL NUMBER DECLUDENTENTS. D. L. CA 410 400 E. L. C.			
PART III: <u>CONTROL/OPERATING/MAINTANANCE REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))			
<ul><li>emission limiting standard of Chapter 62-296.</li><li>Does the facility cause, suffer, allow or permit</li></ul>	the discharge of air pollutants which cause or contribute to	⊠No ⊠No	

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued) (check ☑ appropriate box(es))		
cycles?2) recycling cleaning solvents?	reducing VOC emissions by:  ective application with a minimum of overspray?  e coating?  terborne, ultra-violet cured, or powder coatings)?  nt spillage?  Yes No  Yes No  Yes No	
PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300, F.A.C.  A. New or Modified Process Equipment  1. Since the last inspection has there been  a) installation of any new process equipment?		
Elizabeth F. Susky	06/23/2006	
Inspector's Name (Please Print)	Date of Inspection	
	06/23/2007	
Inspector's Signature	Approximate Date of Next Inspection	
The facility is a marina with a service pad where boat work (bo	22/2006, AQD staff observed activities at Harbour Towne Marina.  ottom painting and sanding) is conducted. Mr. Brad St. Coeur (yard observed workers on the service pad adhering to the BMP by	

**COMMENTS:** In a compliance inspection conducted on 06/22/2006, AQD staff observed activities at Harbour Towne Marina. The facility is a marina with a service pad where boat work (bottom painting and sanding) is conducted. Mr. Brad St. Coeur (yard manager) accompanied staff during the inspection. AQD staff observed workers on the service pad adhering to the BMP by utilizing tarping around boats being worked on and placing geo-textile (highly absorpent material used to collect paint shavings etc.). Mr. St. Coeur submitted paint records and VOC logs to AQD staff during the inspection. The facility is operating under their permit thresholds (9.14 VOC/day).

At the conclusion of the inspection AQD staff and Mr. St. Coeur discussed conducting an on-site training of the Marina BMP in late August, early September 2006.