

Inspection list for Crematories

Facility Name:

Hernando Co. Animal Services

Facility ID No:

0530365

Joseph Rued

12/22/09

Crematory Unit Number

001

Crematory Unit Information:	
Emission Unit No.	001 Model C700P S.N. P/310/0022/00
Specifications:	220-Volts 3 phase - Combustion Fan } Propane 120 Volts - Control circuit } 11 inches WC
Thermocouple Location:	Diagram/Description: See ATTACHED Diagram
Afterburner Location:	Diagram/Description: Right Side See ATTACHED Diagram

Inspection list for Crematories

Facility Name:

Hernando Co. Animal Co.

Facility ID No:

0530 365

Chart and Digital Logic Controller:	
Chart Make & Model:	PARTLOW MRC 5000 - model # 51000031 SN: 971081-0001
Digital Logic Controller Make & Model:	PARTLOW 1160
Chart Specifications:	115 VAC: 5.0 A Resistive 230 VAC: 2.5A Resistive
Digital Logic Controller Specifications:	Not Available
Check for agreement between Chart & Digital Logic Controller	Agreement: YES Agreement: NO If NO, provide comments: n/a
Chart Calibration:	Date of Last Calibration: Calibration Performed by: n/a Results of Calibration:
Digital Logic Controller Calibration:	Date of Last Calibration: Calibration Performed by: n/a Results of Calibration:
Digital Logic Controller Bias	Details of Bias: n/a Chart Recorder reading at Bias determination:

Inspection list for Crematories

Facility Name:

Hernando Co. Animal Co.

Facility ID No:

0530 365

	<p align="center">Comparison: n/A</p> <p>If bias is found, request information of previous calibrations to determine when it was put in and by whom.</p> <p>Obtain copies of the recorder charts, during and after the check.</p>
Chart Recorder	<p>Scan in 2 years of temperature charts</p> <p align="center">n/A</p>
Unit Maintenance	
Date of Last Service	<p align="center">n/A</p>
Name of Company Servicing Unit:	<p>Name/Address/Phone #/email and/or fax #</p> <p align="center">n/A</p>
Description of repairs/adjustments:	<p align="center">n/A</p>
Maintenance Log:	<p align="center">YES NO n/A</p>
Maintained Routinely:	<p align="center">YES NO</p> <p>If NO, provide comments. n/A</p>

Inspection list for Crematories

Facility Name:

Hernando County Au. Co.

Facility ID No:

0530 365

					N/A
Repair Records 62-296.401(5&6)(e), FAC:	2 years of records on-site:	YES	NO		
	If NO, provide comments.				N/A
62-210.310 (3), FAC - General Conditions:					
Permit	Issuance Date:	7/17/2008			
	Expiration Date:	7/17/2013			
Owner:	Same as permit:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		
	If NO, provide current owner information:				
62-296.401(5&6), FAC - Specific Conditions Human and Animal Crematories					
Visible Emissions					N/A
Particulate Matter Emissions					N/A
Carbon Monoxide (CO) Emissions					N/A

Inspection list for Crematories

Facility Name:

Hernando County An. Con.

Facility ID No:

0530365

Operating Temperatures	n/a
Allowed Material	n/a
Operating Procedures for start-up, shutdown and malfunction	n/a
Air-to-Fuel Ration	n/a

Retention Time Calculations and Thermocouple Location:

NOTE If the temperatures cannot be met at the point or beyond where 1.0 second gas residence time is obtained in the secondary chamber combustion zone, then both the closer thermocouple location and bias would compensate for it.

Hernando Co. Animal Services -

0530365

12/22/09

[Signature]

Thermocouple on ^{Left} ~~Right~~ side


40 1/2 From Floor

19 1/2 From Floor

Thermocouple on Right side

32 1/2 From Near Floor

52 1/2 From Floor



2 1/2 " from charge door to front

8 3/8 " from wall/secondary chamber to front