

## $\frac{\textbf{REINFORCED}}{\textbf{OPERATIONS}} \frac{\textbf{RESIN}}{\textbf{OPERATIONS}}$



## COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVER RE-INSPECTION (FUI) ARMS COMPLAINT NO	· / <del>-</del>		
AIRS ID#: 0251153 DATE: <u>9/24/2012</u> ARRIVE: <u>10:55AM</u>	DEPART: <u>11:25AM</u>		
FACILITY NAME: DOLPHIN BOATS INC.			
FACILITY LOCATION: 24601 Packing House Road			
PRINCETON 33032-3821			
OWNER/AUTHORIZED REPRESENTATIVE: KARL ZIMMERMANN PHON Email: Mobile PHON Email: PHON Email: PHON Email: Mobile ENTITLEMENT PERIOD: 9/28/2008 / 9/28/2013 (effective date) (end date)	e: E:		
PART I: <u>INSPECTION</u> <u>COMPLIANCE</u> <u>STATUS</u> (check ✓ only one box)			
☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE			
PART II: CONTROL TECHNOLOGY/RECORDKEEPING REQUIREMENTS — (check ☑ appropriate box(es))  1. Does the facility operate any emissions units other than the polyester resin plasti and emissions units which are exempt from permitting pursuant to the criteria of 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under R (Rule 62-210.300(3)(c)5.a., F.A.C.)——————————————————————————————————	c products fabrication units  S paragraph Rule 62-4.040, F.A.C.?		

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
1. Does the owner or operator voluntarily encourage pollution prevention through such measures as training employees involved in product fabrication on methods of reducing evaporative losses by:  a) lessening the exposure of fresh resin surfaces to the air?		
PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300(4)(d)4., F.A.C.		
(check ☑ appropriate box(es))  A. New or Modified Process Equipment		
<ol> <li>Since the last inspection has there been</li> <li>a) installation of any new process equipment?</li> </ol>		
c) replacement of existing equipment substantially		
notification form and appropriate fee (Rule 62-4.050, F.A.C.) to the appropriate DEP or local program office?		
MARUFUL MALIK	9/24/2012	
Inspector's Name (Please Print)	Date of Inspection	
	9/2013	
Inspector's Signature	Approximate Date of Next Inspection	

**COMMENTS:** On September 24, 2012 I visited this facility to conduct the annual compliance inspection. On site I met Dixon Olan, the manager of the facility. This facility manufactured four (4) boats and three (3) in the last calender year. The total amount of styrene containing materials used in the last calender year was 4827 pounds. There was no objectionable odor detected inside or outside the facility.

REVIEWED

By Ray Gordon at 3:32 pm, Oct 25, 2012