

STATE OF FLORIDA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
SOUTHWEST DISTRICT

CONVERSATION RECORD

Date: 02/08/2012		Subject: Status of Plants at facility 1050372	
Time: Approx. 15:00 PM		Permit No. 1050372-004-AG	
RE: Scott Simpson, Plant Manager; e-mail: Scott.Simpson@hanson.biz		Telephone No. : Mobile: (863) 557-0091 Office: (863) 421-7422; Fax: (863) 421-1250	
Representing: Hanson Hardscape Products; 1980 Marley Dr., Haines City, FL 33844			
<input type="checkbox"/> Telephoned Me	<input checked="" type="checkbox"/> Was Called	<input type="checkbox"/> Scheduled Mtg.	<input type="checkbox"/> Unscheduled Mtg.
Other Individuals Involved in Conversation/Meeting:			
<p>I, Amaury Betancourt, called Mr. Scott Simpson, Plant Manager at Hanson Hardscape Products, Facility ID 1050372), at approximately 15:00 on 02/08/2012. The purpose of the phone call was to verify the status of Plant #2 and Plant #3 at the Hanson facility, which I inspected on 01/24/2012. The facility contains four plants, Plants 1-4. In total, the facility contains fourteen emission units. On 01/24/2012, Visible emissions (VE) tests were conducted by Bill Arlington of Arlington Environmental Services, Inc., on eight emission units, including all emission units of Plant 1 (EU001, EU002, EU003, and EU004), all emission units of Plant 4 (EU011, EU012, and EU013), and a paver tumbler with central dust collector (EU014).</p> <p>Plant #3 contains three emission units, which are EU008, EU009, and EU010. Plant #3 is listed as under construction in ARMS and has never been fully operational. On ARMS, EU010 was listed as part of Plant #2. I asked Mr. Simpson if this was correct, and he stated that it was not correct, and that EU010 is part of Plant #3, so I corrected this information on ARMS.</p> <p>Plant #2 contains three emission units, which are EU005, EU006, and EU007. Plant #2 is listed as active on ARMS. I informed Mr. Simpson to please speak with the environmental consultants for Hanson Hardscape Products to make sure that EU005, EU006, and EU007 are noted on the 2012 VE test report as being non-operational for the Hanson Hardscape Products facility. Mr. Simpson stated that he would speak with Mr. Charles Piwowarski, Area Environmental Manager, to tell him this information.</p> <p>####</p>			
Inspector: Amaury Betancourt		Signature: _____ Date: 02/09/2012	
		Title: Engineering Specialist I	