

## Florida Department of Environmental Protection Inspection Photo Log

<b>Facility Name:</b> Florida Rock Industries	<b>ID #:</b> 1170034
<b>Inspection Date:</b> 11/9/11	<b>Sky Conditions:</b> Partly Cloudy
<b>Persons Present:</b> Wanda Parker-Garvin (FDEP, photographer), Mike Crowe (Florida Rock, Plant Maintenance)	
<b>Digital camera used. Photo files saved at:</b> O:\COMPLIANCE-Central Files\Inspection Reports 2011-2012\Wanda's Inspections\Seminole\Florida Rock Industries 1170034	



EU001 – Cement and fly ash silos.



Stock pile of soil/asphalt located adjacent to the facility.