STANDARDA PROTECTION
and the second
a FLORIDA

SURFACE COATING OPERATIONS



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE:	ANNUAL (INS1, INS2)	COMPLAINT/E ARMS COMPL	DISCOVERY (CI)			
AIRS ID#: 0112681 DA' FACILITY NAME: VE	TE: <u>2/16/2012</u> RTICAL YACHT CLUB BOA	ARRIVE: <u>1300</u> TING CENTER	DEPART: <u>1415</u>			
FACILITY LOCATION OWNER/AUTHORIZE Email: rmatalon@ilo	5000 STATE ROAD 84 FORT LAUDERDALE D REPRESENTATIVE: RIC vemymarina.com	4 2 33312-4815	PHONE: (954)321-1010 Mobile: (954)249-7020			
CONTACT NAME: R Email: rmatalon@ilo ENTITLEMENT PERIC	vemymarina.com		PHONE: (954)321-1010 Mobile: (954)249-7020			
PART I: INSPECTION COMPLIANCE STATUS (check I only one box) IN COMPLIANCE MINOR Non-COMPLIANCE SIGNIFICANT Non-COMPLIANCE						
PART II: RECORDKEEPING REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es)) 1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.) □Yes ☑ No 2. Does the owner/operator of the facility maintain records to document the VOC content of the coatings and the quantity of the coatings used?						
 (check appropriate 1. Is/Are the surface emission limiting 2. Does the facility 	box(es)) e coating operation(s) subject to g standard of Chapter 62-296.50 cause, suffer, allow or permit th	o a VOC Reasonably A 00, F.A.C.? (Rule 62-2 he discharge of air poll	<u>Available Control Technology</u> (RAC 10.300(3)(c)4.b., F.A.C.) lutants which cause or contribute to	□Yes ⊠No		

PART III: <u>CONTROL/OPERATING/MAINTENANCE REQUIREMENTS</u> – Rule 62-210.300, F.A.C. – (continued)

(check ☑ appropriate box(es))

3.	Does the owner/operator encourage pollution prevention through such measures as training employees
	involved in surface coating operations on methods of reducing VOC emissions by:

a)	maintaining spray coating equipment to ensure effective application with a minimum of overspray?	Xes 🗌 No
b)	monitoring the coating thickness to avoid excessive coating?	Xes 🗌 No

c)	considering the use of low-VOC coatings (e.g., waterborne, ultra-violet cured, or powder coatings)?	Yes

	6	U (0	,	Ý 1	0 /
d)	implementing inventory co	ontrol practices to	prevent	spillage?		

e) implementing management practices to reduce VOC emissions during cleanup by:

1	0	\mathcal{U}	1		
1.	spraying lig	ht colo	red coati	tings before dark colored coatings to reduce the number of cleaning	
	cycles?				Y
2)	recycling cl	eaning	solvents	ts?	Y

2) recycling cleaning solvents?----- 3) using water based cleaners?----- Yes No Yes No

PART IV: <u>SPECIAL CONDITIONS AND PROCEDURES</u> – Rule 62-210.300, F.A.C. A. <u>New or Modified Process Equipment</u>		
1. Since the last inspection has there been		
a) installation of any new process equipment?	Yes	No
· / ··································	Yes	No
c) replacement of existing equipment substantially different than that noted on the most		
recent notification form?	Yes	⊠No
d) If you answered \underline{YES} to any of the above, did the owner submit a new and complete		
notification form and appropriate fee (Rule 62-4.050, F.A.C.) to the appropriate DEP or		
local program office?	Yes	No

Elizabeth F.Susky

Inspector's Name (Please Print)

2/16/2012

Date of Inspection

2/16/2013

Inspector's Signature

Approximate Date of Next Inspection

COMMENTS: In a compliance inspection conducted on 2/16/2012, AQD staff (E.Susky) observed operations at Marina Road Boat Yard (Vertical Yacht Club Boating Center). The facility is a boat yard with offices, boat yard/bottom work area, on-water dockage, pull-out area, and haz-mat storage area. Mr. Richard Matalon (Boatyard Manger) accompanied staff on the inspection. Representatives from DEP and City of Fort Lauderdale were on-site investigating a complaint regarding alleged painting on the water. However, no evidence of that painting was observed.

The facility conducts bottom painting on small boats and places tarps below each vessel during work. However, their housekeeping can be improved. This observation was shared with Mr. Matalon. Mr. Matalon is submitting VOC records to the department and emailed staff discussing the submittal.

No

No

No

es

Yes