

## **SURFACE COATING OPERATIONS**



## COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE:	ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/D ARMS COMPLA		Ϋ́ (CI)		
AIRS ID#: 0112681 DATE: 03/4/2014 ARRIVE: 1400  FACILITY NAME: VERTICAL YACHT CLUB BOATING CENTER				DEPART: <u>1530</u>		
FACILITY LOCATION	N: 3000 STATE ROAD 84  FORT LAUDERDALE  CD REPRESENTATIVE: RICIO  Devemymarina.com	33312-4815	Mobile:	(954)321-1010 (954)249-7020 (954)321-1010		
Email: rmatalon@ilo ENTITLEMENT PERIO	ovemymarina.com		Mobile:	(954)249-7020		
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box)  ☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE						
PART II: RECORDKEEPING REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))  1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.) ☐ Yes ☐ No  2. Does the owner/operator of the facility maintain records to document the VOC content of the coatings and the quantity of the coatings used?————————————————————————————————————						
PART III: CONTROL/OPERATING/MAINTANANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))  1. Is/Are the surface coating operation(s) subject to a VOC Reasonably Available Control Technology (RACT) emission limiting standard of Chapter 62-296.500, F.A.C.? (Rule 62-210.300(3)(c)4.b., F.A.C.)——————————————————————————————————						

PART III: CONTROL/OPERATING/MAINTENANCE F (check ☑ appropriate box(es))	REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued)				
cycles?2) recycling cleaning solvents?	reducing VOC emissions by:  fective application with a minimum of overspray?  ve coating?  aterborne, ultra-violet cured, or powder coatings)?  Tyes No  ent spillage?				
PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300, F.A.C.  A. New or Modified Process Equipment  1. Since the last inspection has there been  a) installation of any new process equipment?————————————————————————————————————					
Elizabeth F. Susky	03/14/2014				
Inspector's Name (Please Print)	Date of Inspection				
	03/14/2014				
Inspector's Signature	Approximate Date of Next Inspection				
<b>COMMENTS:</b> In a compliance inspection conducted on 03/04/2014. AOD staff (E. Susky) observed operations at Vertical Yacht					

**COMMENTS:** In a compliance inspection conducted on 03/04/2014, AQD staff (E. Susky) observed operations at Vertical Yacht Club Boating Center. Mr. Richard Matalon (manager) accompanied staff on the inspection. Houskeeping is fair, but could use some improvement. AQD staff suggested this to Mr. Matalon. He agreed and stated that they have now hired staff dedicated to just maintaining housekeeping of the yard. This facility is a a working boat yard that conducts bottom painting. Mr. Matalon emailed the VOC usage and the facility is well below their permit threshold.