

## **SURFACE COATING OPERATIONS**



## COMPLIANCE INSPECTION CHECKLIST

<b>INSPECTION TYPE:</b> ANNUAL (INS1, INS2) COMPLAINT/D	ISCOVERY (CI)	
RE-INSPECTION (FUI) ARMS COMPLA	AINT NO:	
AIRS ID#: 0550052 DATE: <u>04/17/2009</u> ARRIVE: <u>14:15</u>	DEPART: <u>15:04</u>	
FACILITY NAME: A-1 Machinery		
FACILITY LOCATION: 2400 U.S. Hwy 27, South		
AVON PARK 33825		
OWNER/AUTHORIZED REPRESENTATIVE: JULIO LARA PHONE: (863)453-7900		
CONTACT NAME: Julio Lara	<b>PHONE:</b> (863)453-7900	
ENTITLEMENT PERIOD: 4/9/2007 / 4/9/2012 (effective date) (end date)		
(enecure dute) (end dute)		
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box)		
☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE		
PART II: RECORDKEEPING REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)		
PART III: CONTROL/OPERATING/MAINTANANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
<ol> <li>Is/Are the surface coating operation(s) subject to a VOC Reasonably Available Control Technology (RACT) emission limiting standard of Chapter 62-296.500, F.A.C.? (Rule 62-210.300(3)(c)4.b., F.A.C.)</li></ol>		

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued) (check ☑ appropriate box(es))		
3. Does the owner/operator encourage pollution prevention through such measures as training employees involved in surface coating operations on methods of reducing VOC emissions by:  a) maintaining spray coating equipment to ensure effective application with a minimum of overspray?		
PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300, F.A.C.  A. New or Modified Process Equipment  1. Since the last inspection has there been  a) installation of any new process equipment?————————————————————————————————————		
Raquel M. Arias	04/17/09	
Inspector's Name (Please Print)	Date of Inspection	
Inspector's Signature	Approximate Date of Next Inspection	
<b>COMMENTS:</b> Several filters were missing in the spray booth. Overspray was noted outside the building near the vent.		