Air Pollution Source Inspection Florida Department of Environmental Prote	_	PAGE 1 OF 1	
FACILITY: Gulf Coast Concrete Block Plant	· · · · · · · · · · · · · · · · · · ·	ID#: 0170371-001-AG COUNTY: Citrus	
ADDRESS: 8778 South Jump CT, Homosassa 34448	INSPECTION DATI	E: 12/12/2007	
	TIME IN: 0930	TIME OUT: 1100	
CONTACT: Owner, Wallace Hindalong 352-621-3900	inspection type: (	INSPECTION TYPE: Complaint # 10803	
	EU(s) INSPECTED:	EU(s) INSPECTED: EUOO1	
SOURCE DESCRIPTION: Makes Concrete Blocks	Associated with PER	Associated with PERMIT: 775190-002-AG	
	PERMIT EXPIRAT	PERMIT EXPIRATION DATE: 2012	
INSPECTIO	N FINDINGS		
The owner of this facility has sent a registration form to This facility has been in operation since February 2007 Registration Form per Mr. Hindalong.  Note: Located on property is a relocatable concrete Also the registration form for the BLOCK PI have been inputted after the inspection date of 12/12/20 it was still in Finance and Accounting. The Facility ID for the Accounting of the Facility ID for the Accounting of the Facility ID for the Facility ID for the Accounting of the Facility ID for the Fa	without a valid Concrete Batch e batch plant 777519.002.AG LANT was received by Tallahas 007 because I talked with Dick I	ing Plant General Permit see 12/10/2007 and must	
During the inspection two deficience  1) Constructing/operating with out Registration Form  2) No VE test was performed with	a valid Concrete Batching Plan	t General Permit	
Constructing/operating with out Registration Form     No VE test was performed with	a valid Concrete Batching Plan	t General Permit	
1) Constructing/operating with out Registration Form 2) No VE test was performed with	a valid Concrete Batching Plan in 30 days of commencing com  STATUS: MNC	at General Permit	