

CONCRETE BATCHING PLANT



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE:	, , , , , , , , , , , , , , , , , , ,	☐ COMPLAINT/DISCOVI☐ ARMS COMPLAINT No	, , <u>—</u>
	RE-INSPECTION (FUI)	ARMS COMPLAINT N	O.
AIRS ID#: 7775534 DA	TE: <u>09/16/2009</u>	ARRIVE: 1:09 pm	DEPART: <u>1:15 pm</u>
FACILITY NAME: PE	ACE R RESERVOIR PROJE	ECT-RELO CCB PLANT	
FACILITY LOCATION	N: 8999 SW CR 769		
	ARCADIA 34629		
OWNER/AUTHORIZE	D REPRESENTATIVE: (GERRY ARVIDSON PHON	IE: (863)491-7415
CONTACT NAME:		PHON	E:
ENTITLEMENT PERIO	OD: 9/26/2008 / 9/26/2 (effective date) (end date		
	(0.1000.10 0.110)	<i>-</i>	
PART I: INSPECTION	COMPLIANCE STATUS	(check v only one box)	
IN COMPLIANO	CE MINOR Non-CC	OMPLIANCE SIGNIFICA	ANT Non-COMPLIANCE
PART II: TESTING/RE (check ☑ appropriate		<u>REMENTS</u> – Rule 62-296.414, F	F.A.C.
Stack Emissions			
1. Were visible emis		this site visit according to EPA M	Iethod 9 (Ref.: Chapter □Yes □ No
2. Are emissions fro	om silos, weigh hoppers (batch	hers), and other enclosed storage	
3. During visible em	nissions tests of the silo dust of	collector exhaust points was the loo loading rate, or at least at the mi	pading of the silo conducted
unless such rate is	s unachievable in practice?		
to this question is	"Yes", then continue on to q	uestions 4.a) and 4.b) below. If ar	
a) Was the batchi	ing operation in operation dur	ring the visible emissions test?	
duration?			
from the silo dust	collector, are the visible emi	operation are controlled by a dust assions tests of the weigh hopper (esentative of the normal batching r	

PART II: TESTING/RECORDKEEPING REQUIREMENTS – Rule 62-296.414. F.A.C. – (continued)					
PART II: <u>TESTING/RECORDKEEPING REQUIREMENTS</u> – Rule 62-296.414, F.A.C. – (continued) (check ☑ appropriate box(es)					
(check is appropriate box(es)					
Compliance Demonstration - (Rule 62-296.401(5)(i), F.A.C.) 1. Is each dust collector exhaust point tested according to the visible emissions limiting standard as part of the annual compliance demonstration? (Rule 62-297.310(7)(a), F.A.C.)					
New Facilities – (permitted pursuant to Rule 62-210.300(4), F.A.C., Air General Permits) 2. Did this facility demonstrate: a) initial compliance no later than 30 days after beginning operation?					
Existing Facilities – (permitted pursuant to Rule 62-210.300(4), F.A.C., Air General Permits) 3. In order to demonstrate annual compliance, was an annual visible emissions test conducted 60days prior to the AGP Notification form submission, and within 60 days prior to each anniversary date?					
Test Reports – (Rules 62-213.440, F.A.C. and 62-297.310(8)(b), F.A.C.) 4. Was the required test report filed with the department as soon as practical, but no later than 45 days after the test was completed?					
PART III: OPERATING/RECORDKEEPING REQUIREMENTS – Rule 62-210.300(4)(c)2., F.A.C.					
(check \square appropriate box(es))					
 (check appropriate box(es)) 1. Is this facility: 1) a stationary ; 2) a relocatable ; or does it have: 3) both, stationary and relocatable 					

PART III: OPERATING/RECORDKEEPING REQUIREMENTS – Rule 62-296.414(2)(a) and (b), F.A.C. (continued) (check ☑ appropriate box(es))						
Unconfined Emissions – (Rule 62-296.320(4)(c), F.A.C.) 1. Does the owner /operator of the concrete batching plant take reasonable precautions to control unconfined emissions by: a) management of roads, parking areas, stock piles, and yards, which shall include one or more of the following: 1) paving and maintenance of roads, parking areas, stock piles, and yards?						
PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300(4)(d)4., F.A.C. A. New or Modified Process Equipment 1. Since the last inspection has there been a) installation of any new process equipment?						
Wendy D. Simmons	09/16/2009					
Inspector's Name (Please Print)	Date of Inspection	_				
	09/16/2012					
Inspector's Signature	Approximate Date of Next Inspection	_				

COMMENTS: Pre-inspection: On June 4, 2009, I received an email from Mr. Steven Kidd requesting information about taking down the facility. See email dated 06/04/2009 in compliance file. Inspection Findings: On this day, I conducted a Drive-by Inspection to confirm that the equipment described as facility Id# 7775534 was still on the Peace River Resevior site. Photos were taken and are attached to this inspection report. As noted in email correspondence with Mr. Steven Kidd, a relocation notice should be provided to the Department prior to moving the equipment off the Peace River Resevior site.