

Department of Environmental Protection

Jeb Bush
Governor

OCT 11 2001

Southeast District
P.O. Box 15425
West Palm Beach, Florida 33416

David B. Struhs
Secretary

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

WARNING LETTER

Mr. John DeStefano
Jade Cleaners Formerly Known As Amlene Clean
4082 PGA Blvd
Palm Beach Gardens, FL 33410

Palm Beach County
CU/Dry Cleaning Program
#WL01-0136CU50SED

RE: Jade Cleaners Formerly Known As Amlene Clean
4082 PGA Blvd
Palm Beach Gardens, FL 33410
DEP Facility ID: 509501805

Dear Mr. DeStefano:

The purpose of this letter is to advise you of possible violations of law for which you may be responsible, and to seek your cooperation in resolving the matter.

The Department staff inspected the above referenced facility on August 14, 2001, as part of the Southeast District's program to assist in the administration of Chapter 62-781, Florida Administrative Code (F.A.C.). Following the inspection, a copy of the Inspection Exit Summary (copy is attached herewith), was provided to you by the Department, and all tentatively identified non-compliance items were discussed. As explained during the Exit Summary, the Department advised and you agreed to provide documentation of your efforts to bring the facility into compliance by September 14, 2001.

The Department has received the following two facsimile submittals after the deadline for the submittal had expired:

1. On September 24, 2001, the Department received a facsimile copy of a Perchloroethylene DryCleaner Air General Permit Notification Form with the notation "original mailed to Tallahassee".
2. On September 30, 2001, the Department received a facsimile copy of a letter addressing the Department's Inspection Exit Summary, however, no supporting documentation was provided to demonstrate any effort to bring the facility into compliance.

"More Protection, Less Process"

Printed on recycled paper.

Jade Cleaners Formerly Known As Amlene Clean

#WL01-0136CU50SED

CU/Dry Cleaning Program

Department of Environmental Protection personnel observed the following at the above described facility:

1. On August 14, 2001, secondary containment was not provided for solvent based spotting chemicals over one (1) quart in volume.
2. On August 14, 2001, secondary containment was not provided for the press return vacuum, a device which collects and stores perchloroethylene contaminated wastewater.
3. On August 14, 2001, the perchloroethylene wastewater treatment system was inspected and was found to be non-functional and not properly maintained.
4. On August 14, 2001, the facility operator, when requested by Department staff, could not provide monthly records of solvent consumption for the perchloroethylene dry cleaning machine.
5. On August 14, 2001, the facility operator, when requested by Department staff, could not provide leak inspection and repair reports.
6. On August 14, 2001, the facility operator, when requested by Department staff, could not provide records of all control equipment monitoring data on perchloroethylene concentrations and exhaust stream temperatures.
7. On August 14, 2001, the facility operator, when requested by Department staff, could not provide records documenting the purchase of total perchloroethylene purchased in the previous month and calculations of the total amount purchased in the preceding 12 months.
8. On August 14, 2001, Department staff observed that the facility operator failed to post site-specific emergency information.
9. On August 14, 2001, the facility operator, when requested by Department staff, could not provide records documenting weekly hazardous waste container inspections.
10. On August 14, 2001, the facility operator, when requested by Department staff, could not provide records of hazardous waste manifests, waste analysis or test results and Biennial Reports or Exception Reports.
11. On August 14, 2001, Department staff observed that the facility operator failed to properly label two hazardous waste containers with the accumulation start date.
12. Department records indicate that this operating drycleaning facility never registered with the Department within 30 days after the start of operation.
13. Department records indicate that this operating drycleaning facility has failed to pay the annual drycleaning registration fee of \$100.00 and additional late penalty fee of \$75.00 for the fiscal year 1999-2000.

Jade Cleaners Formerly Known As Amlene Clean

#WL01-0136CU50SED

CU/Dry Cleaning Program

14. Department records indicate that this operating drycleaning facility has failed to pay the annual drycleaning registration fee of \$100.00 and additional late penalty fee of \$75.00 for the fiscal year 2000-2001.

15. Department records indicate that this perchloroethylene drycleaning facility failed to obtain a Title V air general permit within 30 days after the start of operation and has operated the facility without Departmental authorization.

16. Department records indicate that this operating drycleaning facility has failed to pay the annual Title V air general permit emissions fee of \$50.00 and additional late fee of \$25.00 for the fiscal year 1999-2000.

17. Department records indicate that this operating drycleaning facility has failed to pay the annual Title V air general permit emissions fee of \$50.00 and additional late fee of \$25.00 for the fiscal year 2000-2001.

18. Department records indicate that this operating drycleaning facility has failed to submit DEP Form No.62-213.900 (7) (Statement of Compliance) for the fiscal year 1999-2000 by March 1, 2001.

19. Department records indicate that the facility owner and/or real property owner failed to pay the Drycleaning Solvent Cleanup Program deductible of \$5,000.00 within 60 days after receipt of billing by the Department.

20. Department records indicate that the facility owner has failed to remit all taxes due, pursuant to Sections 376.70 and 376.75, F.S., to the Department of Revenue.

Please note that:

Sections 376.3078 (9)(a) and (b), Florida Statutes (F.S.), require owners or operators of dry cleaning facilities to provide dikes or other containment structures around each machine or item of equipment in which drycleaning solvents are used and around any area in which solvents or waste containing solvents are stored. Additionally, the dikes or containment structures shall be impermeable and capable of containing 110 percent of the capacity of each machine and each such storage area.

Section 376.303(1)(d)(1) and (2a), F.S., require owners, operators and the real property owners of dry cleaning facilities to jointly register all operating drycleaning facilities with the Department and submit to the Department an initial fee of \$100.00 and an annual renewal registration fee of \$100.00 for each drycleaning facility owned and in operation. New businesses are required to register within 30 days after the start of operation. Facilities that fail to pay their initial or renewal fee within 30 days after receipt of billing are subjected to a late fee of \$75.00. Additionally, F.S. 376.302 (1)(b) provides that it is prohibited for any reason to fail to obtain any permit or registration as required by Chapter 376, F.S.

Rule 62-213.300(3)(k)3, F.A.C., requires that each owner or operator of a perchloroethylene solvent drycleaning facility keep all purchase receipts of perchloroethylene solvent and maintain monthly records of solvent consumption. These records are to be kept in a log onsite for a minimum of five (5) years.

Jade Cleaners Formerly Known As Amlene Clean

#WL01-0136CU50SED

CU/Dry Cleaning Program

Rule 62-213.300(3)(k)3 F.A.C., requires that each owner or operator of a perchloroethylene solvent drycleaning facility to perform leak detection inspections and maintain records of leak detection inspections and repair reports in a log onsite for a minimum of five (5) years.

Rule 62-213.300(3)(k)3, F.A.C., requires that each owner or operator of a perchloroethylene solvent drycleaning facility to perform perchloroethylene concentration monitoring on control equipment and conduct monitoring on exhaust stream temperatures. This monitoring data is to be recorded in a log onsite and kept for a minimum of five (5) years.

Rule 62-213.300(3)(k)3, F.A.C., requires that each owner or operator of a perchloroethylene solvent drycleaning facility to document and maintain records of the purchase of total perchloroethylene purchased in the previous month and calculations of the total amount purchased in the preceding 12 months. These records are to be kept in a log onsite for a minimum of five (5) years.

Rule 62-213.300(1)(a), F.A.C., requires that each owner or operator of a perchloroethylene solvent drycleaning facility submit a completed Perchloroethylene Drycleaner Air General Permit Notification Form (DEP form 62-213.900.900(2)) to the Department at least 30 days prior to beginning operation

Rules 62-213.205 & 62-213.205 (1)(e)(3)(g), F.A.C., requires that each Title V permitted perchloroethylene solvent drycleaning facility must pay between January 15 & March 1 of each year, upon written notice from the Department, an annual emissions fee of \$50.00. If this fee is not paid by March 1 of the year due, the Department shall assess a late fee of \$25.00.

Rule 62-213.440(3)(a)(2) requires that each Title V permitted perchloroethylene solvent drycleaning facility must submit a Statement of Compliance with all terms and conditions of the permit using DEP Form No.62-213.900(7) (Statement of Compliance). Such form must be submitted to the Department and EPA annually, within 60 days after the end of each calendar year during which the Title V permit was effective.

40 CFR 262.34(d)(5)(ii), provides that a generator must post the following information next to the telephone:

- (A) The name and telephone number of the emergency coordinator;
- (B) Location of fire extinguishers and spill control material and if present fire alarm;
- (C) The telephone number of the fire department, unless the facility has a direct alarm

40 CFR 265.174, provides that the owner or operator must inspect areas where containers are stored, at least weekly looking for leaks and for deterioration caused by corrosion or other factors

40 CFR 264.31 provides that the facilities must be designed, constructed, maintained and operated to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water which could threaten human health or the environment.

Jade Cleaners Formerly Known As Amlene Clean
#WL01-0136CU50SED
CU/Dry Cleaning Program

40 CFR 262.40(a), provides that a generator must keep a copy of each manifest signed in accordance with 40 CFR 262.23(a) for three years or until he receives a signed copy from the designated facility which received the waste. This signed copy must be retained for at least three years from the date the waste was accepted by the initial transporter.

40 CFR 262.40(b), provides that a generator must keep a copy of each Biennial Report and Exception Report for a period of at least three years from the due date of the report.

40 CFR 262.40(c), provides that a generator must keep records of any test results, waste analyses, or other determinations made in accordance with 40 CFR 262.11 for at least three years from the date that the waste was last sent to on-site or off-site treatment storage or disposal.

Section 376.3078 F.S., requires participants in the Drycleaning Solvent Cleanup Program to pay the deductible of \$5000.00 within sixty (60) days after receipt of billing.

Section 376.70 and 376.75 F.S., require owners or operators of dry cleaning facilities to remit all taxes due, pursuant to Chapter 376.70 and 376.75 F.S., to the Department of Revenue.

Sections 403.161 and 376.302, F.S., provide that it is prohibited for any reason to violate or fail to comply with any statute, rule, order, permit, registration, or certification adopted or issued by the Department pursuant to its lawful authority.

The activities observed during the Department's field inspection and any other activities at your facility that may be contributing to violations of the above-described statutes or rules should be ceased immediately.

Please be advised that facilities operating in a grossly negligent manner at any time on or after November 19, 1980 shall be ineligible for state cleanup pursuant to Chapter 62-781, F.A.C.

The total administrative penalties assessed in accordance with Chapter 403.121, F.S., for this case is \$10,500.00. The proposed penalty in this case has been reviewed and approved by the Department. In accordance with the August 12, 1997 Department's "Settlement Guidelines for Civil Penalties" and the RCRA Civil Penalty Policy of 1990, the penalty proposed in the case is \$6,400.00.

The total penalties assessed and proposed to resolve this case is \$16,900.00 plus \$1000.00 for Department Cost and expenses. This matter may be resolved through entry of a Consent Order, which will include the civil penalty.

You are requested to contact Mr. Paul Alan Wierzbicki, P.G. at the letterhead address or telephone number (561) 681-6677 or Mr. Ronald King at the letterhead address or telephone number (561) 681-6671 within ten (10) days of receipt of this Warning Letter to arrange a meeting to discuss this matter.

Jade Cleaners Formerly Known As Amlene Clean


#WL01-0136CU50SED

CU/Dry Cleaning Program

The Department is interested in reviewing any facts you may have that will assist in determining whether any violations have occurred. You may bring anyone with you to the meeting that you feel could help resolve this matter.

Please be advised that this Warning Letter is part of an agency investigation, preliminary to agency action in accordance with Section 120.57(5), F.S. We look forward to your cooperation in completing the investigation and resolution of this matter.

Sincerely,



Melissa L. Meeker 10/10/01
Director of District Management
Southeast District

MLM:vk:pw:rk

RECEIVED
OCT 15 2001
Bureau of Air Monitoring
& Mobile Sources

Attachments: Civil Penalty Assessment & RCRA Civil Penalty Justification
Inspection Exit Summary

cc: Bill Burns, DEP/BWC, Tallahassee (w/o enclosures)
West Palm Beach DEP files (w/enclosures)
Waste Cleanup Archboard (w/enclosures)
John O'Malley, PBC Public Health Unit (w/o enclosures)
Sandy Bowman, DEP, Tallahassee (w/enclosures) MS 5510
Titan Management, 53 Forest Ave., 2nd Floor, Old Greenwich, Connecticut 06870
Martin Lubner, PBC Public Health Unit (w/o enclosures)

C:\Warningletter\Jade.doc

Reference document No. N/A

PENALTY JUSTIFICATION

Jade Cleaners Formerly Known As Amlene Clean
4082 PGA Blvd
Palm Beach Gardens, FL 33410

Based upon Guidelines for Characterizing
RCRA Violations dated 3/27/00.

1. **Regulation:** 40 CFR 264.31
Preparedness and Prevention

Violation: Jade Cleaners ("JC") failed to maintain and operate its facility in order to minimize an unplanned or sudden release of hazardous waste by not maintaining the drycleaning unit and Zero Waste wastewater treatment system, which in turn resulted in the discharge of perc contaminated water to the surface of the ground and/or sewer.

Characterization of Violation:

Potential for Harm - Minor

Using the Potential for Harm Ranking System, the nature of the waste, volume of waste (< 6 drums), discharge of the waste, and potential receptors (10-100 people) were taken into account in determining this portion of the matrix. The potential for harm is minor

Extent of Deviation - Moderate

The penalty calculation guidelines in the DEP enforcement manual indicate that if a SQG facility fails to maintain and operate a facility in order to minimize an unplanned or sudden release of hazardous waste, the extent of deviation is moderate.

Multi-day – Unable to determine.

Economic Benefit - Unable to determine.

Adjustments - N/A

2. **Regulation:** 40 CFR 262.40, 263.22, 264.71(b)(5), 265.71(b)(5)
Failure to maintain a uniform manifest or contractual agreement for three years.

Violation: JC failed to maintain a uniform manifest or contractual agreement for three years.

Characterization of Violation:

Potential for Harm - Minor

Using the Potential for Harm Ranking System, the nature of the waste, volume of waste (<6 drums), no discharge of the waste, and potential receptors (10-100 people) were taken into account in determining this portion of the matrix. The potential for harm was determined to be minor.

Extent of Deviation - Minor

The RCRA penalty guidelines in the DEP enforcement manual indicate that the extent of deviation for failing to maintain a uniform manifest or contractual agreement for three years is minor.

Multi-day – Unable to determine.

Economic Benefit – Unable to determine.

Adjustments - N/A

3. **Regulation:** 40 CFR 262.34(d)(5)
Modified Contingency Plan

Violation: JC failed to post site-specific emergency information by its telephones.

Characterization of Violation:

Potential for Harm - Minor

The penalty calculation guidelines in the DEP enforcement manual indicate that the potential for harm for failing to post site-specific emergency information is minor.

Extent of Deviation – Minor

The RCRA penalty calculation guidelines in the DEP enforcement manual indicate that the extent of deviation for failing to post site specific emergency information is minor.

Multi-day - N/A

Economic Benefit - Unable to determine.

Adjustments - N/A

4. **Regulation:** 40 CFR 262.34 (d) & Rule 62-730.160 (6) F.A.C.
Container Management

Violation: JC failed to perform weekly container inspections and maintain a log containing the date and time of the inspection, legible name of the inspector, number and condition of containers and the nature of the corrective actions.

Characterization of Violation:

Potential for Harm - Minor

The penalty guidelines in the DEP enforcement manual indicate that if a facility fails to perform weekly container inspections, the potential for harm is minor.

Extent of Deviation - Major

The penalty guidelines in the DEP enforcement manual indicate that if a facility fails to perform weekly container inspections, the extent of deviation is major.

Multi-day - N/A

Economic Benefit - Unable to determine.

Adjustments - N/A

5. **Regulation:** 40 CFR 262.34 (d)
Labels

Violation: JC failed to label two (2) fifteen (15) gallons containing hazardous waste with an accumulation start date.

Characterization of Violation:

Potential for Harm - Minor

Using the Potential for Harm Ranking System, the nature of the waste, volume of waste (<6 drums), no discharge of the waste, and potential receptors (10-100 people) were taken into account in determining this portion of the matrix. The potential for harm was determined to be minor.

Extent of Deviation - Major

The penalty guidelines in the DEP enforcement manual indicate that if a facility fails to label containers with an accumulation start date, the extent of deviation is major.

Multi-day - Unable to determine.

Economic Benefit - Unable to determine.

Adjustments - N/A

6. **Regulation:** 40 CFR 262.40, 263.22, 264.71(E), 265.71(E)

Failure to retain records of test results, waste analyses, or waste determinations.

Violation: JC failed to retain records of test results, waste analyses, or waste determinations.

Characterization of Violation:

Potential for Harm - Minor

Using the Potential for Harm Ranking System, the nature of the waste, volume of waste (<6 drums), no discharge of the waste, and potential receptors (10-100 people) were taken into account in determining this portion of the matrix. The potential for harm was determined to be minor.

Extent of Deviation - Minor

The RCRA penalty guidelines in the DEP enforcement manual indicate that the extent of deviation for failing to retain records of test results, waste analyses, or waste determinations is minor.

Multi-day - Unable to determine.

Economic Benefit - Unable to determine.

Adjustments - N/A


Penalty Computation Worksheet

Company Name: Jade Cleaners.

Department Staff Responsible for the Penalty Computations:


Ronald King


John Harris


Leslie Smith

Date: October 4, 2001

PART I - Class A Penalty Determinations*

<u>Alleged Violation Type</u>	<u>Potential for Harm</u>	<u>Extent of Dev.</u>	<u>Matrix Amount</u>	<u>Multi-day</u>	<u>Economic Benefit</u>	<u>Total</u>
1. 40 CFR 261.31 Preparedness & Prevention	Minor	Moderate	\$ 1,000	N/A	N/A	\$1,000
2. 40 CFR 262.40 263.22, 264.71(b)(5), 265.71(b)(5) Manifest	Minor	Minor	\$ 300	N/A	N/A	\$300
3. 40 CFR 262.34(d) Mod. Cont. Plan	Minor	Minor	\$ 300	N/A	N/A	\$300
4. 40 CFR 262.34 & Rule 62-730.160 (6), F.A.C. Container Management	Minor	Major	\$ 2,250	N/A	N/A	\$2,250
5. 40 CFR 262.34(d) Labels	Minor	Major	\$2,250	N/A	N/A	\$2,250
6. 40 CFR 262.40, 263.22, 264.71(E), 265.71(E) Records of Test Results, etc.	Minor	Minor	\$300	N/A	N/A	\$300

Total Penalties for all Violations: \$6,400

* All penalty calculations are based on the Florida Department of Environmental Protection Hazardous Waste Regulation Section's "Guidelines for Characterizing RCRA Violations" revised as of 4/18/95 and "Guidelines for Characterizing Used Oil Violations" revised as of 8/96. Certain violations require Potential for Harm Ranking System characterization and have been utilized where applicable. See Part III for each violation for which an adjustment or multi-day

penalty is determined. The attached civil penalty worksheets are formulated and tendered only in the context of settlement negotiations in order to attempt to reach a cooperative settlement.

10/10/01
Date

Melissa L. Meeker
Melissa L. Meeker
Director of District Management
Southeast District

PENALTY COMPUTATION WORKSHEET

Part II - Multi-day Penalties and Adjustments

ADJUSTMENTS	Dollar Amount
Good faith/lack of good faith prior to discovery:	_____
Justification: _____ _____	
Good faith/lack of good faith after discovery:	_____
Justification: _____ _____	
History of non-compliance:	_____
Justification: _____ _____	
Economic Benefit of non-compliance:	_____
Justification: _____ _____	
Ability to pay:	_____
Justification: _____ _____	
Total Adjustments:	_____

MULTI-DAY PENALTIES

DOLLAR AMOUNT _____

Number of days adjustment factor(s) to be applied: _____

Justification:

Number of days matrix amount is to be multiplied: _____

Justification: _____

PENALTY CALCULATION WORKSHEET

Part III - Other Adjustments Made After Meeting With the
Responsible Party

ADJUSTMENTS

Dollar Amount: _____

Relative merits of the case: _____

Resource considerations: _____

Other justifications: _____

Date

Melissa L. Meeker
Director of District Management
Southeast District

CIVIL PENALTY ASSESSMENT

Jade Cleaners Formerly Known As Amlene Clean
4082 PGA Blvd
Palm Beach Gardens, FL 33410

Based upon Chapter 430.121, Florida Statutes

Count I: **Section 376.303(1)(d)(1) and (2a), F.S., Failure to register an operating Drycleaner within 30 days after the start of operation .**

Justification: The violation related in Count I require an assessment of an administrative penalty of \$500.00 under Section 403.121(5) F.S. for failure to comply with any statute, rule order, permit registration, or certification adopted or issued by the Department pursuant to its lawful authority.

Count II **Sections 376.3078 (9)(a) and 376.3078 (9)(b), Florida Statutes (F.S.), Secondary Containment.**

Justification: The violation related in Count II require the assessment of an administrative penalty under Section 403.121(4)(b), of \$4000.00 for failure to install, maintain, or use a required pollution control system or device.

Count III **Section 376.303(1)(d)(1) and (2a), F.S., Failure to pay annual registration fees and late fees for 1999 and 2000.**

Justification: The violation related in Count III require an assessment of an administrative penalty of \$500.00 under Section 403.121(5) F.S. for failure to comply with any statute, rule order, permit registration, or certification adopted or issued by the Department pursuant to its lawful authority.

Count IV **Rule 62-213.300 (1)(a), Failure to submit a completed Perchloroethylene Dry Cleaner Air General Permit Notification Form (Dep Form 62-213.900(2)) to the Department at least 30 days prior to beginning operation.**

Justification: The violation related in Count IV require the assessment of an administrative penalty under Section 403.121(3)(f), of \$4000.00 for operating without an air operating permit.

Count V **Rule 62-213.300 (3)(b) F.A.C., Failure to pay annual emission fees for 1999 and 2000.**

Justification: The violation related in Count IV require an assessment of an administrative penalty of \$500.00 under Section 403.121(5) F.S. for failure to comply with any statute, rule order, permit registration, or certification adopted or issued by the Department pursuant to its lawful authority.

Count VI **Rule 62-213.300(3)(k), Monitoring, Related Recordkeeping & Reporting Requirements**

Justification: The violation related in Count VI require the assessment of an administrative penalty under Section 403.121(4)(d), of \$2000.00 for failure to conduct required monitoring or testing and of 403.121(d)(f) F.S., of \$500.00 for failure to prepare, submit, maintain, or use required reports or other required documentation.

Count VII

Chapter 376.3078 F.S., Failure to pay Drycleaning Solvent Cleanup Program Deductible of

\$5000.00 within sixty (60) days after receipt of billing.

Justification:

The violation related in Count VI require an assessment of an administrative penalty of \$500.00 under Section 403.121(5) F.S. for failure to comply with any statute, rule order, permit registration, or certification adopted or issued by the Department pursuant to its lawful authority.

Count VIII

Chapter 376.70 and 376.75 F.S., Failure to remit all taxes due, pursuant to Chapter 376.70 and

376.75 F.S., to the Department of Revenue.

Justification:

The violation related in Count VI require an assessment of an administrative penalty of \$500.00 under Section 403.121(5) F.S. for failure to comply with any statute, rule order, permit registration, or certification adopted or issued by the Department pursuant to its lawful authority.

Economic Benefit - Not calculated at this time, the Department might calculate economic benefit if necessary.

Multi-day Penalties - Not calculated at this time, the Department might calculate economic benefit if necessary.

The total administrative penalties assessed for Counts I - VIII is \$10,500.00

The Department has incurred expenses to date while investigating this matter in the amount of not less than \$1,000.00.

The total administrative penalties, cost and expenses assessed to date are \$11,500.00.

Name of Department Staff Responsible for the Penalty Computations:


Paul Alan Wierzbicki
Paul Alan Wierzbicki, P.G., Date

Ronald M. King
Ronald M. King, ES II Date

Leslie Smith
Leslie Smith, ES III Date 10/8/01

10/10/01
Date

Melissa L Meeker
Melissa L Meeker
Director of District Management
Southeast District



THE DEP MAINTAINS A TOLL FREE FAX-ON-DEMAND SYSTEM; YOU CAN OBTAIN INFORMATION ON THE DRYCLEANING PROGRAM 24-HRS/DAY 800-789-4502 OUR INTERNET ADDRESS IS WWW.STATE.FL.US/WASTE/PROGRAMS/DRYCLEAN/INDEX.HTM

Inspection Exit Summary

Drycleaning Facility: JADE Cleaners

Date: 8/14/01 Time: 3:00 pm

An inspection of your facility was conducted today for the purpose of determining compliance with applicable Department regulations; this exit interview is the Department's attempt to advise you of possible violations. This list may be incomplete and further inquiry may result in further discovery. The Department has signed an enforcement agreement with the U.S. Environmental Protection Agency which calls for the assessment and collection of monetary penalties under some circumstances. Further, Chapter 376, Florida Statutes, prohibits the Department from expending cleanup funds at sites that have been operated in a grossly negligent manner or are not in compliance with the department's rules regulating drycleaning solvents, drycleaning facilities, or wholesale supply facilities on or after November 19, 1980. While your quick response may not prevent monetary penalties or loss of eligibility, continued non-compliance may result in greater liability.

The following violations have been tentatively identified:

- 1. The registration information for the facility is not correct. - quest 275, in back register per
- 2. The facility has not registered as an operating drycleaner.
- 3. Equipment inspection logs are not current or consistent.
- 4. Records showing proper management of hazardous waste are not available insufficient.
- 5. Equipment does not appear to be maintained to prevent a release.
- 6. There is evidence of releases of contaminants, but no record of response.
- 7. Separator water is being evaporated without proper controls.
- 8. Separator water is being improperly discharged to sewer, septic tank or ground.
- 9. Separator water containers are not covered during collection or storage.
- 10. Vacuum return water is being improperly discharged to sewer, septic tank, or ground.
- 11. No secondary containment is provided for the drycleaning machine.
- 12. No secondary containment is provided for the waste containers.
- 13. No secondary containment is provided for solvent based spotters over one quart in volume.
- 14. Secondary containment is damaged or insufficient.
- 15. Floors are not sealed.
- 16. Sealed floor areas are peeling, pitted, cracked or show other signs of damage or misinstallation.
- 17. Hazardous waste containers are not being stored in a manner to prevent release.
- 18. Product and/or waste containers are not properly labeled. - no date.
- 19. Facility is not equipped to effectively respond to a solvent release.
- 20. Other zero waste is not functional - repair & provide

COMMENTS:

copies of repair documents.

- 2) taxes are to be remitted to the Dept of Revenue - provide proof of payment.
- 3) provide copies of hazardous waste manifest for last 3 yrs.
- 4) start hazardous waste container inspections.
- 5) No following "perc" on clothes. over ->

The following will be provided to help you maintain compliance with Department regulations:

- Multimedia Guide or mailing address
- Secondary Containment Fact Sheet
- Registration Information
- Spill response information/sticker
- Small Business Assistance Program Booklet
- Small Quantity Generator Handbook/Fact Sheet
- Summary of Hazardous Waste Regulations
- Contact Water management Information
- Rule 62-781, F.A.C.
- Application Information
- Summary of Air Regulations
- Other

Operator/Owner was provided copy of Notice of Site Visit. Yes No

I agree to provide written documentation of efforts to address the deficiencies noted above by: 9/14/01

X refused to sign

RECEIPT ACKNOWLEDGED

[Signature]
INVESTIGATOR


- 6) payment of \$5,000.00 deductible w exp. for DSCP.
7. update registration & pay back registration fee of 275.00
8. cease discharge of vacuum return water & separate water to sewer or surface of ground
- 9) cease discharge of mop water (that has been used to clean around unit) to sewer.
- 10) (8 & 9) - discharges are to be disposed of in waste Drum.
- 11) install secondary containment under vacuum unit (Kema.)
- 12) DEP records indicate that this facility does not have a perchloroethylene Dry Clean Air general permit. Attached is a notification of Intent to Use General permit. Fill it out & submit to the following address within. Enclose \$50.00 & submit a copy of completed form to this office.

STATE OF FLORIDA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
MS 5510-37550 304000
2600 BLAIR STONE ROAD
TALLAHASSEE FL 32399-2400

CERTIFIED

Z 210 662 405

MAIL



RETURNED TO SENDER

INSUFFICIENT ADDRESS
 NO SUCH NUMBER
 UNCLAIMED
 ATTEMPTED
 NO SUCH STREET
 VACANT
 NO SUCH STREET
 NOT RECEPTACLE ADDRESS DELIVERABLE AS ROUTE FORWARDED UNABLE TO DELIVER
DATE 6/9
CARR/INITIALS

RECEIVED
JUN 11 2001
Bureau of Air Monitoring
& Mobile Sources

10 AIRS ID # 0990431001AG
STEVEN MILLS
AMLENE CLEAN
4275 A OKEECHOBEE BLVD
WEST PALM BEACH FL 33409

Fold at line over top of envelope to

COMPLETE THIS SECTION ON DELIVERY

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

A. Received by (Please Print Clearly) B. Date of Delivery

C. Signature

X

- Agent
- Addressee

D. Is delivery address different from item 1? Yes
If YES, enter delivery address below: No

1. Article Addressed to:

10 AIRS ID # 0990431001AG
 STEVEN MILLS
 AMLENE CLEAN
 4275 A OKEECHOBEE BLVD
 WEST PALM BEACH FL 33409

3. Service Type

- Certified Mail Express Mail
- Registered Return Receipt for Merchandise
- Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

2. Article Number (Copy from service label)

2210 662 405

TITLE V AIR QUALITY GENERAL PERMIT
INSPECTION SUMMARY REPORT

TYPE OF INSPECTION: ANNUAL COMPLAINT/DISCOVERY RE-INSPECTION

TIME IN: 11:00 TIME OUT: 11:50 AIRS ID#: 0990431
 TYPE OF FACILITY: Dry cleaning
 FACILITY NAME: AMLENEO CLEAN DATE: 1-31-97
 FACILITY LOCATION: 4082 PGA Blvd
P.B.G., FL 33410
 RESPONSIBLE OFFICIAL: Steven Mills PHONE NUMBER: 689-5750

- Based on the results of the compliance requirements evaluated during this inspection, the facility is found to be in compliance with DEP Rule 62-213.300, Florida Administrative Code (F.A.C.).
- Based on the results of the compliance requirements evaluated during this inspection, the following compliance discrepancies were noted:

COMPLIANCE REQUIREMENT/PROBLEM	FOLLOW-UP ACTION REQUIRED

COMMENTS:

The Annual Compliance Certification form has been properly certified and submitted to the inspector. YES NO

DATE OF NEXT INSPECTION: 1-31-98

INSPECTION CONDUCTED BY: R.V. Chokshi
(Approximate)

INSPECTOR'S SIGNATURE: [Signature] PHONE NUMBER: 355-3070
(Please Print)

0990431

Amlene Clean

- spoke with Steven Mills - 9/24/96

p.13 7. add firm

p.14 1.(a) add date machine initially
purchased - Feb-95; add
date(s) control device(s) installed
1.(c) mark out "X" and initial

p.15 5.(f) required

Perchloroethylene Dry Cleaning Facility Notification

Facility Name and Location

1. Facility Owner/Company Name (Name of corporation, agency, or individual owner):	Amlene, Inc.		
2. Site Name (For example, plant name or number):	Amlene Clean		
3. Hazardous Waste Generator Identification Number:	FLR000005710		
4. Facility Location:	Street Address: 4082 PGA Blvd		
	City: Palm Beach Gardens	County: Palm Beach	Zip Code: 33410
5. Facility Identification Number (DEP Use):	0990431		

Responsible Official

6. Name and Title of Responsible Official:	Steven Mills Vice President - Amlene Inc.		
7. Responsible Official Mailing Address:	Organization/Firm: Street Address: 4275A Okeechobee Blvd City: West Palm Beach County: Palm Beach Zip Code: 33409		
8. Responsible Official Telephone Number:	Telephone: (561) 689-5751 Fax: (561) 689-2082		

Facility Contact (If different from Responsible Official)

9. Name and Title of Facility Contact (For example, plant manager):			
10. Facility Contact Address:	Street Address: City: County: Zip Code:		
11. Facility Contact Telephone Number:	Telephone: (561) 622-0107 Fax: () -		

RECEIVED
AUG 30 1998
Bureau of Air Monitoring
& Mobile Sources

Facility Information

(a) Provide the information below for each machine at the facility. Indicate the type of machine, the date of its purchase, and the date the control device was installed, if applicable.

Type of Machine	ID	Date Machine Initially Purchased	Date Control Device Installed	ID	Date Machine Initially Purchased	Date Control Device Installed	ID	Date Machine Initially Purchased	Date Control Device Installed
<i>Example</i>									
	#1	03-OCT-93	12-NOV-93	#2	08-DEC-91		#3	02-MAR-92	02-MAR-92
Dry-to-Dry Unit									
(1) w/ ref. condenser									
(2) w/ carbon adsorber									
(3) w/ no controls									
Washer Unit									
(4) w/ ref. condenser									
(5) w/ carbon adsorber									
(6) w/ no controls									
Dryer Unit									
(7) w/ ref. condenser									
(8) w/ carbon adsorber									
(9) w/ no controls									
Reclaimer Unit									
(10) w/ ref. condenser									
(11) w/carbon adsorber									
(12) w/ no controls									

(b) Control devices are required, but not yet installed

(c) No control devices are required to be installed

2.(a) What was the total quantity of perchloroethylene (perc) purchased in the latest 12 months?
 gallons

(b) If less than 12 months, how many? months

Check why it is less than 12 months: New owner: New store: Did not keep records:

3. What is the facility's source classification based on the definitions found in section (3) of Part II?
 (Indicate with an "X". Select one classification only.)

Existing small area source

New small area source

Existing large area source

New large area source

NEW
Small
P.C.

4. What control technology is required on machines pursuant to section (5) of Part II of this notification form?
(Indicate with an "X".)

Existing large area source

Carbon adsorber

Refrigerated condenser

New small area source

Refrigerated condenser

New large area source

Refrigerated condenser

5. A facility which contains non-exempt emissions units shall not be eligible to use the general permit pursuant to Rule 62-213.300, F.A.C. Verify that all steam and hot water generating units on-site meet the following exemption criteria or that no such units exist on-site:

All steam and hot water generating units on-site (1) have a total heat input of 10 million BTU/hr or less (298 boiler HP or less), and (2) are fired exclusively by natural gas except for periods of natural gas curtailment during which propane or fuel oil containing no more than one percent sulfur is fired.

All steam and hot water generating units exempt
No such units on-site

Equipment Monitoring and Recordkeeping Information

Check all logs which are required to be kept on-site in accordance with the requirements of this general permit:

- (a) Purchase receipts and solvent purchases
- (b) Leak detection inspection and repair
- (c) Refrigerated condenser temperature monitoring
- (d) Carbon adsorber exhaust perc concentration monitoring
- (e) Instrument calibration
- (f) Start-up, shutdown, malfunction plan

Surrender of Existing Air Permit(s)

Please indicate with an "X" the appropriate selection:

- I hereby surrender all existing air permits authorizing operation of the facility indicated in this notification form; specifically, permit number(s) _____.

- No air permits currently exist for the operation of the facility indicated in this notification form.


Responsible Official Certification

I, the undersigned, am the responsible official, as defined in Part II of this form, of the facility addressed in this notification. I hereby certify, based on information and belief formed after reasonable inquiry, that the statements made in this notification are true, accurate and complete. Further, I agree to operate and maintain the air pollutant emissions units and air pollution control equipment described above so as to comply with all terms and conditions of this general permit as set forth in Part II of this notification form.

I will promptly notify the Department of any changes to the information contained in this notification.



Signature



Date



Department of Environmental Protection

Lawton Chiles
Governor

Twin Towers Office Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Virginia B. Wetherell
Secretary

December 9, 1996

Mr. Steven Mills
Vice President
Amlene Clean
4275A Okeechobee Boulevard
West Palm Beach, Florida 33409

Re: Facility I.D. No. 0990431

Dear Mr. Mills:

The Department has received the Title V General Permit Notification Form for the dry cleaning facility that you submitted on August 30, 1996.

Please note that in November of each year the Department will be mailing fee notices to those facilities using the Title V general permit. This annual operation fee is \$50 and it is due and payable between January 15 and March 1 of each year the facility is in operation and is subject to the requirements of the Title V general permit.

If you have or expect to have any changes in your mailing address, location address, responsible official, or phone number, please notify the Department at the following address:

Title V General Permits Office
Bureau of Air Monitoring and Mobile Sources MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, Fl 32399-2400

If there are any changes in the facility status, including change of operating parameters or equipment, or if you have any additional questions regarding the Title V General Permit Program, please contact the District or local air program compliance inspector in your area.

Sincerely,

A handwritten signature in cursive script, appearing to read "Dotty Diltz".

Dotty Diltz, Chief
Bureau of Air Monitoring
and Mobile Sources

DD/jw

cc: Mr. Al Grasso, Palm Beach County

"Protect, Conserve and Manage Florida's Environment and Natural Resources"

ARM

✓

PERCHLOROETHYLENE DRY CLEANERS

TITLE V GENERAL PERMIT COMPLIANCE INSPECTION CHECKLIST

TYPE OF INSPECTION: ANNUAL COMPLAINT/DISCOVERY
RE-INSPECTION

AIRS ID#: 0990431 DATE: 1-31-97 TIME IN: 11:00 TIME OUT: 11:50
 FACILITY NAME: AMLENE CLEAN
 FACILITY LOCATION: 4082 PGA BLVD
P. B. G. FL 33410
Steven Mills) 689-5750

PART I: NOTIFICATION

(check appropriate box)

1. Existing facility notified DARM by 9/1/96

2. New facility notified DARM 30 days prior to startup

3. Facility failed to notify DARM to use general permit

PART II: CLASSIFICATION

Facility indicated on notification form that it is:
(check appropriate box)

A.	1. Existing small area source <input type="checkbox"/> dry-to-dry only, $x < 140$ gal/yr transfer only, $x < 200$ gal/yr both types, $x < 140$ gal/yr (constructed before 12/9/91)	2. New small area source <input checked="" type="checkbox"/> dry-to-dry only, $x < 140$ gal/yr transfer only, $x < 200$ gal/yr both types, $x < 140$ gal/yr (constructed on or after 12/9/91)
	3. Existing large area source <input type="checkbox"/> dry-to-dry only, $140 < x < 2,100$ gal/yr transfer only, $200 < x < 1,800$ gal/yr both types, $140 < x < 1,800$ gal/yr (constructed before 12/9/91)	4. New large area source <input type="checkbox"/> dry-to-dry only, $140 < x < 2,100$ gal/yr transfer only, $200 < x < 1,800$ gal/yr both types, $140 < x < 1,800$ gal/yr (constructed on or after 12/9/91)

This is a correct facility classification. YES NO

If no, please check the appropriate classification:

facility qualified for a general permit as number _____ above

facility exceeds above limits and is not eligible for a general permit

B. The total quantity of perchloroethylene (perc) purchased within the preceding 12 months by this dry cleaning facility was 80 gallons.

Perc delivery person
 directly delivers ~~the~~ Perc into
 machine thru hose

PART III: GENERAL CONTROL REQUIREMENTS

Is the responsible official of the dry cleaning facility:
 (check appropriate boxes)

- 1. Storing perchloroethylene in tightly sealed and impervious containers? Y N N/A
- 2. Examining the containers for leakage? Y N
- 3. Closing and securing machine doors except during loading/unloading? Y N
- 4. Draining cartridge filters in their housing or in sealed containers for at least 24 hours prior to disposal? Y N
- 5. Maintaining solvent-to-carbon ratios and steam pressure for carbon adsorber beds according to the manufacturer's specifications? Y N N/A

PART IV: PROCESS VENT CONTROLS

In Part II-A:

If classification 1 has been checked, no controls are required. Proceed to Part V.

If classification 2 has been checked, the machine should be equipped with a refrigerated condenser (complete A below).

If classification 3 has been checked, the machine should be equipped with either a refrigerated condenser or a carbon adsorber (complete A and B below). *Carbon adsorber must have been installed prior to September 22, 1993*

If classification 4 has been checked, the machine should be equipped with a refrigerated condenser (complete A and B below).

A. Has the responsible official of all new sources and existing large area sources:
 (check appropriate boxes)

- 1. Equipped all machines with the appropriate vent controls? Y N
- 2. Equipped dry-to-dry machines with a closed-loop vapor venting system? Y N N/A
- 3. Equipped the condenser with a diverter valve so airflow will be directed away from the condenser upon opening the door? *(have fan - turns on when you open the door)* Y N N/A
- 4. Measured and recorded the temperature of the outlet exhaust stream of a refrigerated condenser on a weekly basis? Y N
- 5. Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded 45° F? Y N
- 6. Conducted all temperature monitoring after an appropriate cooldown period and after verifying that the coolant had been completely charged? Y N

B. Has the responsible official of an existing large or new large area source also:

1. Measured and recorded the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines on a weekly basis? Y N
2. Measured and recorded the washer exhaust temperature at the condenser inlet and outlet weekly? Y N
Is the temperature differential equal to or greater than 20° F? Y N
3. Measured and recorded the perc concentration in the exhaust stream weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped with a carbon adsorber? Y N N/A
Is the perc concentration equal to or less than 100 ppm? Y N N/A
4. Assured that the sampling port on the carbon adsorber exhaust for measuring perc concentrations is at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet? Y N
5. Equipped transfer machines (dryers, reclaimers, and washers) with individual condenser coils? Y N N/A
6. Routed airflow to the carbon adsorber (if used) at all times? Y N N/A

PART V: RECORDKEEPING REQUIREMENTS

Has the responsible official:
(check appropriate boxes)

1. Maintained receipts for perc purchased? Y N
2. Maintained rolling monthly averages of perc consumption? Y N
3. Maintained leak detection inspection and repair reports for the following:
 - a. documentation of leaks repaired w/in 24 hrs? or; Y N
 - b. documentation of parts ordered to repair leak and leak repaired w/in 2 days and parts installed w/in 5 days of receipt? Y N
4. Maintained calibration data? (for direct reading instruments only) Y N N/A
5. Maintained exhaust duct monitoring data on perc concentrations? Y N N/A
6. Maintained startup/shutdown/malfunction plan? Y N
7. Maintained deviation reports?
Problem corrected? Y N
8. Maintained compliance plan, if applicable? Y N N/A

PART VI: LEAK DETECTION AND REPAIRS

1. Does the responsible official conduct a weekly leak detection and repair inspection? Y N

2. Which method of detection is used by the responsible official?

Visual examination (condensed solvent on exterior surfaces)

Physical detection (airflow felt through gaskets)

Odor (noticeable perc odor)

Use of direct-reading instrumentation (FID/PID/calorimetric tubes) N/A

If using direct-reading instrumentation, is the equipment:

a. Capable of detecting perc vapor concentrations in a range of 0-500 ppm? Y N N/A

b. Calibrated against a standard gas prior to and after each use (PID/FID only)? Y N

c. Inspected for leaks and obvious signs of wear on a weekly basis? Y N

d. Kept in a clean and secure area when not in use? Y N

e. Verified for accuracy by use of duplicate samples (calorimetric only)? Y N

3. Has the facility maintained a leak log? Y N

4. Does the responsible official check the following areas for leaks?

Hose connections, fittings, couplings, and valves Y N

Muck cookers Y N N/A

Door gaskets and seating Y N

Stills Y N N/A

Filter gaskets and seating Y N

Exhaust dampers Y N N/A

Pumps Y N

Diverter valves (Have fern) Y N N/A

Solvent tanks and containers Y N

Cartridge filter housings Y N N/A

Water separators Y N

Steven A. Mills
Name of Responsible Official

R. V. Chokshi
Inspector's Name (Please Print)

R. V. Chokshi
Inspector's Signature

1-31-97

Date of Inspection

1-31-98

Approximate Date of Next Inspection

1. They have secondary containments for cleaning & waste area
2. Have zero waste for water separator water
3. ~~Spotting~~ Spotting area sealed.

looks good.

DRY CLEANER AIR QUALITY GENERAL PERMIT
ANNUAL COMPLIANCE CERTIFICATION FORM

(V)

AIRS ID#0990431
AMLENE INC STEVEN MILLS 4275 A OKEECHOBEE BLVD WEST PALM BEACH FL 33409

Bureau of Air Monitoring
& Mobile Sources

FEB 26 1998

RECEIVED

Do NOT Remove Label

Annual Reporting Period: 1/1 1997 TO 12/31 1997

Based on each term or condition of the Title V general air permit, my facility has remained in compliance with DEP Rule 62-213.300, Florida Administrative Code (F.A.C.), during the period covered by this statement. YES NO

If NO, complete the following:

#1. Term or condition of the general permit that has not been in continuous compliance during the reporting period stated above:

Exact period of non-compliance: from _____ to _____

Action(s) taken to achieve compliance: _____

Method used to demonstrate compliance: _____

#2. Term or condition of the general permit that has not been in continuous compliance during the reporting period stated above:

Exact period of non-compliance: from _____ to _____

Action(s) taken to achieve compliance: _____

Method used to demonstrate compliance: _____

As the responsible official, I hereby certify, based on information and belief formed after reasonable inquiry, that the statements made in this notification are true, accurate and complete. Further, my annual consumption of perchloroethylene solvent, based upon purchase receipts, does not exceed 2,100 gallons per year for dry-to dry facilities or 1,800 gallons per year for transfer or combination facilities.

RESPONSIBLE OFFICIAL: Steven A. Mills [Signature] 2/16/98
 Name (Please Print) Signature Date

*This form is made available to you as an aid in order to meet your annual compliance certification requirements. It is at the discretion of the responsible official to use this form.

PERCHLOROETHYLENE DRY CLEANERS

TITLE V GENERAL PERMIT
COMPLIANCE INSPECTION CHECKLIST

ARMS

TYPE OF INSPECTION: ANNUAL COMPLAINT/DISCOVERY
RE-INSPECTION

AIRS ID#: 0990431 DATE: 5-28-98 TIME IN: 11:25 TIME OUT: 12:15
FACILITY NAME: AMLENE CLEAN
FACILITY LOCATION: 4082 PGA BLVD
PBG, FL 33410
RESPONSIBLE OFFICIAL: Steven Mills PHONE: 689-5750
CONTACT NAME: _____ PHONE: _____

PART I: NOTIFICATION
(check appropriate box)
1. New facility notified DARM 30 days prior to startup
2. Facility failed to notify DARM to use general permit
Bureau of Air Monitoring & Mobile Sources
JUN 16 1998
RECEIVED

PART II: CLASSIFICATION
Facility indicated on notification form that it is:
(check appropriate box) No notification form
 Drop store/out of business/petroleum

1. Existing small area source dry-to-dry only, $x < 140$ gal/yr transfer only, $x < 200$ gal/yr both types, $x < 140$ gal/yr (constructed before 12/9/91) <input type="checkbox"/>	2. New small area source dry-to-dry only, $x < 140$ gal/yr transfer only, $x < 200$ gal/yr both types, $x < 140$ gal/yr (constructed on or after 12/9/91) <input checked="" type="checkbox"/>
3. Existing large area source dry-to-dry only, $140 \leq x \leq 2,100$ gal/yr transfer only, $200 \leq x \leq 1,800$ gal/yr both types, $140 \leq x \leq 1,800$ gal/yr (constructed before 12/9/91) <input type="checkbox"/>	4. New large area source dry-to-dry only, $140 \leq x \leq 2,100$ gal/yr transfer only, $200 \leq x \leq 1,800$ gal/yr both types, $140 \leq x \leq 1,800$ gal/yr (constructed on or after 12/9/91) <input type="checkbox"/>

5. This is a correct facility classification N Can not determine

If no, please check the appropriate classification:
 facility qualified for a general permit as number _____ above
 facility exceeds above limits and is not eligible for a general permit

B. The total quantity of perchloroethylene (perc) purchased within the preceding 12 months by this dry cleaning facility was 95.4 gallons. for 1997

PART III: GENERAL CONTROL REQUIREMENTS

Is the responsible official of the dry cleaning facility:
(check appropriate boxes)

- | | |
|---|---|
| 1. Storing perchloroethylene in tightly sealed and impervious containers? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 2. Examining the containers for leakage? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 3. Closing and securing machine doors except during loading/unloading? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N |
| 4. Draining cartridge filters in their housing or in sealed containers for at least 24 hours prior to disposal? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 5. Maintaining solvent-to-carbon ratios and steam pressure for carbon adsorber beds according to the manufacturer's specifications? | <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> N/A |

PART IV: PROCESS VENT CONTROLS

In Part II-A:

If classification 1 has been checked, no controls are required. Proceed to Part V.

If classification 2 has been checked, the machine should be equipped with a refrigerated condenser (complete A below).

If classification 3 has been checked, the machine should be equipped with either a refrigerated condenser or a carbon adsorber (complete A and B below). *Carbon adsorber must have been installed prior to September 22, 1993*

If classification 4 has been checked, the machine should be equipped with a refrigerated condenser (complete A and B below).

A. Has the responsible official of all new sources and existing large area sources:
(check appropriate boxes)

- | | |
|--|---|
| 1. Equipped all machines with the appropriate vent controls? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N |
| 2. Equipped dry-to-dry machines with a closed-loop vapor venting system? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 3. Equipped the condenser with a diverter valve so airflow will be directed away from the condenser upon opening the door? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 4. Measured and recorded the temperature of the outlet exhaust stream of a refrigerated condenser on a weekly/bi-weekly basis? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N |
| 5. Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded <u>45°F</u> ? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 6. Conducted all temperature monitoring after an appropriate cooldown period and after verifying that the coolant had been completely charged? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N |

B. Has the responsible official of an existing large or new large area source also:

- | | |
|--|--|
| 1. Measured and recorded the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines on a weekly basis? | <input type="checkbox"/> Y <input type="checkbox"/> N |
| 2. Measured and recorded the washer exhaust temperature at the condenser inlet and outlet weekly? | <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| Is the temperature differential equal to or greater than 20° F? | <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 3. Measured and recorded the perc concentration in the exhaust stream weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped with a carbon adsorber? | <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| Is the perc concentration equal to or less than 100 ppm?- | <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 4. Assured that the sampling port on the carbon adsorber exhaust for measuring perc concentrations is at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet? | <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 5. Equipped transfer machines (dryers, reclaimers, and washers) with individual condenser coils? | <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 6. Routed airflow to the carbon adsorber (if used) at all times? | <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |

PART V: RECORDKEEPING REQUIREMENTS

Has the responsible official:
(check appropriate boxes)

- | | |
|--|---|
| 1. Maintained receipts for perc purchased? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N |
| 2. Maintained rolling monthly averages of perc consumption? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N |
| 3. Maintained leak detection inspection and repair reports for the following: | |
| a. documentation of leaks repaired w/in 24 hrs? or; | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| b. documentation of parts ordered to repair leak and leak repaired w/in 2 days and parts installed w/in 5 days of receipt? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 4. Maintained calibration data? (for applicable direct reading instruments) | <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> N/A |
| 5. Maintained exhaust duct monitoring data on perc concentrations? | <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> N/A |
| 6. Maintained startup/shutdown/malfunction plan? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N |
| 7. Maintained deviation reports? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| Problem corrected? | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| 8. Maintained compliance plan, if applicable? | <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> N/A |

PART VI: LEAK DETECTION AND REPAIRS

1. Does the responsible official conduct a weekly (for small sources, bi-weekly) leak detection and repair inspection? Y N

2. Has the facility maintained a leak log? Y N

3. Does the responsible official check the following areas for leaks?

- | | | | |
|---|---|---------------------------|---|
| Hose connections, fittings, couplings, and valves | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A | Muck cookers | <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> N/A |
| Door gaskets and seating | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A | Stills | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| Filter gaskets and seating | <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A | Exhaust dampers | <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> N/A |
| Pumps | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A | Diverter valves | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| Solvent tanks and containers | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A | Cartridge filter housings | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A |
| Water separators | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> N/A | | |

4. Which method of detection is used by the responsible official?

- Visual examination (condensed solvent on exterior surfaces)
 - Physical detection (airflow felt through gaskets)
 - Odor (noticeable perc odor)
 - Use of direct-reading instrumentation (FID/PID/calorimetric tubes) N/A
 - Halogen leak detector N/A
- If using direct-reading instrumentation, is the equipment:
- a. Capable of detecting perc vapor concentrations in a range of 0-500 ppm? Y N
 - b. Calibrated against a standard gas prior to and after each use (PID/FID only)? Y N
 - c. Inspected for leaks and obvious signs of wear on a weekly basis? Y N
 - d. Kept in a clean and secure area when not in use? Y N
 - e. Verified for accuracy by use of duplicate samples (calorimetric only)? Y N

Steven A. Mills
Responsible Official's Name
(Please Print)

[Signature]
Responsible Official's Signature

R V Chokshi
Inspector's Name (Please Print)

5-28-98
Date of Inspection

[Signature]
Inspector's Signature

May 1999
Approximate Date of Next Inspection

ADDITIONAL SITE INFORMATION:

- | | Yes | NO |
|---|-------------------------------------|--------------------------|
| 1. Secondary Containment for: Dry Cleaning Machine & Storage area | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Waste area | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Spotting area Sealed | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

2. Disposal of Water from Water Separator using approved evaporator
or contracted Wastewater service

Safety Clean picks up
The Waste every three
months
or when needed

 **THIS PORTION MUST BE ATTACHED TO REMITTANCE FOR PROPER HANDLING**

(01)



Please include your AIRS ID# on your check or money order. This number can be found below on your mailing label.

TOTAL AMOUNT DUE: \$50.00

303442

Do **NOT** Remove Label

AIRS ID#0990431

AMLENE INC
STEVEN MILLS
4275 A OKEECHOBEE BLVD
WEST PALM BEACH FL 33409

FOR GOVERNMENT USE ONLY
Org.: 37550101000 EO: B
Fund: 20-2-035001
Obj.: 002273

FEB 28 98

RECEIVED
MAIL ROOM

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, 4a, and 4b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

1. Addressee's Address
2. Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:

AIRS ID 0990431

AMLENE INC
STEVEN MILLS
4275 A OKEECHOBEE BLVD
WEST PALM BEACH FL 33409

4a. Article Number

~~E~~ 333612881

4b. Service Type

- | | |
|---|---|
| <input type="checkbox"/> Registered | <input checked="" type="checkbox"/> Certified |
| <input type="checkbox"/> Express Mail | <input type="checkbox"/> Insured |
| <input type="checkbox"/> Return Receipt for Merchandise | <input type="checkbox"/> COD |

7. Date of Delivery

2/14/98

5. Received By: (Print Name)

8. Addressee's Address (Only if requested and fee is paid)

6. Signature: (Addressee or Agent)

X *Donna J. Restina*

UNITED STATES POSTAL SERVICE



First-Class Mail
Postage & Fees Paid
USPS
Permit No. G-10

• Print your name, address, and ZIP Code in this box •

DARM/MOBILE SOURCE CONTROL PROGRAM
DEPT. OF ENVIRONMENTAL PROTECTION
MAIL STATION 5510
2600 BLAIR STONE ROAD
TALLAHASSEE, FLORIDA 32399-2400



Z 333 612 881

US Postal Service

Receipt for Certified Mail

No Insurance Coverage Provided.

Do not use for International Mail (*See reverse*)

AIRS ID 0990431

AMLENE INC
STEVEN MILLS
4275 A OKEECHOBEE BLVD
WEST PALM BEACH FL 33409

PS Form 3800, April 1995

Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, & Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date	

TITLE V AIR QUALITY GENERAL PERMIT
INSPECTION SUMMARY REPORT

TYPE OF INSPECTION: ANNUAL COMPLAINT/DISCOVERY RE-INSPECTION

TIME IN: 11:25 TIME OUT: 12:15 AIRS ID#: 0990431
 TYPE OF FACILITY: Dry Cleaning
 FACILITY NAME: AMLENE CLEAN DATE: 5-28-98
 FACILITY LOCATION: 4082 PGA BLVD
PBG, FL 33410
 RESPONSIBLE OFFICIAL: STEVEN MILLS PHONE NUMBER: 689-5750

Based on the results of the compliance requirements evaluated during this inspection, the facility is found to be in compliance with DEP Rule 62-213.300, Florida Administrative Code (F.A.C.).

Based on the results of the compliance requirements evaluated during this inspection, the following compliance discrepancies were noted:

COMPLIANCE REQUIREMENT/PROBLEM	FOLLOW-UP ACTION REQUIRED

RECEIVED
 JUN 16 1998
 Bureau of Air Monitoring
 & Mobile Sources

COMMENTS:

The Annual Compliance Certification form has been properly certified and submitted to the inspector. YES NO

DATE OF NEXT INSPECTION: May 1999
 (Approximate)

INSPECTION CONDUCTED BY: R.V. Chokshi
 (Please Print)

INSPECTOR'S SIGNATURE: R.V. Chokshi PHONE NUMBER: 355-3070

Please mail to 4275 A Okeechobee Blvd, WPB, FL 33409
 Please send all mails →

TITLE V AIR QUALITY GENERAL PERMIT
 INSPECTION SUMMARY REPORT

TYPE OF INSPECTION: ANNUAL COMPLAINT/DISCOVERY RE-INSPECTION

TIME IN: 11:05 TIME OUT: 11:40 AIRS ID#: 0990431

TYPE OF FACILITY: Dry cleaning

FACILITY NAME: Amione Clean DATE: 4-27-99

FACILITY LOCATION: 4082 PGA Blvd
 Palm Beach Gardens, FL 33410

RESPONSIBLE OFFICIAL: Steve Mills PHONE NUMBER: 689-5750

- Based on the results of the compliance requirements evaluated during this inspection, the facility is found to be in compliance with DEP Rule 62-213.300, Florida Administrative Code (F.A.C.).
- Based on the results of the compliance requirements evaluated during this inspection, the following compliance discrepancies were noted:

COMPLIANCE REQUIREMENT/PROBLEM	FOLLOW-UP ACTION REQUIRED

COMMENTS:

The Annual Compliance Certification form has been properly certified and submitted to the inspector. YES NO

DATE OF NEXT INSPECTION: April 2000 (Approximate)

INSPECTION CONDUCTED BY: R V Chorshi (Please Print)

INSPECTOR'S SIGNATURE: *R. V. Chorshi* PHONE NUMBER: 355-3070

* Please send all mail to: 4275A Okeechobee Blvd
W.P.B. FL 33409

PERCHLOROETHYLENE DRY CLEANERS

TITLE V GENERAL PERMIT
COMPLIANCE INSPECTION CHECKLIST

ARMS

TYPE OF INSPECTION: ANNUAL COMPLAINT/DISCOVERY
RE-INSPECTION

AIRS ID#: 0990431 DATE: 4-27-99 TIME IN: 11:05 TIME OUT: 11:40
FACILITY NAME: AMLENE CLEAN
FACILITY LOCATION: 4082 PGA Blvd
PALM BEACH GARDENS, FLORIDA 33410
RESPONSIBLE OFFICIAL: Steve Mills PHONE: _____
CONTACT NAME: _____ PHONE: _____

PART I: NOTIFICATION

(check appropriate box)

- 1. New facility notified DARM 30 days prior to startup
- 2. Facility failed to notify DARM to use general permit

PART II: CLASSIFICATION

Facility indicated on notification form that it is:
(check appropriate box)

- No notification form
- Drop store/out of business/petroleum

- A.
- 1. Existing small area source
dry-to-dry only, $x < 140$ gal/yr
transfer only, $x < 200$ gal/yr
both types, $x < 140$ gal/yr
(constructed before 12/9/91)
 - 2. New small area source
dry-to-dry only, $x < 140$ gal/yr
transfer only, $x < 200$ gal/yr
both types, $x < 140$ gal/yr
(constructed on or after 12/9/91)
 - 3. Existing large area source
dry-to-dry only, $140 \leq x \leq 2,100$ gal/yr
transfer only, $200 \leq x \leq 1,800$ gal/yr
both types, $140 \leq x \leq 1,800$ gal/yr
(constructed before 12/9/91)
 - 4. New large area source
dry-to-dry only, $140 \leq x \leq 2,100$ gal/yr
transfer only, $200 \leq x \leq 1,800$ gal/yr
both types, $140 \leq x \leq 1,800$ gal/yr
(constructed on or after 12/9/91)
 - 5. This is a correct facility classification N Can not determine

If no, please check the appropriate classification:

- facility qualified for a general permit as number _____ above
- facility exceeds above limits and is not eligible for a general permit

B. The total quantity of perchloroethylene (perc) purchased within the preceding 12 months by this dry cleaning facility was 69.9 gallons. For 1998, For 1999 so far "0" gal

PART III: GENERAL CONTROL REQUIREMENTS

Is the responsible official of the dry cleaning facility:
(check appropriate boxes)

- 1. Storing perchloroethylene in tightly sealed and impervious containers? Y N N/A
- 2. Examining the containers for leakage? Y N N/A
- 3. Closing and securing machine doors except during loading/unloading? Y N
- 4. Draining cartridge filters in their housing or in sealed containers for at least 24 hours prior to disposal? Y N N/A
- 5. Maintaining solvent-to-carbon ratios and steam pressure for carbon adsorber beds according to the manufacturer's specifications? Y N N/A

PART IV: PROCESS VENT CONTROLS

In Part II-A:

If classification 1 has been checked, no controls are required. Proceed to Part V.

If classification 2 has been checked, the machine should be equipped with a refrigerated condenser (complete A below).

If classification 3 has been checked, the machine should be equipped with either a refrigerated condenser or a carbon adsorber (complete A and B below). *Carbon adsorber must have been installed prior to September 22, 1993*

If classification 4 has been checked, the machine should be equipped with a refrigerated condenser (complete A and B below).

A. Has the responsible official of all new sources and existing large area sources:
(check appropriate boxes)

- 1. Equipped all machines with the appropriate vent controls? Y N
- 2. Equipped dry-to-dry machines with a closed-loop vapor venting system? Y N N/A
- 3. Equipped the condenser with a diverter valve so airflow will be directed away from the condenser upon opening the door? Y N N/A
- 4. Measured and recorded the temperature of the outlet exhaust stream of a refrigerated condenser on a weekly/bi-weekly basis? Y N
- 5. Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded 45° F? Y N N/A
- 6. Conducted all temperature monitoring after an appropriate cooldown period and after verifying that the coolant had been completely charged? Y N

B. Has the responsible official of an existing large or new large area source also:

1. Measured and recorded the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines on a weekly basis? Y N
2. Measured and recorded the washer exhaust temperature at the condenser inlet and outlet weekly? Y N N/A
Is the temperature differential equal to or greater than 20° F? Y N N/A
3. Measured and recorded the perc concentration in the exhaust stream weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped with a carbon adsorber? Y N N/A
Is the perc concentration equal to or less than 100 ppm? Y N N/A
4. Assured that the sampling port on the carbon adsorber exhaust for measuring perc concentrations is at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet? Y N N/A
5. Equipped transfer machines (dryers, reclaimers, and washers) with individual condenser coils? Y N N/A
6. Routed airflow to the carbon adsorber (if used) at all times? Y N N/A

PART V: RECORDKEEPING REQUIREMENTS

Has the responsible official:
(check appropriate boxes)

1. Maintained receipts for perc purchased? Y N
2. Maintained rolling monthly total of perc consumption? Y N
3. Maintained leak detection inspection and repair reports for the following:
- a. documentation of leaks repaired w/in 24 hrs? or; Y N N/A
 - b. documentation of parts ordered to repair leak and leak repaired w/in 2 days and parts installed w/in 5 days of receipt? Y N N/A
4. Maintained calibration data? (for applicable direct reading instruments) Y N N/A
5. Maintained exhaust duct monitoring data on perc concentrations? Y N N/A
6. Maintained startup/shutdown/malfunction plan? Y N
7. Maintained deviation reports? Y N N/A
Problem corrected? Y N N/A
8. Maintained compliance plan, if applicable? Y N N/A

PART VI: LEAK DETECTION AND REPAIRS

1. Does the responsible official conduct a weekly (for small sources, bi-weekly) leak detection and repair inspection? Y N
2. Has the facility maintained a leak log? Y N
3. Does the responsible official check the following areas for leaks?

Hose connections, fittings, couplings, and valves	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A	Muck cookers	<input type="checkbox"/> Y	<input type="checkbox"/> N	<input checked="" type="checkbox"/> N/A
Door gaskets and seating	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A	Stills	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A
Filter gaskets and seating	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A	Exhaust dampers	<input type="checkbox"/> Y	<input type="checkbox"/> N	<input checked="" type="checkbox"/> N/A
Pumps	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A	Diverter valves	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A
Solvent tanks and containers	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A	Cartridge filter housings	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A
Water separators	<input checked="" type="checkbox"/> Y	<input type="checkbox"/> N	<input type="checkbox"/> N/A				
4. Which method of detection is used by the responsible official?
 - Visual examination (condensed solvent on exterior surfaces)
 - Physical detection (airflow felt through gaskets)
 - Odor (noticeable perc odor)
 - Use of direct-reading instrumentation (FID/PID/calorimetric tubes) N/A
 - Halogen leak detector N/A

If using direct-reading instrumentation, is the equipment:

 - a. Capable of detecting perc vapor concentrations in a range of 0-500 ppm? Y N
 - b. Calibrated against a standard gas prior to and after each use (PID/FID only)? Y N
 - c. Inspected for leaks and obvious signs of wear on a weekly basis? Y N
 - d. Kept in a clean and secure area when not in use? Y N
 - e. Verified for accuracy by use of duplicate samples (calorimetric only)? Y N

Steven Mills
Responsible Official's Name
(Please Print)

[Signature]
Responsible Official's Signature

R. V. Chokshi
Inspector's Name (Please Print)

4-27-99
Date of Inspection

[Signature]
Inspector's Signature

April 2000
Approximate Date of Next Inspection

ADDITIONAL SITE INFORMATION:

- | | Yes | NO |
|---|-------------------------------------|--------------------------|
| 1. Secondary Containment for: Dry Cleaning Machine & Storage area | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Waste area | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Spotting area Sealed | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

2. Disposal of Water from Water Separator using approved evaporator
or contracted Wastewater service

Safety Kleen picks up the waste
When called.

Z 210 662 405

US Postal Service

Receipt for Certified Mail

No Insurance Coverage Provided.

Postage for International Mail (See reverse)

10 AIRS ID # 0990431001AG

STEVEN MILLS

AMLENE CLEAN

4275 A OKEECHOBEE BLVD

WEST PALM BEACH FL 33409

PS Form 3800, April 1995

Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, & Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date	

THIS PORTION MUST BE ATTACHED TO REMITTANCE FOR PROPER HANDLING

0354602

Please include your AIRS ID# on your check or money order. This number can be found below on your mailing label.

RECEIVED
MAIL ROOM

TOTAL AMOUNT DUE: \$50.00
DEC 17 98

Do NOT Remove Label

AIRS ID # 0990431

AMLENE CLEAN
STEVEN MILLS
4275 A OKEECHOBEE BLVD
WEST PALM BEACH FL 33409

FOR GOVERNMENT USE ONLY
Org.: 37550101000 EO: B1
Fund: 20-2-035001
Obj.: 002273

Amlene, Inc.

PMB 355
931 Village Bl #905
West Palm Beach, FL 33409
(561)622-0107

RECEIVED
AUG 12 1999
Bureau of Air Monitoring
& Mobile Sources

August 4, 1999

Sandy Bowman
Title V General Permits Office
Bureau of Air Monitoring and Mobile Sources MS5510
DEP
2600 Blair Stone Rd
Tallahassee, FL 32399-2400

Re: Facility ID **0990431**

Dear Madam:

Please be advised that as of August 6, 1999 we no longer operate the above referenced facility number located at 4082 PGA Blvd, Palm Beach Gardens, FL 33410. We, therefore, surrender our Title V permit back to you.

We have advised the new operator that they must file the required registration forms with your office immediately.

Sincerely,



Steven A. Mills
Vice President Amlene, Inc

AMLENE, INC
PMB 355
931 VILLAGE BLVD. #905
WEST PALM BEACH, FL 33409

A

RETURN RECEIPT
REQUESTED

CERTIFIED

Z 448 515 037

MAIL



0000

U.S. POSTAGE
PAID
WEST PALM BEACH, FL
33417
AUG 10, 99
AMOUNT

\$2.98
00075438-16

Sandy Bowman
Title V General Permits Office
Bureau of Air Monitor & Mobile Services MS 5510
DEP
2600 Blair Stone Rd
Tallahassee, FL 32399-2400

32339X2400

