

Jeb Bush
Governor

Department of Environmental Protection

Twin Towers Office Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Colleen M. Castille
Secretary

February 24, 2006

Mr. Michael Pecora
Unilens Corporation, USA
10431 72nd Street, North
Largo, Florida 33777

Re: Facility No.: 1030481-002

Dear Mr. Pecora:

The Department has received the Title V General Permit Notification Form for the halogenated solvent degreasers facility that you submitted on January 6, 2006.

Please note that in January of each year the Department will be mailing fee notices to those facilities using the Title V general permit. This annual operation fee is \$50 and it is due and payable between January 15 and March 1 of each year the facility is in operation and is subject to the requirements of the Title V general permit.

If you have or expect to have any changes in your mailing address, location address, responsible official, or phone number, please notify the Department at the following address:

Title V General Permits Office
Bureau of Air Monitoring and Mobile Sources MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

If there are any changes in the facility status, including change of operating parameters or equipment, or if you have any additional questions regarding the Title V General Permit Program, please contact the district or local air program compliance inspector in your area.

Sincerely,

Joseph Kahn, Chief
Bureau of Air Monitoring
and Mobile Sources

JK/jw

cc: Mr. Gary Robbins, Pinellas County

"More Protection, Less Process"

Printed on recycled paper.



NO ACTIVITY FOR FACILITY.....
EMISSION FEE DATES 2001-2004
SOC REPORTS 5.....

COMP. STATUS - SNC MNC (IN)

8/2/2005

GR

TRPT - SOCR - Statement of
Compliance Report

HALOGENATED SOLVENT DEGREASERS
AIR GENERAL PERMIT NOTIFICATION FORM

RECEIVED
JAN 6 2006
Bureau of Air Monitoring
& Mobile Sources

Part III. Notification of Intent to Use General Permit

Prior to filling out this form, please read the instructions provided at the end of the form. Send completed form to the address listed in the instructions and keep a copy of the form for your files.

Facility Name and Location

1. Facility Owner/Company Name (Name of corporation, agency, or individual owner): Unilens Corp., USA
2. Site Name (For example, plant name or number):
3. Hazardous Waste Generator Identification Number: FDL057727836
4. Facility Location: Street Address: 10431 72 nd Street, North City: Largo, FL County: Pinellas Zip Code: 33777
5. Facility Identification Number (DGP Use ONLY - do not fill in) 1030481-002

Responsible Official

6. Name and Title of Responsible Official: Name: Michael Pecora Title: Vice President
7. Responsible Official Mailing Address: Organization/Firm: Unilens Corp., USA Street Address: 10431 72 nd Street, North City: Largo, FL County: Pinellas Zip Code: 33777
8. Responsible Official Telephone Number: Telephone: (727) 544 - 2531 Fax: (727) 545 - 1883

Facility Contact (If different from Responsible Official)

9. Name and Title of Facility Contact (For example, plant manager):
10. Facility Contact Address: Street Address: City: County: Zip Code:
11. Facility Contact Telephone Number: Telephone: () - Fax: () -

Facility Information

1. Provide the information below for each machine at the facility. Indicate the type of machine, the date of its purchase, and the date the control device was installed, if applicable.

Affected Machines	Date Initially Purchased From Manufacturer	Machine Classification (circle one)	Date Control Device Installed (if none, enter N/A)
Batch Vapor (solvent-air interface area)			
$x \leq 1.21 \text{ m}^2$	Nov 29, 1993	NEW/EXISTING	N/A
$x > 1.21 \text{ m}^2$	_____	NEW/EXISTING	_____
Batch Cold	_____	NEW/EXISTING	_____
In-line	_____	NEW/EXISTING	_____

2. (a) What was the total amount of halogenated solvents used in the latest 12 months?

[6.6] gallons

(b) If less than 12 months, how many? [] months

Check why it is less than 12 months: New owner: [] New store: [] Did not keep records: []

3. (a) Please indicate which of the following halogenated solvents are used at your facility.

- [] perchloroethylene [] methylene chloride
- [] trichloroethylene [X] 1,1,1-trichloroethane
- [] carbon tetrachloride [] chloroform

(b) The total volume of halogenated solvent emissions shall not exceed 10 tons per year. I choose to meet this requirement by (choose one):

- [] complying with an alternative solvent emission limit
- [] implementing a control device combination/work practice standards
- [X] meeting an idling emission limit/work practice standards

OR

[] meeting the requirements for batch cold cleaning machines

Facility Information

1. Provide the information below for each machine at the facility. Indicate the type of machine, the date of its purchase, and the date the control device was installed, if applicable.

Affected Machines	Date Initially Purchased From Manufacturer	Machine Classification (circle one)	Date Control Device Installed (if none, enter N/A)
Batch Vapor (solvent-air interface area)			
x ≤ 1.21 m ²	Nov 29, 1993	NEW/EXISTING	N/A
x > 1.21 m ²	_____	NEW/EXISTING	_____
Batch Cold	_____	NEW/EXISTING	_____
In-line	_____	NEW/EXISTING	_____

2. (a) What was the total amount of halogenated solvents used in the latest 12 months?

[3, 5] gallons

(b) If less than 12 months, how many? [] months

Check why it is less than 12 months: New owner: [] New store: [] Did not keep records: []

3. (a) Please indicate which of the following halogenated solvents are used at your facility.

[] perchloroethylene

[] methylene chloride

[] trichloroethylene

[X] 1,1,1-trichloroethane

[] carbon tetrachloride

[] chloroform

(b) The total volume of halogenated solvent emissions shall not exceed 10 tons per year. I choose to meet this requirement by (choose one):

[] complying with an alternative solvent emission limit

[] implementing a control device combination/work practice standards

[X] meeting an idling emission limit/work practice standards

OR

[] meeting the requirements for batch cold cleaning machines

4. If you choose to implement a control device combination, please select the appropriate controls from the list provided below. Indicate with an "X" all controls that apply to your facility. (Refer to paragraph (5)(c)1.-4.).

- | | |
|---|---|
| <input type="checkbox"/> 1.0 freeboard ratio | <input type="checkbox"/> carbon adsorber |
| <input type="checkbox"/> dwell time | <input type="checkbox"/> reduced room draft |
| <input type="checkbox"/> working mode cover | <input type="checkbox"/> super-heated vapor |
| <input type="checkbox"/> freeboard refrigeration device | |

5. Equipment Monitoring and Recordkeeping Information

Check all logs which are required to be kept on-site in accordance with the requirements of this general permit:

ALL FACILITIES

- | | |
|--|-------------------------------------|
| (a) Estimates of monthly halogenated solvent consumption | <input checked="" type="checkbox"/> |
| (b) Inspection records | <input checked="" type="checkbox"/> |
| (h) Remedial action log | <input checked="" type="checkbox"/> |
| (e) Instrument calibration | <input type="checkbox"/> |
| (g) Solvent content records | <input type="checkbox"/> |

FOR FACILITIES USING CONTROL COMBINATIONS

- | | |
|-------------------------------|--------------------------|
| (c) Temperature monitoring | <input type="checkbox"/> |
| (f) Dwell time records | <input type="checkbox"/> |
| (i) Control device monitoring | <input type="checkbox"/> |

FOR FACILITIES MEETING EMISSION STANDARDS

- | | |
|---|-------------------------------------|
| (j) Log of solvent additions and removals | <input checked="" type="checkbox"/> |
| (d) Idling emission concentration monitoring | <input checked="" type="checkbox"/> |
| (k) Monthly emissions calculations | <input checked="" type="checkbox"/> |
| (l) Rolling 3-month average emissions calculations* | <input type="checkbox"/> |
| (m) Cleaning capacity calculations* | <input type="checkbox"/> |

* Only for facilities meeting the alternative emission limitation standards*

6. Surrender of Existing DEP Air Permit(s)

Please indicate with an "X" the appropriate selection:

I hereby surrender all existing DEP air permits authorizing operation of the facility indicated in this notification form; the permit number(s) are:

No DEP air permits currently exist for the operation of the facility indicated in this notification form.

Responsible Official Certification

I, the undersigned, am the responsible official, as defined in Part II of this form, of the facility addressed in this notification. I hereby certify, based on information and belief formed after reasonable inquiry, that the statements made in this notification are true, accurate and complete. Further, I agree to operate and maintain the air pollutant emissions units and air pollution control equipment described above so as to comply with all terms and conditions of this general permit as set forth in Part II of this notification form.

I will promptly notify the Department of any changes to the information contained in this notification.

MICHAEL J. PECORA
Print name of responsible official

Michael J. Pecora
Signature

1/4/06
Date

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

Jeffrey H. Morris
Air Quality Division
Department of Environmental Management
300 South Garden Avenue
Clearwater, FL 33756

RECEIVED
JAN 14 2008
Bureau of Air Monitoring
& Mobile Sources

Re: 2007 Reports and Reporting Discrepancies Corrections for Halogenated Solvent
Degreasing General Permit, Permit No. 1030481-001-AG

Dear Mr. Morris:


In a meeting August 8, 2007 with Unilens Corp., USA Executive Management and later by email on August 9, 2007, you advised Unilens of the need to provide back reports to eliminate deficiencies in the noted permit file for operation of degreasing and cleaning operations.

Copies of the reports sent to General Permits Section of the DEP in Tallahassee are attached, and should eliminate the deficiencies. Each report has a separate signed cover. In addition, I have provided a copy of the reports for 2007 as well which are due this month.

In one circumstance, an annual report was provided on 11/12/2004 that covered the time period 6/2003 through 6/2004 as noted in your email; for uniformity and correct reporting, new reports are provided to cover the years 2003 and 2004 separately.

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Re: 2007 Reports and Reporting Discrepancies Corrections for Halogenated Solvent
Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:


In a meeting August 8, 2007 with Unilens Corp., USA Executive Management and later by email on August 9, 2007, Mr. Jeffrey H. Morris of the Pinellas County office advised Unilens of the need to provide back reports to eliminate deficiencies in the noted permit file for operation of degreasing and cleaning operations.

The attached reports should eliminate the deficiencies. Each report has a separate signed cover. In one circumstance, an annual report was provided on 11/12/2004 that covered the time period 6/2003 through 6/2004; reports are provided to cover the years 2003 and 2004 separately.

Current 2007 reports that are due in January are included as well.

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

c. Jeffrey H. Morris

**INITIAL
STATEMENT OF
COMPLIANCE
FIRST 3 MONTHS CONSUMPTION REPORT**

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Re: Initial Statement of Compliance - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG


Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the initial results of the first 3-month average emissions calculation was not submitted after the original notification of the permit in 2001, as required by 40 CFR 63.468 subpart (e)(4). Unilens wishes to correct this deficiency.

The three month averages are attached.

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Initial Solvent Emissions Report
Halogenated Solvent Degreasing General Permit No. 1030481-001-AG
(using 1,1,1 trichloroethane)
Time Period March through June 2001

		Mar-01	Apr-01	May-01	Jun-01
activity		loss (ml)	loss (ml)	loss (ml)	loss (ml)
D1	ultrasonic cleaning	10000	3893	8516	19871
D2	ultrasonic deblocking	10000	3785	8516	23656
D1 consumption (kg/month)		13	5	11	26
D2 consumption (kg/month)		13	5	11	31
Total consumption (kg/month)		26	10	22	57
D1 emissions (kg solvent/m ² of interface)		81.0	31.5	69.0	160.9
3-month rolling avg		-	-	60.5	87.1
D2 emissions(kg solvent/m ² of interface)		81.0	30.7	69.0	191.6
3-month rolling avg		-	-	60.2	97.1

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
 10431 72nd Street North
 Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
 Largo, FL 33777

SOLVENT EMISSION and ANNUAL REPORTS

2001

2002

2003

2004

2005

2006

2007

9 January 2008

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Re: Solvent Emission Report
Annual Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG
for the Time Period of 1 Jan 2001 through 31 Dec 2001


Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp, USA via email that the solvent emission report required under the noted permit for 2001 was not submitted. Unilens Corp., USA wishes to correct this deficiency by providing the attached combined Solvent Emissions and Annual Reports to comply with 40 CFR 63.468 subparts (f) and (g).

All operators of solvent cleaning machines have received training on the proper operation of solvent cleaning machines and their control devices sufficient to pass the test required in 40 CFR 63.463(d)(10).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Combined Solvent Emissions Report and Annual Report
 Halogenated Solvent Degreasing General Permit No. 1030481-001-AG
 (using 1,1,1 trichloroethane)
 Reporting Year 2001

		*Mar-01	Apr-01	May-01	Jun-01	Jul-01	Aug-01	Sep-01	Oct-01	Nov-01	Dec-01	Total
activity		loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (kg)
D1	ultrasonic cleaning	10000	3893	8516	19871	16086	5678	18925	2839	7385	2839	
D2	ultrasonic deblocking	10000	3785	8516	23656	28388	5678	11355	0	5385	2839	
D1 consumption (kg/month)		13	5	11	26	21	7	25	4	10	4	127
D2 consumption (kg/month)		13	5	11	31	37	7	15	0	7	4	131
Total consumption (kg/month)		26	10	22	57	59	15	40	4	17	7	258
D1 emissions (kg solvent/m ² of interface)		81.0	31.5	69.0	160.9	130.3	46.0	153.3	23.0	59.8	23.0	
3-month rolling avg		-	-	60.5	87.1	120.1	112.4	109.8	74.1	78.7	35.3	
D2 emissions(kg solvent/m ² of interface)		81.0	30.7	69.0	191.6	229.9	46.0	92.0	0.0	43.6	23.0	
3-month rolling avg		-	-	60.2	97.1	163.5	155.8	122.6	46.0	45.2	22.2	

* Permit approved in March 2001

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
 10431 72nd Street North
 Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
 Largo, FL 33777

9 January 2008

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Re: Solvent Emission Report
Annual Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG
for the Time Period of 1 Jan 2002 through 31 Dec 2002


Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp, USA via email that the solvent emission report required under the noted permit for 2002 was not submitted. Unilens Corp., USA wishes to correct this deficiency by providing the attached combined Solvent Emissions and Annual Reports to comply with 40 CFR 63.468 subparts (f) and (g).

All operators of solvent cleaning machines have received training on the proper operation of solvent cleaning machines and their control devices sufficient to pass the test required in 40 CFR 63.463(d)(10).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Combined Solvent Emissions Report and Annual Report
 Halogenated Solvent Degreasing General Permit No. 1030481-001-AG
 (using 1,1,1 trichloroethane)
 Reporting Year 2002

activity		Jan-02	Feb-02	Mar-02	Apr-02	May-02	Jun-02	Jul-02	Aug-02	Sep-02	Oct-02	Nov-02	Dec-02	Total
		loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (kg)
D1	ultrasonic cleaning	17979	9463	9463	7570	26495	5678	5678	12301	4731	9463	4731	0	
D2	ultrasonic deblocking	15140	13248	4731	0	26495	5678	7570	15140	3785	1893	5678	0	
D1 consumption (kg/month)		24	12	12	10	35	7	7	16	6	12	6	0	150
D2 consumption (kg/month)		20	17	6	0	35	7	10	20	5	2	7	0	131
Total consumption (kg/month)		44	30	19	10	70	15	17	36	11	15	14	0	281
D1 emissions (kg/month)		145.6	76.6	76.6	61.3	214.6	46.0	46.0	99.6	38.3	76.6	38.3	0.0	
3-month rolling avg		76.1	81.7	99.6	71.5	117.5	107.3	102.2	63.9	61.3	71.5	51.1	38.3	
D2 emissions (kg/month)		122.6	107.3	38.3	0.0	214.6	46.0	61.3	122.6	30.7	15.3	46.0	0.0	
3-month rolling avg		63.1	84.3	89.4	48.5	84.3	86.8	107.3	76.6	71.5	56.2	30.7	20.4	

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

UNIT LOCATIONS

10431 72nd Street North
 Largo, FL 33777

OWNER

Unilens Corp., USA
 10431 72nd Street North
 Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Re: Solvent Emission Report
Annual Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG
for the Time Period of 1 Jan 2003 through 31 Dec 2003


Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp, USA via email that the solvent emission report required under the noted permit for 2003 was not submitted. Unilens Corp., USA wishes to correct this deficiency by providing the attached combined Solvent Emissions and Annual Reports to comply with 40 CFR 63.468 subparts (f) and (g).

All operators of solvent cleaning machines have received training on the proper operation of solvent cleaning machines and their control devices sufficient to pass the test required in 40 CFR 63.463(d)(10).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Combined Solvent Emissions Report and Annual Report
 Halogenated Solvent Degreasing General Permit No. 1030481-001-AG
 (using 1,1,1 trichloroethane)
 Reporting Year 2003

activity		Jan-03	Feb-03	Mar-03	Apr-03	May-03	Jun-03	Jul-03	Aug-03	Sep-03	Oct-03	Nov-03	Dec-03	Total loss (kg)
		loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	
D1	ultrasonic cleaning	0	1893	0	0	0	0	5678	0	0	0	0	3785	
D2	ultrasonic deblocking	1725	5678	0	0	0	0	1893	0	0	0	0	3785	
D1 consumption (kg/month)		0	2	0	0	0	0	7	0	0	0	0	5	15
D2 consumption (kg/month)		2	7	0	0	0	0	2	0	0	0	0	5	17
Total consumption (kg/month)		2	10	0	0	0	0	10	0	0	0	0	10	32
D1 emissions (kg/month)		0.0	15.3	0.0	0.0	0.0	0.0	46.0	0.0	0.0	0.0	0.0	30.7	
3-month rolling avg		12.8	5.1	5.1	5.1	0.0	0.0	15.3	15.3	15.3	0.0	0.0	10.2	
D2 emissions (kg/month)		14.0	46.0	0.0	0.0	0.0	0.0	15.3	0.0	0.0	0.0	0.0	30.7	
3-month rolling avg		20.0	20.0	20.0	15.3	0.0	0.0	5.1	5.1	5.1	0.0	0.0	10.2	

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

UNIT LOCATIONS

10431 72nd Street North
 Largo, FL 33777

OWNER

Unilens Corp., USA
 10431 72nd Street North
 Largo, FL 33777

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

Re: Solvent Emission Report
Annual Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG
for the Time Period of 1 Jan 2004 through 31 Dec 2004


Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the solvent emission report required under the noted permit for 2004 was submitted on 11/12/04; however, the report covered the time period June 2003 through June 2004 and not Jan 2004 through Dec 2004. Unilens Corp., USA wishes to correct this deficiency by providing the attached combined Solvent Emissions and Annual Reports to comply with 40 CFR 63.468 subparts (f) and (g).

All operators of solvent cleaning machines have received training on the proper operation of solvent cleaning machines and their control devices sufficient to pass the test required in 40 CFR 63.463(d)(10).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Combined Solvent Emissions Report and Annual Report
 Halogenated Solvent Degreasing General Permit No. 1030481-001-AG
 (using 1,1,1 trichloroethane)
 Reporting Year 2004

activity	Jan-04	Feb-04	Mar-04	Apr-04	May-04	Jun-04	Jul-04	Aug-04	Sep-04	Oct-04	Nov-04	Dec-04	Total loss (kg)
	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	
D1 ultrasonic cleaning	0	0	0	1893	1893	0	0	1893	1893	0	1893	0	
D2 ultrasonic deblocking	0	0	0	1893	1893	0	0	1893	1893	0	1893	0	
D1 consumption (kg/month)	0	0	0	2	2	0	0	2	2	0	2	0	12
D2 consumption (kg/month)	0	0	0	2	2	0	0	2	2	0	2	0	12
Total consumption (kg/month)	0	0	0	5	5	0	0	5	5	0	5	0	25
D1 emissions (kg/month)	0.0	0.0	0.0	15.3	15.3	0.0	0.0	15.3	15.3	0.0	15.3	0.0	
3-month rolling avg	10.2	10.2	0.0	5.1	10.2	10.2	5.1	5.1	10.2	10.2	10.2	5.1	
D2 emissions (kg/month)	0.0	0.0	0.0	15.3	15.3	0.0	0.0	15.3	15.3	0.0	15.3	0.0	
3-month rolling avg	10.2	10.2	0.0	5.1	10.2	10.2	5.1	5.1	10.2	10.2	10.2	5.1	

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

UNIT LOCATIONS

10431 72nd Street North
 Largo, FL 33777

OWNER

Unilens Corp., USA
 10431 72nd Street North
 Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Re: Solvent Emission Report
Annual Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG
for the Time Period of 1 Jan 2005 through 31 Dec 2005


Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp, USA via email that the solvent emission report required under the noted permit for 2005 was not submitted. Unilens Corp., USA wishes to correct this deficiency by providing the attached combined Solvent Emissions and Annual Reports to comply with 40 CFR 63.468 subparts (f) and (g).

All operators of solvent cleaning machines have received training on the proper operation of solvent cleaning machines and their control devices sufficient to pass the test required in 40 CFR 63.463(d)(10).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Combined Solvent Emissions Report and Annual Report
 Halogenated Solvent Degreasing General Permit No. 1030481-001-AG
 (using 1,1,1 trichloroethane)
 Reporting Year 2005

activity		Jan-05	Feb-05	Mar-05	Apr-05	May-05	Jun-05	Jul-05	Aug-05	Sep-05	Oct-05	Nov-05	Dec-05	Total
		loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)
D1	ultrasonic cleaning	1893	5678	1893	1703	9463	1893	0	9464	9464	13249	0	5678	
D2	ultrasonic deblocking	1893	5678	1893	1893	0	0	0	9464	5678	0	0	5678	
D1 consumption (kg/month)		2	7	2	2	12	2	0	12	12	17	0	7	80
D2 consumption (kg/month)		2	7	2	2	0	0	0	12	7	0	0	7	42
Total consumption (kg/month)		5	15	5	5	12	2	0	25	20	17	0	15	122

D1 emissions (kg/month)	15.3	46.0	15.3	13.8	76.6	15.3	0.0	76.6	76.6	107.3	0.0	46.0
3-month rolling avg	10.2	20.4	25.5	25.0	35.3	35.3	30.7	30.7	51.1	86.9	61.3	51.1
D2 emissions (kg/month)	15.3	46.0	15.3	15.3	0.0	0.0	0.0	76.6	46.0	0.0	0.0	46.0
3-month rolling avg	10.2	20.4	25.5	25.5	10.2	5.1	0.0	25.5	40.9	40.9	15.3	15.3

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

UNIT LOCATIONS

10431 72nd Street North
 Largo, FL 33777

OWNER

Unilens Corp., USA
 10431 72nd Street North
 Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Re: Solvent Emission Report
Annual Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG
for the Time Period of 1 Jan 2006 through 31 Dec 2006


Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp, USA via email that the solvent emission report required under the noted permit for 2006 was not submitted. Unilens Corp., USA wishes to correct this deficiency by providing the attached combined Solvent Emissions and Annual Reports to comply with 40 CFR 63.468 subparts (f) and (g).

All operators of solvent cleaning machines have received training on the proper operation of solvent cleaning machines and their control devices sufficient to pass the test required in 40 CFR 63.463(d)(10).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Combined Solvent Emissions Report and Annual Report
 Halogenated Solvent Degreasing General Permit No. 1030481-001-AG
 (using 1,1,1 trichloroethane)
 Reporting Year 2006

activity	Jan-06	Feb-06	Mar-06	Apr-06	May-06	Jun-06	Jul-06	Aug-06	Sep-06	Oct-06	Nov-06	Dec-06	Total
	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (kg)
D1 ultrasonic cleaning	3785	13249	13249	7571	5678	3785	0	0	3785	3785	11356	5678	
D2 ultrasonic deblocking	3785	17034	17034	7571	0	0	0	0	0	0	0	0	
D1 consumption (kg/month)	5	17	17	10	7	5	0	0	5	5	15	7	95
D2 consumption (kg/month)	5	22	22	10	0	0	0	0	0	0	0	0	60
Total consumption (kg/month)	10	40	40	20	7	5	0	0	5	5	15	7	155

D1 emissions (kg/month)	30.7	107.3	107.3	61.3	46.0	30.7	0.0	0.0	30.7	30.7	92.0	46.0
3-month rolling avg	25.5	61.3	81.7	92.0	71.5	46.0	25.5	10.2	10.2	20.4	51.1	56.2
D2 emissions (kg/month)	30.7	137.9	137.9	61.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
3-month rolling avg	25.5	71.5	102.2	112.4	66.4	20.4	0.0	0.0	0.0	0.0	0.0	0.0

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

UNIT LOCATIONS

10431 72nd Street North
 Largo, FL 33777

OWNER

Unilens Corp., USA
 10431 72nd Street North
 Largo, FL 33777

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

Re: Solvent Emission Report
Annual Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG
for the Time Period of 1 Jan 2007 through 31 Dec 2007


Dear General Permits Section:

This combined Solvent Emissions and Annual Report is submitted for comply to the noted permit according to the requirements of 40 CFR 63.468 subparts (f) and (g).

All operators of solvent cleaning machines have received training on the proper operation of solvent cleaning machines and their control devices sufficient to pass the test required in 40 CFR 63.463(d)(10).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Combined Solvent Emissions Report and Annual Report
 Halogenated Solvent Degreasing General Permit No. 1030481-001-AG
 (using 1,1,1 trichloroethane)
 Reporting Year 2007

activity		Jan-07	Feb-07	Mar-07	Apr-07	May-07	Jun-07	Jul-07	Aug-07	Sep-07	Oct-07	Nov-07	Dec-07	Total
		loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)	loss (ml)
D1	ultrasonic cleaning	5678	15142	9464	9463.5	0	0	0	0	0	0	0	0	
D2	ultrasonic deblocking	0	0	0	26498	0	0	0	5678	0	0	0	0	
D1 consumption (kg/month)		7	20	12	12	0	0	0	0	0	0	0	0	52
D2 consumption (kg/month)		0	0	0	35	0	0	0	7	0	0	0	0	42
Total consumption (kg/month)		7	20	12	47	0	0	0	7	0	0	0	0	95
D1 emissions (kg/month)		46.0	122.6	76.6	76.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
3-month rolling avg		61.3	71.5	81.7	92.0	51.1	25.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0
D2 emissions (kg/month)		0.0	0.0	0.0	214.6	0.0	0.0	0.0	46.0	0.0	0.0	0.0	0.0	0.0
3-month rolling avg		0.0	0.0	0.0	71.5	71.5	71.5	0.0	15.3	15.3	15.3	0.0	0.0	0.0

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

UNIT LOCATIONS

10431 72nd Street North
 Largo, FL 33777

OWNER

Unilens Corp., USA
 10431 72nd Street North
 Largo, FL 33777

EXCEEDANCE REPORTS

7/30/2001

1/30/2002

7/30/2002

1/30/2003

7/30/2003

1/30/2004

7/30/2004

1/30/2005

7/30/2005

1/30/2006

7/30/2006

1/30/2007

7/30/2007

1/30/2008

Unilens Corp., USA

10431 72nd Street North

Largo, Florida 33777

727.544.2531

800.446.2020

Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 01/2001 through 06/2001 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
01-2001 through 06-2001

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 07/2001 through 12/2001 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
07-2001 through 12-2001

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 01/2002 through 06/2002 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
01-2002 through 06-2002

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 07/2002 through 12/2002 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
07-2002 through 12-2002

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 01/2003 through 06/2003 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
01-2003 through 06-2003

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 07/2003 through 12/2003 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
07-2003 through 12-2003

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 01/2004 through 06/2004 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

**Exceedance Report
01-2004 through 06-2004**

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 07/2004 through 12/2004 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
07-2004 through 12-2004

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 01/2005 through 06/2005 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
01-2005 through 06-2005

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 07/2005 through 12/2005 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
07-2005 through 12-2005

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover with a freeboard refrigeration device.

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

The main power cables to the D1 unit shorted out and were replaced. The unit was not in operation for one day. There was no loss of solvent during the incident since the tank remained closed and was not affected.

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 01/2006 through 06/2006 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
01-2006 through 06-2006

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 07/2006 through 12/2006 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
07-2006 through 12-2006

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover with a freeboard refrigeration device.

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None.

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883


Re: Semi-Annual Exceedance Report - Correction
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

On August 9, 2007, Jeffrey H. Morris of the Pinellas County office notified Unilens Corp., USA via email that the Exceedance Report required under the noted permit for the time period 01/2007 through 06/2007 was not submitted. Unilens wishes to correct this deficiency to comply with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
01-2007 through 06-2007

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover, freeboard refrigeration device.

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

Unit D1 found leaking at strainer 4-11-2007. Unit removed from service. Replaced heater and installed secondary condensing coils and chiller. Unit returned to service 4-23-2007. No exceedance since unit converted to use of alternate solvent (n-propyl bromide) 4-11-2007.

Unit D2 strainer cracked 5-2-2007 during maintenance and replaced. Unit tested after repair and no leakage found. Unit was drained immediately upon cracking of strainer, and refilled after repair. No loss of solvent was observed.

Additional Monitoring Required:

None

EXCEEDANCES NOTED AS ABOVE with applied corrective actions taken.

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER

Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
Fax: 727.545.1883

9 January 2008

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400


Re: Semi-Annual Exceedance Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG

Dear General Permits Section:

Attached is the exceedance report for 07-2007 through 12-2007 in compliance with 40 CFR 63.468.subpart (h).

Please contact me at (727) 544 2531 if you need any further information.

Regards,



Alan J. Frazer
Director of Quality Assurance
alan.frazer@unilens.com

Exceedance Report
07-2007 through 12-2007

Control Options:

Each degreaser complies with 40 CFR 63.463, (b)(1)(i), table option 3, using a working-mode cover with a freeboard refrigeration device.

1. Cover was inspected monthly and found in good condition and sealed properly.
2. The hoist timing was found in specification

Repairs Made:

None.

Additional Monitoring Required:

None

NO EXCEEDANCES OF ANY PARAMETER HAVE OCCURRED in the stated time period for this report

UNIT INFORMATION

unit	manufacturer	solvent/air interface area
D1	Branson degreaser	0.163 m sq
D2	Branson degreaser	0.163 m sq

OWNER


Unilens Corp., USA
10431 72nd Street North
Largo, FL 33777

UNIT LOCATIONS

10431 72nd Street North
Largo, FL 33777



10431 72nd Street North
Largo, FL 33777-1511



neopost 044J83047373
\$2.160
01/10/2008
Mailed From 33777
US POSTAGE

**General Permits Section
Bureau of Air Monitoring and
Mobile Sources, MS 5510
Department of Environmental
Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400**

Dibble, Dickson

From: Dibble, Dickson
Sent: Friday, August 10, 2007 10:24 AM
To: Robbins, Gary W
Cc: Bowman, Sandy
Subject: Airs ID# 1030481-001-AG, UNILENS CORP - Annual SOC & semi-Annual Exceedance Rpt
Attachments: socpinellas.pdf

Tracking: **Recipient** **Delivery**
 Robbins, Gary W
 Bowman, Sandy Delivered: 8/10/2007 10:24 AM

Gary,

Just this morning we received the subject item report which you will find attached as a scanned .pdf file for your records. I am not sure why it was sent here, but I wanted to make sure that you at least had a copy of the document.

If you require the original, let me know and I will be more than happy to stick it in the USPS mail.

Thanks,

Dickson E. Dibble

Dickson E. Dibble

FL Dept of Environmental Protection
Div. of Air Resource Management
Bureau of Air Monitoring & Mobile Sources
Air General Permit Program
(850) 921-9586
SunCom 291-9586
ICG-#345
Dickson.Dibble@dep.state.fl.us



Please note: Florida has a very broad public records law. Most written communications to or from state officials regarding state business are public records available to the public and media upon request. Your e-mail communications may therefore be subject to public disclosure

8/10/2007



August 8, 2007

General Permits Section
Bureau of Air Monitoring and Mobile Sources, MS 5510
Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Unilens Corp., USA
10431 72nd Street North
Largo, Florida 33777
727.544.2531
800.446.2020
fax: 727.545.1883

RECEIVED

AUG 09 2007

Bureau of Air Monitoring
Mobile Sources

Re: Annual Statement of Compliance and Semi-annual Exceedance Report
Halogenated Solvent Degreasing General Permit, Permit No. 1030481-001-AG
for the Time Period of July 1, 2006 to June 30, 2007


Dear Sir or Madam,

This letter is being submitted as an annual statement of compliance to notify you that Unilens Corp., USA located at 10431 72nd Street North, Largo, FL 33777 is in compliance with the idling emission limit of not exceeding 1000 lbs/year per activity and 10 tons/year per facility. We have one Branson degreaser unit with an estimated solvent consumption of 270 lbs during the time period of July 1, 2006 to June 30, 2007. Operator training has been performed in accordance with the requirements of 40 CFR Part 63, Subpart T.

This letter is also being submitted to state that no exceedances of any parameter have occurred during the same time period.

Please contact us at (727) 544 2531 if you need any further information.

Sincerely,


Michael J. Pecora
President

1,1,1 trichloroethane usage analysis
July 2006 to June 2007

ACTIVITY	Jul-06	Aug-06	Sep-06	Oct-06	Nov-06	Dec-06	Jan-07	Feb-07	Mar-07	Apr-07	May-07	Jun-07	total per activity	average per month
	loss (gal)	loss (gal)	loss (gal)	loss (gal)	loss (gal)	loss (gal)	loss (gal)	loss (gal)	loss (gal)	loss (gal)	loss (gal)	loss (gal)		
D1 branson	0.0	0.0	1.0	1.0	3.0	1.5	1.5	4.0	2.5				14.5	1.2
D2 branson										10.0	0.0	0.0	10.0	0.8
facility total (ml)	0	0	3785	3785	11355	5678	5678	15140	9463	37850	0	0	92733 ml/year	7728
facility total (gal)	0.0	0.0	1.0	1.0	3.0	1.5	1.5	4.0	2.5	10.0	0.0	0.0	24.5 gal/year	2.0
facility total (lbs)	0.0	0.0	11.0	11.0	33.0	16.5	16.5	44.1	27.5	110.1	0.0	0.0	269.9 lbs/year	22.5

UNIT INFORMATION		solvent/air
unit	manufacturer	interface area
D1	Branson degreaser	1.75 ft sq
D2	Branson degreaser	1.75 ft sq

CALCULATIONS

EPA General Permit Limits:

1000 lbs/yr per activity = 28636 ml/month allowed for each activity
 10 tons/yr per facility = 631421 ml/month allowed for the whole facility

density of 1,1,1 = 1.32 g/ml
 1 ton = 2205 lbs
 1 lb = 453.5924 g



EXPRESS

EXTREMELY URGENT

1-800-CALL DHL

1-800-225-5345

www.dhl-usa.com

DO NOT SEND CASH, CASH EQUIVALENT OR JEWELRY
DHL CANNOT DELIVER TO P.O. BOXES

All services provided by DHL Express are subject to DHL Terms and Conditions of Carriage as published at www.dhl-usa.com and on the DHL Waybill*. DHL liability shall not exceed US \$100.00. Shipment Value Protection may be arranged upon request. If this shipment involves an ultimate stop in a country other than the country of departure, the Warsaw Convention may be applicable.

*Subject to change without notice.



FM: ALCON
PEPI BRUNO
10431 72ND ST
LARGO, FL
33777
United States Of America
Phone: 727-544-2531

MAS

Parcels 1/1

ACCT: 798211020 ORIG: 1/1

PIE
Sender's Ref COMPLIANCE

TO: GENERAL PERMITS SECTION
BUREAU OF AIR MONITORING, MS 5510
DEPT OF ENVIRONMENTAL PROTECTION
2500 BLAIR STONE ROAD

POSTCODE


32399

32399, TALLAHASSEE, FL
United States Of America TEL:

Description CONTACT LENSES

FRT Bill to SHP
Weight 0.1 lb
Date: 2007-08-08

DHL standard terms and conditions apply




(2) US32399

TLHX 6Z

FSC

UnitID 24300



WAYBILL: 88898202492

(Non-negotiable)

LB0019

(2/06) FDS

this envelope for these services:
bund
IL@home Residential Delivery
IL Smart & Global Mail



DHL Express (USA), Inc.
1200 S Pine Island Rd
Plantation, FL 33324

THIS PORTION MUST BE ATTACHED TO REMITTANCE FOR PROPER HANDLING

Please include your AIRS ID# on your check or money order. This number is located on the mailing label.

467400 JAN19 2007

TOTAL AMOUNT DUE: \$50.00

Do NOT Remove Label


AIRS ID 1030481
UNILENS CORP, USA
10431 72nd Street North
LARGO, FLORIDA 33777




FLAIR ACCT. CODE 372020350013755010000
BENEFITTING OBJECT CODE 002000
BENEFITTING CATEGORY 000200

FOR GOVERNMENT USE ONLY
ORG.: 37550101000 EO: A1
FUND: 20-2-035001
OBJECT: 002273

Printed on recycled paper.



5608 02-01024 11 2007



044J83047373

\$0.390

01/17/2007



TITLE V - General Permit
Receipts
Post Office Box 3070
Tallahassee, FL 32315-3070

CHECK
NUMBER **39779**

Unilens Corp. U.S.A.

VENDOR
NUMBER **3680**

VOUCHER NO.	VENDOR INVOICE NUMBER	PURCHASE ORDER NO.	GROSS	DISCOUNT	NET
67977	PERMIT		50.00	0.00	50.00
THE ATTACHED CHECK IS IN PAYMENT FOR THE INVOICE LISTED. PLEASE DETACH FOR YOUR RECORDS.			50.00	.00	50.00