

PERCHLOROETHYLENE DRY CLEANERS



COMPLIANCE INSPECTION CHECKLIST

	ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/DISCOVERY ARMS COMPLAINT NO:	(CI)	
Γ			(FILE) ************************************	
AIRS ID#: 0251085 DAT	E: <u>01/15/09</u>	ARRIVE: <u>12:30P.M.</u>	DEPART: <u>12:45P.M.</u>	
FACILITY NAME: NORWOOD CLEANERS				
FACILITY LOCATION:	724 NW 183rd Street			
	MIAMI GARDENS 33	169-4250		
OWNER/AUTHORIZED REPRESENTATIVE: KITT-CHANCE MARCELLUS PHONE: (305)651-6160				
CONTACT NAME:		PHONE:		
ENTITLEMENT PERIOD: 2/8/2007 / 2/8/2012 (effective date) (end date)				
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box) ☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE				
PART II: FACILITY CLASSIFICATION - Rule 62-213.300 FAC (check ☑ only one box in A)				
transfer only, 20	x, x < 140 gal/yr x < 200 gal/yr x < 200 gal/yr x < 140 gal/yr x < 12/9/91) x = x < 12/9/91 x < 140 < x < 2,100 gal/yr x < 1,800 gal/yr	 New small area source dry-to-dry only, x < 140 g transfer only, x < 200 gal/y both types, x < 140 gal/yr (constructed on or after 12 New large area source dry-to-dry only, 140 ≤ x ≤ transfer only, 200 ≤ x ≤ 1, 	/yr 2/9/91) □ ≤ 2,100 gal/yr 800 gal/yr	
(constructed bei	General Permit 🔀 of business/petroleum	both types, $140 \le x \le 1,80$ (constructed on or after 12)		
B. The total quantity of perchloroethylene (perc) purchased within the preceding 12 months by this dry cleaning facility was 0 gallons.				

detection and repair inspection?	Yes No			
2. Does the facility maintain a leak log? Yes No				
c) Filter gaskets and seating d) Pumps Yes No N/A i) Yes No N/A j)	<u> </u>			
4. Which method(s) of detection (is/are) used by the responsible official? a) Visual examination (condensed solvent on exterior surfaces)				
MARUFUL MALIK	01/15/2009			
Inspector's Name (Please Print)	Date of Inspection			
	01/10			
Inspector's Signature	Approximate Date of Next Inspection			
<u> </u>				

COMMENTS: On January 15, 2009 I visited this facility to conduct an annual compliance inspection. On site I met Mr.Laivier Zarosa, the manager of the facility. This facility is now a drop store, the dry cleaning machine was removed.