						ARMINV01
POINT Off	ice * SWD SW: TAMPA		County* SUF	MTER	AIRS	D 1190047
Owner/Comp *	PRO-CRETE PRECAST INC			Site PRO-	CRETE PRECAST - 1	WILDWOOD PLANT
Directions	LOT#8					
Street	1320 Industrial Dr					
City *	WILDWOOD			Zip 34785	5200	Validate Address
UTM Zone	17 East 399.77	North 3192.59	Latitude 2	28 51 19.1520	Longilude [8	02 58.7724
Status *	NACTIVE	Maj (Froup SIC * 32	STONE, CLAY, G	LASS AND CONCR	ETE PRODUCTS
Reloc N 🔻	Shtdwn Dt	Strt D	ot	F	inal Shtdwn Dt 📗	
Gov Fac * 0	IOT OWNED OR OPERATED BY	A FEDERAL, STATE	, OR LOCAL GO	VE HAZ Waste C	enerator ID: FLD	
AOR Req * N +	Ozone SIP Facility	/* N 🔻	Type 23 C	ONCRETE PLANT		
Compliance Tracki	ng []				Current Permit I	ndicator AG 🕶
Title V NON T	non-HAP CI	ass MINOR	HAP C	lass MINOR	Pub	lic Exempt N
# of Emis Uni	ts C 0	A 0	1 1	Gene	rator Rating	MW

Dibble, Dickson

From:

Henry, Danielle D.

Sent:

Friday, July 15, 2011 2:41 PM

To:

Dibble, Dickson

Cc:

Haines, Chris; Schroeder, Bill; Hughes, Rhonda

Subject:

INACTIVATION: Pro-Crete Precast Inc., Facility ID No. 1190047-001-AG

Attachments:

Pro-Crete Precast-1190047.pdf

Dick,

The SWD has inactivated the GP noted above. It appears the last permitting action for this GP was handled by you so I am forwarding the necessary information to you so you can update your files. Feel free to contact me if you have any questions.

Have a great weekend, Danielle

Air Pollution Source Inspection Report Form Florida Department of Environmental Protection, Sou	thwest District	PAGE 1 OF 1	
FACILITY: Pro-Crete Precast, Wildwood Plant	ID#: 1190047	<u>'</u>	
The Entry of the Process, who would have	COUNTY: Sumte	r	
ADDRESS: 1320 Industrial Drive	INSPECTION DA	TE: 07/14/11	
Wildwood, Florida 34785	TIME IN:	TIME OUT:	
	11:00AM	11:05AM	
CONTACT: David Jacobs	INSPECTION TYPE: INS1		
davidjacobsjr@gmail.com	EU(s) INSPECTE	D: N/A	
SOURCE DESCRIPTION: Concrete Batching and Block Plant	CURRENT PERM	T: 1190047-001-AG	
	PERMIT EXPIRATION DATE: 11/29/12		
]		
I (Chris Haines) performed a drive-by inspection of the above- alleged shut-down status. Around 11:00AM I arrived at the pl entrances of the plant were shut and locked. The plant seemed	ant and first observed to be not in operation	that the gates to both ; no cars were parked at the	
I (Chris Haines) performed a drive-by inspection of the above-alleged shut-down status. Around 11:00AM I arrived at the plentrances of the plant were shut and locked. The plant seemed facility, no lights were on, and no personnel were present. The I left the facility shortly afterwards around 11:05.	ant and first observed to be not in operation	that the gates to both ; no cars were parked at the	
I (Chris Haines) performed a drive-by inspection of the above- alleged shut-down status. Around 11:00AM I arrived at the pl entrances of the plant were shut and locked. The plant seemed facility, no lights were on, and no personnel were present. The	ant and first observed to be not in operation	that the gates to both ; no cars were parked at th	
I (Chris Haines) performed a drive-by inspection of the above-alleged shut-down status. Around 11:00AM I arrived at the plentrances of the plant were shut and locked. The plant seemed facility, no lights were on, and no personnel were present. The I left the facility shortly afterwards around 11:05. COMPLIANCE STATUS: IN	ant and first observed to be not in operation	that the gates to both ; no cars were parked at th	

.

DIGITAL PHOTOGRAPHIC LOG

- 1. Facility Name: Pro-Crete Precast Wildwood Plant
- 2. County / Facility ID No: Sumter/1190047
- 3. Inspection Type: INS1
- 4. Inspection Date: 07/14/11
- 5. Type of Camera Used: Cannon PowerShot SD750 Digital ELPH 7.1 Mpixel (Air Section digital camera)
- 6. Digital Recording Media: SanDisk SDHC Card 4GB
- 7. All Digital Photos Were Copied To: C:\Documents and Settings\sherman SJS\Desktop\Pictures\1050377-04-08-2011
- 8. Original Copy Is Stored In/On: C:\Documents and Settings\haines_c\Desktop\Inspections\1190047 Were the photos altered?: NO X YES explain yes:
- 9. Photographer: Chris Haines
- 10. Signature of Photographer:



Photo ID No.1 7/14/11 11AM
Concrete driveway and office with closed and locked gate.



Photo ID No.2 7/14/11 11AM Barb-wire topped fence and main building.



Photo ID No.3 7/14/11 11AM Close-up of main building and fence.

Facility Name: Pro-Crete Precast: Wildwood Plant

Facility ID No. 1190047



Photo ID No.4 7/14/11 11AM Main building from second entrance.

Inspection Date: 7/14/11

Page 1 of 2



Photo ID No.5 7/14/11 11AM Back entrance to main building with closed and locked gate



Page 2 of 2

Photo ID No.6 7/14/11 11AM Barb-wire topped around back of site.



Photo ID No.7 7/14/11 11AM Close-up of blocks and sand piles. No parked cars, no apparent activity.

Facility Name: Pro-Crete Precast: Wildwood Plant Inspection Date: 7/14/11 Facility ID No. 1190047

Schroeder, Bill

119 00 47 Pau Cegra Will) Nier D

From:

David Jacobs [davidjacobsjr@gmail.com]

Sent:

Friday, April 15, 2011 9:03 AM

To:

Schroeder, Bill

Subject:

Re:

Hello Bill, Pro-Crete closed it's doors august of last year and is no longer in business. Thank you DJ

Sent from my iPhone

On Apr 5, 2011, at 11:00 AM, "Schroeder, Bill" < Bill. Schroeder@dep.state.fl.us> wrote:

Mr. Jacobs:

Our records show that visible emissions testing was not conducted at the Wildwood plant in 2010. If testing was performed, kindly provide a scanned copy of the test. If this facility was not operating in 2010, please send an email stating same with the date of shutdown.

Thank you for your assistance.

William E. Schroeder

Environmental Engineering Specialist IV

Florida Department of Environmental Protection

Southwest District

Division of Air Resource Management

Ph. (813) 632-7600 ext 113

fax (813) 632-7668

Suncom: 514-9155