


ENVIRONMENTAL PROTECTION
COMMISSION

ROBERT E. CURRY, CHAIRMAN
FRANCES M. DAVIN, VICE CHAIRMAN
BOB BOND
ELIZABETH B. CASTOR
BOB LESTER



ROGER P. STEWART
DIRECTOR

7402 NORTH 56th STREET
BUILDING 500
TAMPA, FLORIDA 33617
TELEPHONE (813) 272-5960



COUNTY of HILLSBOROUGH
Tampa, Florida 33601



November 19, 1976

Mr. Bud Steeleman
9721 Executive Center Dr. North
Suite 200
St. Petersburg, Fl. 33702

D. E. R.
NOV 23 1976
SOUTH WEST DISTRICT
ST. PETERSBURG

Dear Bud,

Enclosed are source tests from Gannon Unit No. 1, No. 3, and Big Bend Unit No. 1.

The tests from Gannon Unit No. 3, and Big Bend Unit No. 1, show compliance and have been accepted as valid tests by this department. The test from Gannon Unit No. 1 shows appreciable differences in SO₂ values obtained from fuel analysis versus stack testing. Since the SO₂ values from the stack test are consistent with each other and much higher than the allowable we are not accepting this test. This will delay their permit application for this unit until a valid test can be performed.

If you have any questions regarding these tests, please call.

Sincerely,

Joe Griffiths
Air Engineer
Hillsborough County Environmental
Protection Commission

JG/glf