JOHN CARLO, INC.

Rex Concrete Plant No. 1866 **Hillsborough County, Florida**FDEP Relocation to TIA Application

FDEP Permit No. 7770210-002-A0 **NOVEMBER - 2000**



Department of Environmental Protection

Division of Air Resources Management

NOTIFICATION OF INTENT TO RELOCATE AIR POLLUTANT EMITTING FACILITY

See Instructions for Form No. 62-210.900(6)
Submit to DEP district office for the area in which the facility is to be relocated.

(DEP Note: Update existing facility location data in ARMS. Do not create new facility record.)

Current Facility Information

1. Facility ID:

7770210

7770210-002-AO

3. Facility Owner or Operator:

JOHN CARLO, INC.

4. Facility Name:

JOHN CARLO, INC. — PORTABLE CONCERTE PLANT NO. 1866

5. Facility Street Address or Location Description:

5300 INTERSTATE 95 NORTH

6. City: YULEE

7. County: NASSAU

8. Shutdown Date at This Location: CURRENTLY SHUT DOWN AT THIS SITE

Proposed New Facility Location

1. Facility Street Address or Location Description:
HOOVER DRIVE (SOUTH OF HILLSBOROUGH AVE.) @ TAMPA INTERNATIONAL AIRPORT

2. City: TAMPA County: HILLSBOROUGH
*** facility has already advertised for Hillsborough County

5. Facility Coordinates:
UTM Zone 17 Latitude: 27°59'34" N Longitude: 82°32'13"W

6. Startup Date at New Location: **FEBRUARY 1, 2001**

7. Facility Comment:

This concrete plant has ceased operation at the location in Yulee, Nassau County. The unit will move to an advertised site in at Tampa International Airport on Hoover Drive, Hillsborough County. This facility as in the past will follow all FDEP Rules and Regulations as specified by it's FDEP "state-wide" Operation Permit The Annual Visible Emission Compliance Testing will be performed at this site.

DEP Form No. 62-210.900(6) - Form

Effective: 2/11/99

Owner/Authorized Representative or Responsible Official Name and Title of Owner/Authorized Representative or Responsible Official: Mr. David Ammon, Project Manager Organization/Firm: John Carlo, Inc. Street Address or P. O. Box: 4201 Ridgeway Lane City: Lakeland State: Florida Zip: 33803 Telephone: (904) 741-4228 Fax: (904) 225-3120 **Facility Contact** Name and Title of Facility Contact: **** SAME AS ABOVE Organization/Firm: Street Address or P. O. Box: City: Zip: State: Telephone: Fax: Certification Statement by Owner/Authorized Representative or Responsible Official:

I hereby certify that the information given in this report is correct to the best of my knowledge.

Signature

/2/6/00 Date

Supplemental Requirements

- 1. Provide a scale map (e.g., the relevant portion of a USGS topographic map) showing the proposed new location of the facility and points of air pollutant emissions in relation to residences, roads, and other features of the surrounding area.
- 2. If relocating to a different DEP district, provide a copy of the most recent compliance test report.

DEP Form No. 62-210.900(6) - Form


Effective: 2/11/99


TABLE OF CONTENTS

- I. MAP SHOWING RELOCATION
- H. LAST ANNUAL COMPLIANCE TEST

JOHN CARLO, INC. - Plant 1866

Relocation to TIA Site







CENTRAL FLORIDA TESTING LABORATORIES, INC.

VISIBLE EMISSIONS OBSERVATION FORM

METHOD USED (CIRCLE ONE) METHOD 9 203A 203B OTHER:	FORM NUMBER]	AGE	1 01	F (
COMPANY NAME C T	CONTINUED ON VEO NUMBER							\blacksquare			
STREET ADDRESS						ART TIM					
large Bay Blud, and Wasding Blvd. Tamps MAJENG ADDRESS VO Bay 1207	May	<u> </u>	<u> 19</u> 15	77 30	45	7.10 P	0	15	30	45	
VO. Box 1297	1 1		<u>7</u>	0		міn 31	Š	0	0	0	
East Yuler FL 32041-1297	2	7	$\frac{\mathcal{C}}{\mathcal{C}}$	5	4	32	0	0)(0	0	
17710210-001-AC	3			\mathcal{L}		33	0	$\frac{8}{2}$	$\frac{\circ}{\circ}$	0	
PROCESS EQUIPMENT OPERATING MODE		X	$\frac{1}{2}$			34	0	\lesssim	$\frac{\mathcal{L}}{\mathcal{L}}$	M	
Rex Cartral Mix Canaste Plast Silo Filling at 27+ph CONTROL FQUIPMENT OPERATING MODE	5	3	$\frac{\mathcal{C}}{\mathcal{C}}$	5		35	5	$\frac{9}{6}$	\mathcal{O}	\bowtie	
PROCESS EQUIPMENT CONTROL EQUIPMENT CONTROL EQUIPMENT Bashouse DESCRIBE EMISSION PT. OPERATING MODE COATINGUIS	6		$\overline{\wedge}$	13	\mathcal{L}	36	ă	$\frac{3}{1}$	$\overset{\circ}{\triangle}$	β	
Horizontal vent on top of bashouse	7	12	$\frac{\mathcal{L}}{\Delta}$	\sim		37	$\tilde{\Delta}$	$\frac{\mathcal{S}}{\mathcal{S}}$	$\frac{\circ}{\circ}$	H	
	8		6	0	0	38	δ	\sim	$\widetilde{\frown}$		
DISTANCE TO EMISS. PT. START ~ 100' END ~ 100' START ~ 300' END ~ 3000	9	8	$\frac{\mathcal{C}}{\mathcal{C}}$	0	5	39	3	7	$\overline{\Diamond}$	0	
HEIGHT OF EMISS PT. HEIGHT TO EMISS. PT. REL. TO OBSERVER START $\sim 25'$ END $\sim 25'$ START $\sim 20'$ END $\sim 20'$	10		0	5		40	0	0	δ	X	
VERTICAL ANGLE TO ORS PT INDECTION TO ORS PT (DEGREES)	11	0	$\frac{\mathcal{L}}{\mathcal{L}}$	1	0	41	7	Ŏ	$\overline{\bigcirc}$	0	
START ~ 70 END ~ 7 START ~ 2000 END ~ 3000 APPROX. DISTANCE AND DIRECTION FROM EMISS. PT. TO OBSERV. PT	12	121	7	0	0	42	0	0	Ŏ	0	
STAR Cheen of Emission Pointend Same	13	0	0	Ŏ	0	43	0	Ō	Ŏ	0	
START VONC END VONC EMISSION COLOR WATER DROPLET PLUME	14	101	0	0	0	44	0	0	0	0	
START NA END NA DATTACHED DETACHED NONE	15	1	Ō	0	0	45	0	0	0	0	
DESCRIBE PLUME BACKGROUND START SKV END	16	0	0	0	0	46	0	0	0	0	
BACKGROUND COLOR SKY CONDITIONS	17	0	0	0	0	47	Plan	+ S	hut '	Dan	
I WIND SPEED I WIND DIRECTION I	18	0	0	0	0	48					
START 4-10 LEND 4-13 START WAST END WEST AMBIENT TEMPERATURE WET BULB TEMP. PERCENT RH	19	0	0	0	0	49					
START ~840F END ~67	20	0	0	0	0	50					
SOURCE LAYOUT SKETCH DRAW NORTH ARROW MAGNETIC TRUE		0	0	0	0	51					
DE DESERVATION	22	0	0	0	0	52					
J'ontal Inc	23	0	0	0	0	53					
mixec	24	0	<u>0</u>	0	Q	54	ļ		 		
	25	0	<u>0</u>	10	Q	55			ļ	<u> </u>	
OBSERVER'S POSITION	26_	<u>IQ</u>	<u> </u>	10	10	56	ļ		-		
SIDE VIEW	27	0	<u>()</u>	10	0	57	<u> </u>		ļ		
STACK WITH PLIME	28	2	<u>Q</u>	10	Ŏ	58	ļ		 	<u> </u>	
SUN LOCATION LINE	29	191	$\frac{\mathcal{O}}{\mathcal{O}}$	10	1Q	59					
WIND	30		<u>U</u>	10	10	60	X MINUT	E INTER			
LAT: LONG: DECLINATION ADDITIONAL INFORMATION	AVERA	GE OPACI	11 1	<u>0%</u>	нк		A MINUI	- INTER		0%	
No objectionable edges detected. Batching	OBSER	KIJS!	ME (PF	I B	. K	eith					
Consiste and sila filling during test. Approximately	OBSERVER'S SIGNATURE XXXX										
49 rands concrete butched during text.	ORGANIZATION TO										
1 had sentier - where control	CERTIFIED BY ETA - Tampa DATE 2/13/1999										
	J	LIN	100	· • • • • • • • • • • • • • • • • • • •			1	$-\phi +$	~//		