



Florida Power & Light Company, 9700 S.W. 344 Street, Homestead, FL 33035  
Turkey Point Fossil Plant

August 16, 2004

Mr. H. Patrick Wong  
Division Chief  
Dade County Department of Environmental Resources Management  
Air Division  
33 S.W. 22<sup>nd</sup> Avenue, Suite 900  
Miami, Florida 33130

Dear Mr. Wong,


**Re: Semi-Annual Monitoring Report**  
Florida Power & Light - Cutler Plant  
Title V Permit No. 0250001-002-AV

Florida Power & Light (FPL) submits this Semi-Annual Monitoring Report for the above referenced facility. Title V Permit Condition 43 of Appendices TV-4 (TV-1, 2, 3 or 4), which implements Rule 62-213.440(1)(b) 3a., states that "The permittee shall submit reports of required monitoring at least every six (6) months. All instances of deviations from permit requirements must be clearly identified in such reports."

FPL has reviewed the above-referenced Title V permit for conditions related to monitoring and has reviewed all related monitoring information for the period of January 1, through June 30, 2004 and reports no instances of deviation from the Title V Operating Permit.

If you have any questions or require additional information, please contact either myself at (305) 242-3822 or Gary Andersen at (305) 242-3826.

Sincerely,

  
H. O. Nunez  
Plant General Manager  
(Responsible Official)

cc:

Ray Gordon  
Laxmana Tallam  
Al Linero  
File

Dade County DERM  
FDEP District Office  
FDEP Tallahassee ✓