

SURFACE COATING OPERATIONS



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI)		
RE-INSPECTION (FUI) ARMS COMPLAINT NO:		
AIRS ID#: 0112373 DATE: <u>3/31/2009</u> ARRIVE: <u>2:30PM</u> DEPART: <u>4:00PM</u>		
FACILITY NAME: FORT LAUDERDALE BOAT CLUB, LTD.		
FACILITY LOCATION: 1915 SW 21 AVENUE		
FORT LAUDERDALE 33312-3113		
OWNER/AUTHORIZED REPRESENTATIVE: KATHY CARTER PHONE: (954)797-7437		
CONTACT NAME: Kelly Ruff PHONE:		
ENTITLEMENT PERIOD: 12/15/2007 / 12/15/2012 (effective date) (end date)		
PART I: INSPECTION COMPLIANCE STATUS (check only one box)		
☑ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE		
PART II: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)		
PART III: CONTROL/OPERATING/MAINTANANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
1. Is/Are the surface coating operation(s) subject to a VOC Reasonably Available Control Technology (RACT)		

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued) (check ☑ appropriate box(es))	
3. Does the owner/operator encourage pollution prevention through such measures as training employees involved in surface coating operations on methods of reducing VOC emissions by: a) maintaining spray coating equipment to ensure effective application with a minimum of overspray? Yes No No No No No No No N	
PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300, F.A.C. A. New or Modified Process Equipment 1. Since the last inspection has there been a) installation of any new process equipment?————————————————————————————————————	
Elizabeth F. Susky	03/31/2009
Inspector's Name (Please Print)	Date of Inspection
	03/31/2010
Inspector's Signature	Approximate Date of Next Inspection
The facility is a marina with boat repair, bottom work area, boa	31/2009, AQD staff observed activities at Fort Lauderdale Boat Club. out pull out, boat storage and offices. Ms. Kelly Ruff accompanied at the facility. Ms. Ruff stated that they will be eventually ending

COMMENTS: In a compliance inspection conducted on 03/31/2009, AQD staff observed activities at Fort Lauderdale Boat Club. The facility is a marina with boat repair, bottom work area, boat pull out, boat storage and offices. Ms. Kelly Ruff accompanied AQD staff on the inspection as well various company owners at the facility. Ms. Ruff stated that they will be eventually ending painting and body work at the yard, however at the time of the inspection the facility was still conducting it. Ms. Ruff showed AQD staff the VOC records and AQD staff did observe that there were a few months were the VOC lbs per day were 43 (close to threshold). However, Ms. Ruff let AQD staff know that would not be an ongoing occurrence and those contractors would be leaving the yard in 60-120 days.

Housekeeping was better at the yard and all vessels were observed encapsulated in tarps. One contractor had recently obtained a containment vessl for his resin drum (the facility utilizes some resin which is tracked in records).